Appendix B

Block diagram of the stepper controller ASIP



Notes:

1. Dark Green: The output status signals. Or the names of the wires that have been declared in the starter project for these output status signals.
2. Dark Red: The input control signals. Or the names of the wires that have been declared in the starter project for these input control signals.
3. Blue: Ports of the datapath elements.
4. Thick Blue Lines: The four wires that have been declared in the starter project.
5. Thick Red Lines: Wires that you may need to declare for completing your project.
6. Orange Text: The three basic stages in the execution of the instructions.