

Table 1: Description of Each State

IDLE_STATE	FAN_ON	INCREMENT_THRESH	DECREMENT_THRESH
- Read the temperature from the L35 and update display. - Detect when current temp exceeds threshold temp. - Poll the touchscreen buttons	Detect when the current temp is less than threshold temp and turn off fan.	Highlight increment button and increase threshold temp by 0.5.	Highlight decrement button and decrease threshold temp by 0.5.




Figure 1: Diagram for Finite State Machine