

Copyright of Saudia Technic - Regeneration is not allowed without prior approval by Saudia Technic.



Task Card Title:

ANTI-CRASH ROD JUNCTION

Task Card NO:

532130-39-1

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP**Job Description**

1.
B. REMOVE THE APPLICABLE PASSENGER SEATS THAT ARE BETWEEN FRAME 29 AND FRAME 35.7 ON THE RIGHT SIDE AND BETWEEN FRAME 24 AND FRAME 35.7 ON THE LEFT SIDE AS PER AMM 53-21-00-220-827-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/AP		HRS				
Insp.			HRS				

REMOVE THE LOWER SIDEWALL PANELS**Job Description**

1.
C. REMOVE THE APPLICABLE LOWER SIDEWALL PANELS THAT ARE BETWEEN FRAME 29 AND FRAME 35.7 ON THE RIGHT SIDE AND BETWEEN FRAME 24 AND FRAME 35.7 ON THE LEFT SIDE AS PER AMM 53-21-00-220-827-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/AP		HRS				
Insp.			HRS				

PREPERATION**Job Description**

1.
D. REMOVE THE APPLICABLE INSULATION BLANKETS TO GET ACCESS TO THE INSPECTION AREA AS PER 53-21-00-220-827-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/AP		HRS				
Insp.			HRS				

PREPARATION**Job Description**

1.
E. CLEAN THE INSPECTION AREA WITH THE NON AQUEOUS CLEANER-GENERAL AND A CLEAN TEXTILE-LINT FREE COTTON AS PER AMM 53-21-00-220-827-A.



Task Card Title:

ANTI-CRASH ROD JUNCTION



Task Card NO:

532130-39-1

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	ACFT_TECH/AP			HRS				
Insp.				HRS				

TASK INSTRUCTION

Job Description

2.

A. PERFORM A DETAILED INSPECTION OF STRINGER 23 AT ANTI-CRASH ROD JUNCTION FROM FR29 TO FR35.7 RH AND FROM FR24 TO FR35.7 LH, INTERNAL STRUCTURE (VISIBLE PART) AS PER AMM 53-21-00-220-827-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	ACFT_TECH/AP			HRS				
Insp.	INSP/II			HRS				

CLOSEUP

Job Description

3.

A. OK TO INSTALL THE REMOVED INSULATION BLANKETS AMM 53-21-00-220-827-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	INSP/II			HRS				
Insp.				HRS				

CLOSE UP

Job Description

3.

B. INSTALL THE REMOVED INSULATION BLANKETS AMM 53-21-00-220-827-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	ACFT_TECH/AP			HRS				



Task Card Title:

ANTI-CRASH ROD JUNCTION



Task Card NO:

532130-39-1

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

Insp.

HRS

CLOSE UP

Job Description

3.
C. OK TO INSTALL THE REMOVED LOWER SIDEWALL PANELS AS PER AMM 53-21-00-220-827-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	INSP/II		HRS				

JOB-CLOSEUP

Job Description

3.
D. INSTALL THE REMOVED LOWER SIDEWALL PANELS AS PER AMM 53-21-00-220-827-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/AP		HRS				
Insp.			HRS				

CLOSE UP

Job Description

3.
E. OK TO INSTALL INSTALL THE REMOVED PASSENGER SEATS AS PER AMM 53-21-00-220-827-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	II/INSP		HRS				

CLOSE UP

Job Description

3.
F. INSTALL THE REMOVED PASSENGER SEATS (REF AMM 53-21-00-220-827-A).

 MET.32721991	Task Card Title: ANTI-CRASH ROD JUNCTION						
Task Card NO: 532130-39-1	Work Package: ASP/H-26 C7-CHK	A/C Registration: HZ-ASP					
.							
STEP COMPLETION SIGN OFF:							
	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	CAB/ACFT_TECH			HRS			
Insp.				HRS			
CLOSEUP							
Job Description							
3. G. PERFORM JOB-CLOSEUP AND RETURN AIRCRAFT BACK TO NORMAL AS PER AMM 53-21-00-220-827-A. .							
STEP COMPLETION SIGN OFF:							
	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/AP			HRS			
Insp.				HRS			
-Aircraft Maintenance Manual used: Revision No. _____ Dated._____. Task card finding (Tick Applicable Box) [☐] Yes [☐] No. If yes update the system and list Task card finding WO below Work order No: _____ _____ Note: Make sure to creat the finding Work Order on task card level. Remark's: _____ _____							



Task Card Title:

ANTI-CRASH ROD JUNCTION

Task Card NO:

532130-39-1

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.32722071		Task Card Title: FWD CARGO DOOR HINGE FITTING INSP				
Task Card NO: 532132-01-1		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP		
A/C Type: 321		Single Running Taskcard		Main Skill: IL,INSP,AF,ACFT_TECH		PROD Final Acceptance:
Project No: 01BASPC72608		Related Task Card:		A/C Area: 09		
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 401
ENCLOSURE: ☒ CMR: ☐ CPCP: ☒ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒						
Type Code: DET		Special Code: AF		MSG Code: CPCP, MRB, ALI		Request: CLEAN-UP, INSPECTION, INSPECTION, JOB-CL Phase: OSEUP
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.						
Zones: 100,132						
DOCUMENT REFERENCES:						
Doc Typ		Reference				
ALI		532132-01-1				
AMM		53-21-00-200-027-A				
AMM		532100-200-027				
ACCESS PANELS:						
MATERIAL REQUIREMENTS:						
Part Number		Description				Qty.
AMS3819		CLEAN LINT-FREE CLOTH				1.0
AV 8		PREVENTIVE- WATER DISPLACE HARD FILM				1.0
LOTOXANE		NON-AQUEOUS CLEANER				1.0
LPS 3		CPC- WATER DISPLACING SOFT FILM				1.0
MASKINGTAPE112INX36*		TAPE MASKING (MRP NO. P061)				1.0
TOOLING REQUIREMENTS:						
Part Number		Description				Qty.
No tools assigned to this Task Item						
TASK PREPARATION						
Job Description						
A. CLEAN THE INSPECTION AREA AND REMOVE THE CORROSION PREVENTATIO AS REQUIRED AS PER AMM TASK 53-21-00-200-027-A.						
STEP COMPLETION SIGN OFF:						
Qualification / Skill		Number of employees		Duration		Number./Signature
						Date Day Month Year



Task Card Title:

FWD CARGO DOOR HINGE FITTING INSP

Task Card NO:

532132-01-1

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

Mechanic/s	AF/ACFT_TECH			HRS				
Insp.				HRS				

TASK INSTRUCTION**Job Description****! NOTE**

Ensure to fill the attached TSV# 92-634 along with this task.

A. PERFORM A DETAILED VISUAL INSPECTION OF THE STRUCTURE ALONG THE FULL LENGTH OF THE HINGE FITTING AND ATTACHMENT RIVETS AS PER AMM TASK 53-21-00-200-027-A.

NOTE: THIS INSPECTION IS APPLICABLE ON THE CLOSED FORWARD COMPARTMENT DOOR.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	HRS	Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	II/INSP			HRS				

TASK INSTRUCTION**Job Description**

B. PERFORM A DETAILED VISUAL INSPECTION OF THE STRUCTURE ALONG THE FULL LENGTH OF THE HINGE FITTING AND ATTACHMENT RIVETS AS PER AMM TASK 53-21-00-200-027-A.

NOTE: THIS INSPECTION IS APPLICABLE ON THE OPEN FORWARD COMPARTMENT DOOR.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	HRS	Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	II/INSP			HRS				

TASK CLOSE UP**Job Description**

A. APPLY CORROSION PREVENTATION AV8 OR LPS3 AS PER AMM TASK 53-21-00-200-027-A.

STEP COMPLETION SIGN OFF:



Task Card Title:

FWD CARGO DOOR HINGE FITTING INSP

Task Card NO:

532132-01-1

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS				
Insp.	II/INSP			HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below
Work order No: _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 2 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 3 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 4 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 5 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

**Task Completion Close Up And
System Update****Station****Date****Signature**

 MET.32722062		Task Card Title: FUS STRINGER 23 TO CROWN CENTERLINE					
Task Card NO: 532164-01-6		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,AF,ACFT_TECH		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 09			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 402	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☐							
Type Code: GVI		Special Code: INSP		MSG Code: MRB, SOEE		Request: Phase: CLEAN-UP, INSPECTION	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 200							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
AMM		53-21-00-210-802-B					
AMM		532100-210-802					
DO		SOEE TR SA00ME2302736					
ACCESS PANELS:							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
LOTOXANE		NON-AQUEOUS CLEANER				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
No tools assigned to this Task Item							
PREPARATION							
Job Description							
A. CLEAN THE INSPECTION AREA AS REQUIRED.							
STEP COMPLETION SIGN OFF:							
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date	
						Day	Month
Mechanic/s	AF/ACFT_TECH		HRS				Year
Insp.			HRS				
TASK INSTRUCTION							
Job Description							
A. PERFORM GENERAL VISUAL INSPECTION OF LH/RH FUSELAGE EXTERNAL SURFACE, FROM STRINGER 23 TO CROWN CENTERLINE, EXCEPT AREAS COVERED BY BELLY FAIRING AS PER AMM. TASK 53-21-00-210-802-B.							
STEP COMPLETION SIGN OFF:							



Task Card Title:

FUS STRINGER 23 TO CROWN CENTERLINE

Task Card NO:

532164-01-6

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
				HRS		Day	Month	Year
Mechanic/s				HRS				
Insp.	INSP/II			HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

_____, _____, _____, _____, _____, _____, _____, _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 2 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 3 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 4 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 5 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

**Task Completion Close Up And
System Update****Station****Date****Signature**

 MET.25534555		Task Card Title: PRESS DEK MEMBRANES LWR SURFACE INSP					
Task Card NO: 533111-01-2		Work Package: ASP/H-26 C7-CHK			A/C Registration: HZ-ASP		
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,AF,ACFT_TECH		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 09			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 403	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☒ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: DET		Special Code: INSP		MSG Code: CPCP, MRB, ALI		Request: 	
Phase: CLEAN-UP, INSPECTION							
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 147,148							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
ALI		533111-01-2					
AMM		53-31-00-210-006-A					
AMM		533100-210-006					
ACCESS PANELS:							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
No parts assigned to this Task Item							
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
No tools assigned to this Task Item							
PREPARATION							
Job Description							
A. CAREFULLY CLEAN THE LOWER SURFACE OF THE PRESSURE DECK WITH 08BBB1NON AQUEOUS CLEANER-PETROLEUM BASED AND A CLEAN LINT-FREE CLOTH.							
STEP COMPLETION SIGN OFF:							
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date	
						Day	Month
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				
TASK INSTRUCTION							
Job Description							



Task Card Title:

PRESS DEK MEMBRANES LWR SURFACE INSP

Task Card NO:

533111-01-2

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP
NOTE

Ensure to fill the attached TSV# 92-634 along with this task.

A. PERFORM A DETAILED INSPECTION OF LOWER SURFACE OF PRESSURE DECK MEMBRANES, BETWEEN FR 42 AND FR 46, INCLUDING CONNECTIONS TO LONGITUDINAL BEAMS, SIDE BOXES, SUPPORT RIBS, REAR SPAR OF CENTER WING BOX AND PRESSURE BULKHEAD AS PER AMM TASK 53-31-00-210-006-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	INSP/II			HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

_____, _____, _____, _____, _____, _____, _____, _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____

_____, _____, _____, _____, _____, _____, _____, _____



Task Card Title:

PRESS DEK MEMBRANES LWR SURFACE INSP

Task Card NO:

533111-01-2

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following according (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.32722082		Task Card Title: FUS SKIN BETWEEN FR35.8 & FR36 INSP					
Task Card NO: 533141-01-2		Work Package: ASP/H-26 C7-CHK			A/C Registration: HZ-ASP		
A/C Type: 321		Single Running Taskcard		Main Skill: IL,INSP,AF,ACFT_TECH		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 09			
Internal Check:		Check Type:		Work Order NO:			
						Tally Sequence NO: 404	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: DET		Special Code: INSP		MSG Code: ALI		Request: JOB-SETUP,CLEAN-UP,INSPECTION,JOB-CLOSURE EUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 190							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
ALI		533141-01-2					
AMM		53-31-00-210-025-A					
AMM		533100-210-025					
ACCESS PANELS:							
191BT, 191EB, 192BT, 192EB							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
LOTOXANE		NON-AQUEOUS CLEANER				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
98D27803000000		LOCKING TOOL-FLAP SLAT LEVER, IN (HM)				2.0	
PREPARATION							
Job Description							
A. PERFORM JOB SET UP AS PER AMM TASK 53-31-00-210-025-A.							
STEP COMPLETION SIGN OFF:							
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date	
						Day Month Year	
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				
PREPARATION							
Job Description							
B. CLEAN THE INSPECTION AREA AS REQUIRED.							
STEP COMPLETION SIGN OFF:							



MET.32722082

Task Card Title:

FUS SKIN BETWEEN FR35.8 & FR36 INSP

Task Card NO:

533141-01-2

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS				
Insp.				HRS				

TASK INSTRUCTION**Job Description**

A. PERFORM A DETAILED VISUAL INSPECTION OF THE LH AND RH EXTERNAL FUSELAGE SKIN BETWEEN FR35.8 AND FR36, AND BETWEEN STRINGER 25 AND STRINGER 30 AS PER AMM TASK 53-31-00-210-025-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	II/INSP			HRS				

CLOSE UP**Job Description**

A. PERFORM JOB CLOSE UP AS PER AMM TASK 53-31-00-210-025-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS				
Insp.				HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

_____, _____, _____, _____, _____, _____, _____, _____

Note: Make sure to create the finding Work Order on task card level.

Remark's: _____



Task Card Title:

FUS SKIN BETWEEN FR35.8 & FR36 INSP

Task Card NO:

533141-01-2

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following accordingly (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.25512469		Task Card Title: PRESS FLOOR FR42 TO FR46 FRAME ATTCH					
Task Card NO: 533144-01-1		Work Package: ASP/H-26 C7-CHK			A/C Registration: HZ-ASP		
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,AF,ACFT_TECH		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 09			
Internal Check:		Check Type:		Work Order NO:			
						Tally Sequence NO: 405	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: DET		Special Code: INSP		MSG Code: ALI		Request: INSPECTION, INSPECTION, JOB-CLOSEUP, JOB-CLOSEUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRID OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 145,146							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
ALI		533144-01-1					
AMM		53-31-00-210-030-A					
AMM		533100-210-030					
ACCESS PANELS:							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
LOTOXANE		NON-AQUEOUS CLEANER				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
No tools assigned to this Task Item							
PREPARATION							
Job Description							
A. PERFORM JOB SET UP AS PER AMM TASK 53-31-00-210-030-A.							
STEP COMPLETION SIGN OFF:							
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date	
						Day	Month
Mechanic/s	AF/ACFT_TECH		HRS				Year
Insp.			HRS				
PREPARATION							
Job Description							
B. CLEAN THE INSPECTION AREA AS REQUIRED.							
STEP COMPLETION SIGN OFF:							



Task Card Title:

PRESS FLOOR FR42 TO FR46 FRAME ATTCH

Task Card NO:

533144-01-1

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS				
Insp.				HRS				

TASK INSTRUCTION**Job Description**

A. PERFORM A DETAILED VISUAL INSPECTION OF THE LH AND RH FRAME ATTACHMENTS TO THE PRESSURE FLOOR FROM FR42 TO FR46 AS PER AMM TASK 53-31-00-210-030-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	INSP/II			HRS				

CLOSE UP**Job Description**

A. OK TO INSTALL THE LOWER SIDEWALL PANELS BETWEEN FR42 AND FR46.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	INSP/II			HRS				

CLOSE UP**Job Description**

B. INSTALL THE LOWER SIDEWALL PANELS BETWEEN FR42 AND FR46 (REF. AMM TASK 25-23-44-400-001-A).

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS				
Insp.	II/INSP			HRS				

CLOSE UP**Job Description**

C. PERFORM JOB CLOSE UP AS PER AMM TASK 53-31-00-210-030-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS				
Insp.				HRS				



MET.25512469

Task Card Title:

PRESS FLOOR FR42 TO FR46 FRAME ATTCH

Task Card NO:

533144-01-1

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 2 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 3 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 4 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 5 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

**Task Completion Close Up And
System Update****Station****Date****Signature**

 MET.28342493		Task Card Title: DETAILED INSPECTION OF FORWARD PRESSURE BULKHEAD LOWER FLANGE AT FR 35 (A318/A319/A320) OR AT FR 35.							
Task Card NO: 533183-01-1-001		Work Package: ASP/II-26-67-CHK		A/C Registration: HZ-ASP					
A/C Type: 321		Single Running Taskcard		Main Skill: STR,INSP,II,ACFT_TECH		PROD Final Acceptance:			
Project No: 01BASPC72608		Related Task Card:		A/C Area:					
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 406			
ENCLOSURE: ☐ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒									
Type Code: DET		Special Code: STR		MSG Code: ALI		Request: Phase:			
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.									
Zones: 137									
DOCUMENT REFERENCES:									
Doc Typ		Reference							
ALI		533183-01-1							
AMM		533100-220-820							
ACCESS PANELS:									
131PW									
MATERIAL REQUIREMENTS:									
Part Number		Description				Qty.			
No parts assigned to this Task Item									
TOOLING REQUIREMENTS:									
Part Number		Description				Qty.			
No tools assigned to this Task Item									
DETAILED INSPECTION OF FORWARD PRESSURE BULKHEAD LOWER FLANGE (LH)									
Job Description									
A. 1. PERFORM JOB-SET UP DETAILED INSPECTION OF FORWARD PRESSURE BULKHEAD LOWER FLANGE AS PER AMM 53-31-00-220-820-A									
STEP COMPLETION SIGN OFF:									
		Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
							Day	Month	Year
Mechanic/s		STR/ACFT_TECH		HRS					
Insp.				HRS					
Job Description									
A.									



MET.28342493

Task Card Title:

DETAILED INSPECTION OF FORWARD PRESSURE BULKHEAD**~~D LOWER FLANGE AT FR 35 (A318/A319/A320) OR AT FR 35.~~**

Task Card NO:

533183-01-1-001

Work Package:

ASP/II-26-67-GHK

A/C Registration:

HZ-ASP

2. PERFORM DETAILED INSPECTION OF FORWARD PRESSURE BULKHEAD LOWER FLANGE AT FR 35 (A318/A319/A320) OR AT FR 35.8 (A321), BETWEEN STRINGER 37 AND STRINGER 38, INTERNAL SIDE, LH/RH AS PER AMM 53-31-00-220-820-A

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	INSP/II			HRS				

Job Description

A.
3. RETURN AIRCRAFT TO ORIGINAL CONFIGURATION AS PER AMM 53-31-00-220-820-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	STR/ACFT_TECH			HRS				
Insp.				HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____



MET.28342493

Task Card Title:

DETAILED INSPECTION OF FORWARD PRESSURE BULKHEAD**D LOWER FLANGE AT FR 35 (A318/A319/A320) OR AT FR 35.**

Task Card NO:

533183-01-1-001

Work Package:

ASP/H-26-67-GHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following accordingly (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.28342265		Task Card Title: DETAILED INSPECTION OF FORWARD PRESSURE BULKHEAD LOWER FLANGE AT FR 35 (A318/A319/A320) OR AT FR 35.					
Task Card NO: 533183-01-1-002		Work Package: ASP/H-26-67-GHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,ACFT_TECH,AP		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area:			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 407	
ENCLOSURE: ☐ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: DET		Special Code: STR		MSG Code: ALI		Request: Phase:	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 138							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
ALI		533183-01-1					
AMM		53-31-00-220-820-A					
AMM		533100-220-820					
ACCESS PANELS:							
132PW							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
No parts assigned to this Task Item							
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
No tools assigned to this Task Item							
DETAILED INSPECTION OF FORWARD PRESSURE BULKHEAD LOWER FLANGE (RH)							
Job Description							
A. 1. PERFORM JOB-SET UP DETAILED INSPECTION OF FORWARD PRESSURE BULKHEAD LOWER FLANGE AS PER AMM 53-31-00-220-820-A							
STEP COMPLETION SIGN OFF:							
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date	
				HRS		Day	Month
Mechanic/s	ACFT_TECH/AP			HRS			
Insp.				HRS			
Job Description							



Task Card Title:

DETAILED INSPECTION OF FORWARD PRESSURE BULKHEAD**D LOWER FLANGE AT FR 35 (A318/A319/A320) OR AT FR 35.8**

Task Card NO:

533183-01-1-002

Work Package:

ASP/II-26-67-GHK

A/C Registration:

HZ-ASP

A.

2.PERFORM DETAILED INSPECTION OF FORWARD PRESSURE BULKHEAD LOWER FLANGE AT FR 35 (A318/A319/A320) OR AT FR 35.8 (A321), BETWEEN STRINGER 37 AND STRINGER 38, INTERNAL SIDE, LH/RH AS PER AMM 53-31-00-220-820-A

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	INSP/II			HRS				

Job Description

A.

3.RETURN AIRCRAFT TO ORIGINAL CONFIGURATION AS PER AMM 53-31-00-220-820-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	ACFT_TECH/AP			HRS				
Insp.				HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to create the finding Work Order on task card level.

Remark's: _____



Task Card Title:

DETAILED INSPECTION OF FORWARD PRESSURE BULKHEAD**D LOWER FLANGE AT FR 35 (A318/A319/A320) OR AT FR 35.**

Task Card NO:

8 (A321), BETWEEN STRINGER 37 AND STRINGER 38, INTL

Work Package:

ASP/H-26-67-GHK

A/C Registration:

HZ-ASP**533183-01-1-002**

(1) If Task card interrupted or performed by different personals updates the system and update the following accordingly (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.32722077		Task Card Title: PRESS BLKHD AFT FACE LOWER PART INSP					
Task Card NO: 533188-01-2		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,II		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 09			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 408	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: DET		Special Code: INSP		MSG Code: ALI		Request: INSPECTION	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 191,192							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
ALI		533188-01-2					
AMM		53-31-00-220-806-A					
AMM		533100-220-806					
ACCESS PANELS:							
191BB, 191EB, 192EB, 192FB							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
No parts assigned to this Task Item							
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
No tools assigned to this Task Item							
TASK INSTRUCTION							
Job Description							
A. PERFORM A DETAILED VISUAL INSPECTION OF THE AFT FACE OF THE PRESSURE BULKHEAD ON THE LOWER PART OF THE VERTICAL STRUTS AT FR35.8 (200 MM FROM BOTTOM) AT Y= +/-765 MM (2 PLACES) AS PER AMM TASK 53-31-00-220-806-A.							
STEP COMPLETION SIGN OFF:							
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date	
				HRS		Day	Month
Mechanic/s				HRS			
Insp.	INSP/II			HRS			



Task Card Title:

PRESS BLKHD AFT FACE LOWER PART INSP

Task Card NO:

533188-01-2

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

- Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to create the finding Work Order on task card level.

Remark's: _____

(1) If Task card interrupted or performed by different persons updates the system and update the following accordingly (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 2 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 3 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 4 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 5 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

**Task Completion Close Up And
System Update****Station****Date****Signature**

 MET.32722068		Task Card Title: FUSELAGE EXTERNAL SURFACE INSPECTION										
Task Card NO: 534108-01-2		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP								
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,AF,ACFT_TECH		PROD Final Acceptance:						
Project No: 01BASPC72608		Related Task Card:		A/C Area: 09								
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 409						
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒												
Type Code: GVI		Special Code: INSP		MSG Code: ALI		Request: Phase: PRE INSP,PRE INSP						
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.												
Zones: 100												
DOCUMENT REFERENCES:												
Doc Typ		Reference										
ALI		534108-01-2										
AMM		53-41-00-210-810-A										
ACCESS PANELS:												
MATERIAL REQUIREMENTS:												
Part Number		Description				Qty.						
No parts assigned to this Task Item												
TOOLING REQUIREMENTS:												
Part Number		Description				Qty.						
No tools assigned to this Task Item												
PREPARATION												
Job Description												
A. CLEAN THE AREA WITH A LINT-FREE COTTON CLOTH AND THE CLEANING AGENTS AND LET THE AREA DRY AMM TASK 53-41-00-210-810.												
STEP COMPLETION SIGN OFF:												
		Qualification / Skill		Number of employees		Duration		Number./Signature		Date		
Mechanic/s		AF/ACFT_TECH				HRS						
Insp.						HRS						
TASK INSTRUCTION												
Job Description												
A. PERFORM GENERAL VISUAL INSPECTION OF THE FUSELAGE EXTERNAL SURFACE BETWEEN FR47 AND FR70, FROM STRINGER 23 LH/RH TO BOTTOM CENTERLINE (EXCEPT THE AREA COVERED BY THE BELLY FAIRING) AS PER AMM TASK 53-41-00-210-810.												



Task Card Title:

FUSELAGE EXTERNAL SURFACE INSPECTION

Task Card NO:

534108-01-2

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP**STEP COMPLETION SIGN OFF:**

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s				HRS			
Insp.	INSP/II			HRS			

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 2 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 3 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 4 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 5 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

**Task Completion Close Up And
System Update****Station****Date****Signature**

 MET.25450096		Task Card Title: GUSSET PLATE FASTENER HOLE NDT INSP					
Task Card NO: 534123-01-3		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main skill: STR,INSP,IL,RII,NDT_INSP,CAB, ACFT_TECH,NDT		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 05			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 410	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: SDI		Special Code: INSP		MSG Code: ALI		Request: CTION,INSPECTION,IN SPECTION,JOB-CLOSE UP,	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRID OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 261,262,263,264							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
ALI		534123-01-3					
AMM		53-41-00-220-802-A					
AMM		534100-220-802					
NDT		NTM 53-41-23					
ACCESS PANELS:							
832, 842							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
LOTOXANE		NON-AQUEOUS CLEANER				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
No tools assigned to this Task Item							
TASK PREPARATION							
Job Description							
A. PERFORM JOB SET UP AS PER AMM TASK 53-41-00-220-802-A AND PERFORM THE FOLLOWING:							
(1) IF INSTALLED, REMOVE THE GALLEYS AND/OR THE LAVATORIES FROM THE INSPECTION AREA (REF. AMM 25-33-00-00 AND AMM 25-43-00-00).							
(2) REMOVE THE DOOR FRAME LINING (REF. AMM TASK 25-23-45-000-003-A AND AMM TASK 25-23-45-000-004-A).							
(3) REMOVE THE INSULATION BLANKETS 25-80-00-000-001-A .							
NOTE: IDENTIFY THE INSULATION BLANKETS TO MAKE THE SUBSEQUENT INSTALLATION PROCEDURE EASIER.							
STEP COMPLETION SIGN OFF:							
Qualification / Skill		Number of employees		Duration		Number./Signature	
Date							
Day Month Year							
Mechanic/s		CAB/ACFT_TECH		HRS			



Task Card Title:

GUSSET PLATE FASTENER HOLE NDT INSP

Task Card NO:

534123-01-3

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

Insp.

HRS

TASK PREPARATION**Job Description**

B. CLEAN THE INSPECTION AREA AS REQUIRED.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	CAB/ACFT_TECH		HRS				
Insp.			HRS				

TASK PREPARATION**Job Description**

C. REMOVE THE FASTENERS TO INSPECT THE HOLES (REF. SRM 514200) AS PER AMM TASK 53-41-00-220-802-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	STR/ACFT_TECH		HRS				
Insp.			HRS				

TASK INSTRUCTIONS**Job Description**

A. PERFORM SPECIAL DETAILED INSPECTION (ROTO) OF THE FASTENER HOLE OF GUSSET PLATE ATTACHMENTS FROM FR66 AND FR68 LH/RH SIDES. DO THIS INTERNALLY FROM STGR 10 TO STGR 16 LH/RH POSITIONS (REF. NTM 534123) AS PER AMM TASK 53-41-00-220-802-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	NDT_INSP/NDT		HRS				

TASK CLOSE UP**Job Description**

A. INSTALL THE FASTENERS THAT ATTACH THE GUSSET PLATES TO THE FR66 AND FR68 FROM STGR 10 TO STGR 16.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	STR/ACFT_TECH		HRS				
Insp.	INSP/RII		HRS				

TASK CLOSE UP**Job Description**



Task Card Title:

GUSSET PLATE FASTENER HOLE NDT INSP

Task Card NO:

534123-01-3

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

B. OK TO INSTALL THE INSULATION BLANKETS.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	II/INSP			HRS				

TASK CLOSE UP

Job Description

C. INSTALL THE INSULATION BLANKETS (REF. AMM TASK 25-80-00-400-001-A).

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	CAB/ACFT_TECH			HRS				
Insp.	INSP/II			HRS				

TASK CLOSE UP

Job Description

D. OK TO INSTALL THE DOOR FRAME LINING.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	INSP/II			HRS				

TASK CLOSE UP

Job Description

E. INSTALL THE DOOR FRAME LINING (REF. AMM TASK 25-23-45-400-008-A AND AMM TASK 25-23-45-400-005-A).

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	CAB/ACFT_TECH			HRS				
Insp.	II/INSP			HRS				

TASK CLOSE UP

Job Description

F. IF REMOVED, INSTALL THE GALLEYS AND/OR THE LAVATORIES IN THE INSPECTION AREA.
(REF. AMM 25-33-00-00 AND AMM 25-43-00-00).

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	CAB/ACFT_TECH			HRS				
Insp.	INSP/II			HRS				



MET.25450096

Task Card Title:

GUSSET PLATE FASTENER HOLE NDT INSP

Task Card NO:

534123-01-3

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to create the finding Work Order on task card level.

Remark's: _____

(1) If Task card interrupted or performed by different persons updates the system and update the following accordingly (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 2 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 3 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 4 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 5 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

**Task Completion Close Up And
System Update****Station****Date****Signature**

 MET.31486331		Task Card Title: PAX/CREW DR CUTOUT UPR CORN NDT INSP					
Task Card NO: 534124-01-3		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: INSP, I, NDT, INSP, CAB, ACFT_TECH, NDT, AP		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 05			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 411	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: SDI		Special Code: INSP		MSG Code: ALI		Request: LOSEUP, JOB-CLOSEUP, Phase: JOB-CLOSEUP, JOB-CLOSEUP, SEUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 260,263,264							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
ALI		534124-01-3					
AMM		53-41-00-220-808-A					
AMM		534100-220-808					
NDT		NTM 53-41-24					
ACCESS PANELS:							
261VW, 262VW, 832, 842							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
08BAA9		NON AQUEOUS CLEANER - GENERAL				1.0	
14SBA1		TEXTILE - LINT FREE COTTON AMS3819				1.0	
12ABC1		CORROSION PREVENTIVE SOFT FILM				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
No tools assigned to this Task Item							
PREPARATION							
Job Description							
1. A. PERFORM JOB SET UP FOR SPECIAL DETAILED INSPECTION (HFEC) OF AFT PASSENGER/ CREW DOOR CUTOUT, AFT UPPER CORNER BETWEEN STRINGER 8 AND STRINGER 10, FR 68 WEB JOINT TO DOOR FRAME, AFT FACE, LH/RH AS PER AMM TASK 53-41-00-220-808-A.							
STEP COMPLETION SIGN OFF:							
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date	
				HRS		Day	Month
Mechanic/s	CAB/ACFT_TECH			HRS			
Insp.				HRS			
PREPARATION							



MET.31486331

Task Card Title:

PAX/CREW DR CUTOUT UPR CORN NDT INSP

Task Card NO:

534124-01-3

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP**Job Description**

1.

B. CLEAN THE INSPECTION AREA WITH NON AQUEOUS CLEANER AS PER AMM 53-41-00-220-808-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	CAB/ACFT_TECH		HRS				
Insp.			HRS				

PREPARATION**Job Description**

2.

A. PERFORM SPECIAL DETAILED INSPECTION (HFEC) OF AFT PASSENGER/ CREW DOOR CUTOUT, AFT UPPER CORNER BETWEEN STRINGER 8 AND STRINGER 10, FR 68 WEB JOINT TO DOOR FRAME, AFT FACE, LH/RH AS PER AMM TASK 53-41-00-220-808-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	NDT_INSP/NDT		HRS				

TASK INSTRUCTIONS**Job Description**

2.

B. REMOVE THE DAMAGED TPS LAYER AND APPLY A NEW LAYER OF CORROSION PREVENTIVE COMPOUND-WATER DISPLACING SOFT FILM - (MATERIAL REF. 12ABC1) REF. AMM TASK 51-78-00-916-001. AS PER AMM TASK 53-41-00-220-808-A

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/AP		HRS				
Insp.			HRS				

CLOSE UP**Job Description**

3.

A. OK TO INSTALL THE INSULATION BLANKETS AS PER AMM TASK 53-41-00-220-808-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	INSP/II		HRS				

TASK INSTRUCTIONS**Job Description**

3.



Task Card Title:

PAX/CREW DR CUTOUT UPR CORN NDT INSP

Task Card NO:

534124-01-3

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

B. INSTALL THE INSULATION BLANKETS (REF. AMM TASK 25-80-00-400-001-A). AS PER AMM TASK 53-41-00-220-808-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	ACFT_TECH/AP			HRS				
Insp.				HRS				

CLOSE UP**Job Description**

3.
C. IF REMOVED FOR ACCESS, INSTALL THE GALLEY AT FRAME 68. REFER TO AMM D/O 25-33-00-00 FOR THE APPLICABLE INSTALLATION INSTRUCTIONS. AS PER AMM TASK 53-41-00-220-808-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	CAB/ACFT_TECH			HRS				
Insp.				HRS				

CLOSE UP**Job Description**

3.
E. PERFORM JOB CLOSE UP AND RETURN AIRCARFT BACK TO NORMAL AS PER AMM 53-41-00-220-808-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	ACFT_TECH/AP			HRS				
Insp.				HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____



MET.31486331

Task Card Title:

PAX/CREW DR CUTOUT UPR CORN NDT INSP

Task Card NO:

534124-01-3

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following according (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.25383414		Task Card Title: FUSELAGE AT WASTE SVC PANEL NDT INSP					
Task Card NO: 534126-01-3		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: II,INSP,NDT_INSP,CAB,ACFT_TECH,NDT		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 09			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 412	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: SDI		Special Code: INSP		MSG Code: ALI, WFD		Request: Phase: CLEAN-UP, INSPECTION, X-RAY / NDT	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 100							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
ALI		534126-01-3					
AMM		53-41-00-220-810-A					
AMM		534100-220-810					
DO		WFD					
NDT		NTM 53-41-26					
ACCESS PANELS:							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
LOTOXANE		NON-AQUEOUS CLEANER				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
No tools assigned to this Task Item							
PREPARATION							
Job Description							
A. CLEAN THE INSPECTION AREA AS REQUIRED.							
STEP COMPLETION SIGN OFF:							
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date	
				HRS		Day	Month
Mechanic/s	CAB/ACFT_TECH			HRS			
Insp.				HRS			
PREPARATION							
Job Description							
B. PERFORM A VISUAL INSPECTION OF THE OUTER SURFACE OF THE INSPECTION AREA. LOOK FOR DAMAGE, AND							



MET.25383414

Task Card Title:

FUSELAGE AT WASTE SVC PANEL NDT INSP

Task Card NO:

534126-01-3

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

DEFECTS IN THE SHAPE OF THE SURFACE AS PER AMM TASK 53-41-00-220-810-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	II/INSP			HRS				

TASK INSTRUCTIONS**Job Description**

A. PERFORM A SPECIAL DETAILED INSPECTION (HFEC) OF FUSELAGE SKIN EXTERNAL SURFACE AT WASTE SERVICE PANEL CUTOUT, BETWEEN FR 65 AND FR 66 BELOW STRINGER 33, TWO UPPER RIVET ROWS AT SKIN TO REINFORCEMENT JOINT (REF. NTM 534126) AS PER AMM TASK 53-41-00-220-810-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	NDT_INSP/NDT			HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

_____, _____, _____, _____, _____, _____, _____, _____, _____, _____

Note: Make sure to create the finding Work Order on task card level.

Remark's: _____

_____, _____, _____, _____, _____, _____, _____, _____, _____, _____



Task Card Title:

FUSELAGE AT WASTE SVC PANEL NDT INSP

Task Card NO:

534126-01-3

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.25402520		Task Card Title: FUSE BETWEEN STGR4 & STGR5 NDT INSP					
Task Card NO: 534127-01-3		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: II,INSP,NDT_INSP,CAB,ACFT_TECH,NDT		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 05			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 413	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: SDI		Special Code: INSP		MSG Code: ALI		Request: ON,INSPECTION,JOB-CLOSEUP,LOOSEUP,JOB-CLOSEUP,JOE-CLOSEUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 263,264							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
ALI		534127-01-3					
AMM		53-41-00-220-811-A					
AMM		534100-220-811					
NDT		NTM 53-41-27					
ACCESS PANELS:							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
MILT81533		SOLVENT DEGREASER.				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
No tools assigned to this Task Item							
TASK PREPARATION							
Job Description							
A. PERFORM JOB SET UP AS PER AMM TASK 53-41-00-220-811-A AND REMOVE THE FOLLOWING:							
(1) THE DOOR FRAME LININGS (REF. AMM TASK 25-23-45-000-003-A AND 25-23-45-000-004-A).							
(2) THE CEILING PANELS 261CC AND 262CC (REF. AMM TASK 25-23-42-000-002-A).							
(3) THE INSULATION BLANKETS FROM THE INSPECTION AREA (REF. AMM TASK 25-80-00-000-001-A).							
STEP COMPLETION SIGN OFF:							
		Qualification / Skill		Number of employees		Duration	
Mechanic/s		CAB/ACFT_TECH					
Insp.							
TASK PREPARATION							
Job Description							



Task Card Title:

FUSE BETWEEN STGR4 & STGR5 NDT INSP

Task Card NO:

534127-01-3

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

B. CLEAN THE INSPECTION AREA AS PER AMM TASK 53-41-00-220-811-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	CAB/ACFT_TECH			HRS				
Insp.				HRS				

TASK INSTRUCTION**Job Description**

A. PERFORM A SPECIAL DETAILED INSPECTION OF THE LH FUSELAGE INTERNAL STRUCTURE BETWEEN STGR4 AND STGR5 FROM LATERAL FR68 JOINT TO UPPER FR68 (REF. NTM 534127) AS PER AMM TASK 53-41-00-220-811-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	NDT_INSP/NDT			HRS				

TASK INSTRUCTION**Job Description**

B. PERFORM A SPECIAL DETAILED INSPECTION OF THE RH FUSELAGE INTERNAL STRUCTURE BETWEEN STGR4 AND STGR5 FROM LATERAL FR68 JOINT TO UPPER FR68 (REF. NTM 534127) AS PER AMM TASK 53-41-00-220-811-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	NDT_INSP/NDT			HRS				

TASK CLOSE UP**Job Description**

A. OK TO INSTALL THE INSULATION BLANKETS, CEILING PANELS 261CC & 262CC AND DOOR FRAME LININGS.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	II/INSP			HRS				

TASK CLOSE UP**Job Description**

B. INSTALL THE INSULATION BLANKETS (REF. AMM TASK 25-80-00-400-001-A).

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year

 MET.25402520	Task Card Title: FUSE BETWEEN STGR4 & STGR5 NDT INSP						
Task Card NO: 534127-01-3		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
Mechanic/s	CAB/ACFT_TECH			HRS			
Insp.	II/INSP			HRS			
TASK CLOSE UP							
Job Description							
C. INSTALL THE CEILING PANELS 261CC AND 262CC (REF. AMM TASK 25-23-42-400-002-A).							
STEP COMPLETION SIGN OFF:							
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date	
				HRS		Day	Month
Mechanic/s	CAB/ACFT_TECH			HRS			
Insp.	INSP/II			HRS			
TASK CLOSE UP							
Job Description							
D. INSTALL THE DOOR FRAME LININGS (REF. AMM TASK 25-23-45-400-008-A AND 25-23-45-400-005-A).							
STEP COMPLETION SIGN OFF:							
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date	
				HRS		Day	Month
Mechanic/s	CAB/ACFT_TECH			HRS			
Insp.	INSP/II			HRS			
-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____. Task card finding (Tick Applicable Box) [☐] Yes [☐] No. If yes update the system and list Task card finding WO below Work order No: _____ _____ Note: Make sure to creat the finding Work Order on task card level. Remark's: _____ _____							



Task Card Title:

FUSE BETWEEN STGR4 & STGR5 NDT INSP

Task Card NO:

534127-01-3

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following accordingly (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.32478491		Task Card Title: REAR FUSELAGE					
Task Card NO: 534135-02-1		Work Package: ASP/H-26 C7-CHK			A/C Registration: HZ-ASP		
A/C Type: 321		Single Running Taskcard		Main Skill: IL,INSP,ACFT_TECH,AP		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area:			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 414	
ENCLOSURE: ☐ CMR: ☐ CPCP: ☒ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☐							
Type Code: GVI		Special Code: AP		MSG Code: CPCP		Request: Phase: JOB SETUP,INSPECTION,JOB-CLOSEUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 261,262,263,264							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
AMTOSS		534100-210-848					
SSI		534135-02-1					
ACCESS PANELS:							
832, 842							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
No parts assigned to this Task Item							
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
No tools assigned to this Task Item							
TASK PREPARATION							
Job Description							
1. A. PERFORM JOB SET UP FOR GENERAL VISUAL INSPECTION OF INTERNAL STRUCTURE AROUND AFT PASSENGER/CREW DOOR CUTOUT, ABOVE CABIN FLOOR LEVEL, BETWEEN FR 65 AND FR 69 AND BETWEEN STRINGER 6 AND STRINGER 23, LH/RH, EXCLUDING THE LOWER CORNERS OF THE DOOR ENTRANCE AREA AT FRAME 66 AND FRAME 68, BETWEEN STRINGER 22 AND STRINGER 23, LH/RH. AS PER AMM 53-41-00-210-848-A.							
STEP COMPLETION SIGN OFF:							
Qualification / Skill		Number of employees		Duration		Number./Signature	
Date							
Day Month Year							
Mechanic/s		ACFT_TECH/AP		HRS			
Insp.				HRS			
TASK INSTRUCTIONS							
Job Description							
2. A. PERFORM GENERAL VISUAL INSPECTION OF INTERNAL STRUCTURE AROUND AFT PASSENGER/CREW DOOR CUTOUT, ABOVE CABIN FLOOR LEVEL, BETWEEN FR 65 AND FR 69 AND BETWEEN STRINGER 6 AND STRINGER 23, LH/RH,							

 MET.32478491	Task Card Title: REAR FUSELAGE						
Task Card NO: 534135-02-1	Work Package: ASP/H-26 C7-CHK	A/C Registration: HZ-ASP					
EXCLUDING THE LOWER CORNERS OF THE DOOR ENTRANCE AREA AT FRAME 66 AND FRAME 68, BETWEEN STRINGER 22 AND STRINGER 23, LH/RH. AS PER AMM 53-41-00-210-848-A.							
STEP COMPLETION SIGN OFF:							
	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s				HRS			
Insp.	II/INSP			HRS			
TASK CLOSE UP							
Job Description							
3. A. PER FORM JOB-CLOSEUP AND RETURN AIRCRAFT BACK TO NORMAL AS PER AMM 53-41-00-210-848-A.							
STEP COMPLETION SIGN OFF:							
	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/AP			HRS			
Insp.				HRS			
-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____. Task card finding (Tick Applicable Box) [☐] Yes [☐] No. If yes update the system and list Task card finding WO below Work order No: _____ _____ Note: Make sure to creat the finding Work Order on task card level. Remark's: _____ _____							



MET.32478491

Task Card Title:

REAR FUSELAGE



Task Card NO:

534135-02-1

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following according (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station

Date

Signature

 MET.32722083		Task Card Title: AFT CRGO DOOR ACTUA ATTACH BRKT INSP					
Task Card NO: 534163-01-1		Work Package: ASP/H-26 C7-CHK			A/C Registration: HZ-ASP		
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,AF,ACFT_TECH		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 09			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 415	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☐							
Type Code: GVI		Special Code: INSP		MSG Code: MRB		Request: Phase: PRE INSP, PRE INSP, PRE INSP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 152							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
AMM		53-41-00-210-819-A					
AMM		534100-210-819					
MRB		534163-01-1					
ACCESS PANELS:							
151CC, 826							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
LOTOXANE		NON-AQUEOUS CLEANER				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
No tools assigned to this Task Item							
TASK PREPARATION							
Job Description							
A. CLEAN THE INSPECTION AREA WITH A CLEAN LINT-FREE COTTON CLOTH AND CLEANING AGENTS AND LET THE AREA DRY AS PER AMM TASK 53-41-00-210-819-A.							
STEP COMPLETION SIGN OFF:							
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date	
				HRS		Day	Month
Mechanic/s	AF/ACFT_TECH			HRS			
Insp.				HRS			
TASK INSTRUCTIONS							
Job Description							
A. PERFORM A GENERAL VISUAL INSPECTION OF THE AFT CARGO DOOR ACTUATOR ATTACH BRACKET BETWEEN THE FLOOR BEAMS, FR53, FR54 AND FR55 AS PER AMM TASK 53-41-00-210-819-A.							
STEP COMPLETION SIGN OFF:							



MET.32722083

Task Card Title:

AFT CRGO DOOR ACTUA ATTACH BRKT INSP

Task Card NO:

534163-01-1

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	INSP/II			HRS				

TASK CLOSE UP**Job Description**

A. MAKE SURE THAT THE WORK AREA IS CLEAN AND CLEAR OF TOOLS AND ALL OTHER ITEMS.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS				
Insp.				HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____



MET.32722083

Task Card Title:

AFT CRGO DOOR ACTUA ATTACH BRKT INSP

Task Card NO:

534163-01-1

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following according (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.32722067		Task Card Title: BULK CARGO DOOR CUTOUT SEALING PROFILE					
Task Card NO: 534172-01-4		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,AF,ACFT_TECH		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 09			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 416	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☐							
Type Code: GVI		Special Code: INSP		MSG Code: ALI		Request: CLEAN-UP,INSPECTION,INSPECTION	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 162							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
ALI		534172-01-4					
AMM		53-41-00-210-804-A					
AMM		534100-210-804					
ACCESS PANELS:							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
08BAA9		NON AQUEOUS CLEANER - GENERAL				1.0	
12ABB1		CORROSION PREVENTIVE, USE PN: AV 8				1.0	
12ABC1		CORROSION PREVENTIVE SOFT FILM				1.0	
14SBA1		TEXTILE - LINT FREE COTTON AMS3819				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
No tools assigned to this Task Item							
PREPARATION							
Job Description							
A. CLEAN THE INSPECTION AREA AS REQUIRED AS PER AMM TASK 53-41-00-210-804-A.							
STEP COMPLETION SIGN OFF:							
Qualification / Skill		Number of employees		Duration		Number./Signature	
Date							
Day		Month		Year			
Mechanic/s		AF/ACFT_TECH		HRS			
Insp.				HRS			
TASK INSTRUCTION							
Job Description							



MET.32722067

Task Card Title:

BULK CARGO DOOR CUTOUT SEALING PROFILE

Task Card NO:

534172-01-4

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

A. PERFORM GENERAL VISUAL INSPECTION OF THE SEALING PROFILE OF THE BULK CARGO DOOR CUTOUT AT THE UPPER CORNERS AS PER AMM TASK 53-41-00-210-804-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	INSP/II			HRS				

TASK INSTRUCTION**Job Description**

B. APPLY TEMPORARY PROTECTION SYSTEM AS PER AMM TASK 53-41-00-210-804-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS				
Insp.				HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

_____, _____, _____, _____, _____, _____, _____, _____

Note: Make sure to create the finding Work Order on task card level.

Remark's: _____

_____, _____, _____, _____, _____, _____, _____, _____



Task Card Title:

BULK CARGO DOOR CUTOUT SEALING PROFILE

Task Card NO:

534172-01-4

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following according (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.25383649		Task Card Title: SDI (ROTO) OF DOOR STOP FITTING FASTENER HOLES IN F R 47.2A AND FR 47.4 AT STRINGER 13 AND AT STRINGER 22					
Task Card NO: 534189-02-1		Work Package: (LH/RH). ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: IL,INSP,RII,NDT_INSP,CAB,ACFT _TECH,CLEANER,NDT		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area:			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 417	
ENCLOSURE: ☐ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☐							
Type Code: SDI		Special Code: INSP		MSG Code: ALI		Request: Phase: JOB-SETUP,CLEAN-UP,INSPECTION,JOB-CLOSEUP,JOB-CLOSEUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 251,252							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
AMM		53-41-00-280-811-A					
AMM		534100-280-811					
ACCESS PANELS:							
834, 844							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
LOTOXANE		NON-AQUEOUS CLEANER				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
No tools assigned to this Task Item							
TASK PREPARATION							
Job Description							
A. PERFORM JOB SETUP AS PER AMM TASK 53-41-00-280-811-A AND REMOVE THE APPLICABLE BOLTS FROM THE DOOR STOP FITTINGS (REF. AMM TASK 52-22-31-000-002-A).							
STEP COMPLETION SIGN OFF:							
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date	
						Day	Month
Mechanic/s	CAB/ACFT_TECH		HRS				
Insp.			HRS				
TASK PREPARATION							
Job Description							
B. CLEAN THE INSPECTION AREA AS REQUIRED PER AMM 53-41-00-280-811-A.							
STEP COMPLETION SIGN OFF:							



Task Card Title:

SDI (ROTO) OF DOOR STOP FITTING FASTENER HOLES IN FRAMES 47.2A AND 47.4 AT STRINGER 13 AND AT STRINGER 22


Task Card NO:

534189-02-1

Work Package (LH/RH).

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/CLEANER		HRS				
Insp.			HRS				

TASK INSTRUCTIONS**Job Description**

A. PERFORM A SPECIAL DETAILED INSPECTION OF THE FASTENER HOLES OF THE DOOR STOP FITTINGS FOR DAMAGE OR DISCONTINUITIES REF. NTM 53-41-89. DO THIS INSPECTION ON FRAMES 47.2A AND 47.4, AT STRINGERS 13 AND 22, ON THE LEFT AND RIGHT SIDES. AS PER AMM TASK 53-41-00-280-811-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	NDT_INSP/NDT		HRS				

TASK CLOSE UP**Job Description**

A. OK TO INSTALL THE BOLTS ON THE DOOR STOP FITTINGS.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	II/INSP		HRS				

TASK CLOSE UP**Job Description**

B. INSTALL THE APPLICABLE BOLTS ON THE DOOR STOP FITTINGS (REF. AMM TASK 52-22-31-400-002-A). (REF AMM 53-41-00-280-811-A).

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	CAB/ACFT_TECH		HRS				
Insp.	INSP/RII		HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to create the finding Work Order on task card level.

Remark's: _____



Task Card Title:

**SDI (ROTO) OF DOOR STOP FITTING FASTENER HOLES IN F
R 47.2A AND FR 47.4 AT STRINGER 13 AND AT STRINGER 22**


Task Card NO:

534189-02-1

Work Package (LH/RH).

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following according (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.28342398		Task Card Title: LWR FLANGES OF FR72 & FR74 NDT INSP					
Task Card NO: 535163-01-1		Work Package: ASP/H-26 C7-CHK			A/C Registration: HZ-ASP		
A/C Type: 321		Single Running Taskcard		Main Skill: II,INSP,NDT_INSP,CAB,ACFT_TECH,NDT		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 09			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 418	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: SDI		Special Code: INSP		MSG Code: ALI		Request: CLEAN-UP,INSPECTION,X-RAY / NDT	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 311,312							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
ALI		535163-01-1					
AMM		53-51-00-220-802-A					
AMM		535100-220-802					
ACCESS PANELS:							
312AR, 314AR							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
LOTOXANE		NON-AQUEOUS CLEANER				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
No tools assigned to this Task Item							
TASK PREPARATION							
Job Description							
A. CLEAN THE INSPECTION AREA AS REQUIRED.							
STEP COMPLETION SIGN OFF:							
		Qualification / Skill		Number of employees		Duration	
						Number./Signature	
						Date	
						Day Month Year	
Mechanic/s		CAB/ACFT_TECH				HRS	
Insp.						HRS	
TASK INSTRUCTIONS							
Job Description							
A. PERFORM A VISUAL CHECK OF THE INSPECTION AREA FOR DAMAGE AS PER AMM TASK 53-51-00-220-802-A.							



Task Card Title:

LWR FLANGES OF FR72 & FR74 NDT INSP

Task Card NO:

535163-01-1

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP**STEP COMPLETION SIGN OFF:**

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	II/INSP			HRS				

TASK INSTRUCTIONS**Job Description**

B. PERFORM A SPECIAL DETAILED INSPECTION (HFEC) OF THE LOWER FLANGES OF FR72 AND FR74 BETWEEN STGR10 LH AND STGR10 RH, (REF. NTM 535163) AS PER AMM TASK 53-51-00-220-802-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	NDT_INSP/NDT			HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to create the finding Work Order on task card level.

Remark's: _____



Task Card Title:

LWR FLANGES OF FR72 & FR74 NDT INSP

Task Card NO:

535163-01-1

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following according (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.32722078		Task Card Title: NO. 1 ENGINE AFT ATTACH BEAM INSP					
Task Card NO: 545107-01-1-001		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,ACFT_TECH,AP		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 01			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 419	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: DET		Special Code: INSP		MSG Code: MRB, ALI		Request: Phase: JOB-SETUP,CLEAN-UP,INSPECTION,JOB-CLOSURE EUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 415							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
ALI		545107-01-1					
AMM		54-51-00-200-005-A					
AMM		545100-200-005					
MRB		545107-01-1					
ACCESS PANELS:							
437AL, 438AR, 451AL, 452AR							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
LOTOXANE		NON-AQUEOUS CLEANER				1.0	
LOTOXANE		NON-AQUEOUS CLEANER				1.0	
08BAA9		NON AQUEOUS CLEANER - GENERAL				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
No tools assigned to this Task Item							
PREPARATION							
Job Description							
1. A. PERFORM JOB SET UP AND DEACTIVATE THE THRUST REVERSER AS PER AMM TASK 54-51-00-200-005-A.							
STEP COMPLETION SIGN OFF:							
Qualification / Skill		Number of employees		Duration		Number./Signature	
Date							
Day		Month		Year			
Mechanic/s		ACFT_TECH/AP		HRS			
Insp.				HRS			
PREPARATION							
Job Description							
1.							



MET.32722078

Task Card Title:

NO. 1 ENGINE AFT ATTACH BEAM INSP



Task Card NO:

545107-01-1-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

B. CLEAN THE INSPECTION AREA AS REQUIRED AS PER AMM 54-51-00-200-005-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/AP		HRS				
Insp.			HRS				

TASK INSTRUCTIONS

Job Description

2.

A. PERFORM A DETAILED VISUAL INSPECTION OF THE STRUCTURE OF THE L/H BEAM OF THE AFT ENGINE-TO-PYLON ATTACH-FITTING AS PER AMM TASK 54-51-00-200-005-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	INSP/II		HRS				

CLOSE UP

Job Description

3.

A. PERFORM JOB-CLOSEUP AS PER (REF. AMM TASK 78-30-00-081-041-B) (AMM 54-51-00-200-005-A).

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/AP		HRS				
Insp.			HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to create the finding Work Order on task card level.

Remark's: _____



Task Card Title:

NO. 1 ENGINE AFT ATTACH BEAM INSP

Task Card NO:

545107-01-1-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.32722080		Task Card Title: NO. 2 ENGINE AFT ATTACH BEAM INSP					
Task Card NO: 545107-01-1-002		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: IL,INSP,ACFT_TECH,AP		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 02			
Internal Check:		Check Type:		Work Order NO:			
						Tally Sequence NO: 420	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: DET		Special Code: INSP		MSG Code: MRB, ALI		Request: JOB-SETUP,CLEAN-UP,INSPECTION,JOB-CLOSURE Phase: EUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 425							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
ALI		545107-01-1					
AMM		54-51-00-200-005-A					
AMM		545100-200-005					
MRB		545107-01-1					
ACCESS PANELS:							
447AL, 448AR, 461AL, 462AR							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
LOTOXANE		NON-AQUEOUS CLEANER				1.0	
14SBA1		TEXTILE - LINT FREE COTTON AMS3819				1.0	
LOTOXANE		NON-AQUEOUS CLEANER				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
No tools assigned to this Task Item							
PREPARATION							
Job Description							
1. A. PERFORM JOB SET UP AND DEACTIVATE THE THRUST REVERSER AS PER AMM TASK 54-51-00-200-005-A.							
STEP COMPLETION SIGN OFF:							
Qualification / Skill		Number of employees		Duration		Number./Signature	
Date							
Day Month Year							
Mechanic/s		ACFT_TECH/AP		HRS			
Insp.				HRS			
PREPARATION							
Job Description							



Task Card Title:

NO. 2 ENGINE AFT ATTACH BEAM INSP



Task Card NO:

545107-01-1-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

1.

B. CLEAN THE INSPECTION AREA AS REQUIRED AMM 54-51-00-200-005-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/AP		HRS				
Insp.			HRS				

TASK INSTRUCTIONS

Job Description

2.

A. PERFORM A DETAILED VISUAL INSPECTION OF THE STRUCTURE OF THE R/H BEAM OF THE AFT ENGINE-TO-PYLON ATTACH-FITTING AS PER AMM TASK 54-51-00-200-005-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	II/INSP		HRS				

CLOSE UP

Job Description

3.

A. JOB-CLOSEUP AS PER AMM 54-51-00-200-005-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/AP		HRS				
Insp.			HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to create the finding Work Order on task card level.

Remark's: _____



MET.32722080

Task Card Title:

NO. 2 ENGINE AFT ATTACH BEAM INSP

Task Card NO:

545107-01-1-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following according (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.25473704		Task Card Title: L/H OUTER WING REAR SPAR AFT FACE					
Task Card NO: 572007-01-4-001		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: IL,INSP,AF,ACFT_TECH		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area:			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 421	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☒ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: DET		Special Code: INSP		MSG Code: CPCP, MRB, ALI		Request: Phase: JOB-SETUP,CLEAN-UP,INSPECTION,JOB-CLOSURE,EUP,JOB-CLOSEUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 571							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
ALI		ALI 572007-01-4					
AMM		57-20-00-200-005-A					
AMM		572000-200-005					
MRB		572007-01-2					
SSI		572007-01-2					
ACCESS PANELS:							
734							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
LOTOXANE HD		SOLVENT				1.0	
TN10138		COMPOUND CORROSION INHIB*HAZ MATS/L				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
98D27803500001		LOCK				1.0	
PREPARATION							
Job Description							
A. PREPARE FOR TASK ACCOMPLISHMENT AS PER AMM TASK 57-20-00-200-005-A.							
STEP COMPLETION SIGN OFF:							
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date	
				HRS		Day	Month
Mechanic/s	AF/ACFT_TECH			HRS			
Insp.				HRS			
PREPARATION							
Job Description							
B. CLEAN THE REAR SPAR AFT FACE BETWEEN RIB 1 AND RIB 5, USING THE SOLVENTGENERAL PURPOSE WITH							



Task Card Title:

L/H OUTER WING REAR SPAR AFT FACE



Task Card NO:

572007-01-4-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

LINT-FREE COTTON CLOTH.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS				
Insp.				HRS				

TASK INSTRUCTIONS

Job Description

A. PERFORM A DETAILED VISUAL INSPECTION OF THE L/H OUTER WING, REAR SPAR, AFT FACE, BETWEEN RIB 1 AND GEAR REAR SPAR ANGLE AS PER AMM TASK 57-20-00-200-005-A.

NOTE

Ensure to fill the attached TSV# 92-634 along with this task.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	II/INSP			HRS				

CLOSE UP

Job Description

A. APPLY A LAYER OF STORAGE PRESERVATION CORROSION TEMPORARY PREVENTIVE COMPOUND TO THE REAR SPAR AFT FACE BETWEEN RIBS 1 AND 5 TOGETHER WITH THE REAR SPAR ANGLE (REF. AMM TASK 51-78-00-916-001).

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS				
Insp.	II/INSP			HRS				

CLOSE UP

Job Description

B. RETURN THE AIRCRAFT TO ITS NORMAL CONFIGURATION AS PER AMM TASK 57-20-00-200-005-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS				



Task Card Title:

L/H OUTER WING REAR SPAR AFT FACE

Task Card NO:

572007-01-4-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

Insp.

HRS

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

_____, _____, _____, _____, _____, _____, _____, _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 2 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 3 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 4 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 5 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

**Task Completion Close Up And
System Update****Station****Date****Signature**

 MET.25445741		Task Card Title: R/H OUTER WING REAR SPAR AFT FACE					
Task Card NO: 572007-01-4-002		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,AF,ACFT_TECH		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area:			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 422	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☒ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: DET		Special Code: INSP		MSG Code: CPCP, MRB, ALI		Request: JOB-SETUP,CLEAN-UP,INSPECTION,JOE-CLOSEUP,JOE-CLOSEUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 671							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
ALI		ALI 572007-01-4					
AMM		57-20-00-200-005-A					
AMM		572000-200-005					
MRB		572007-01-2					
SSI		572007-01-2					
ACCESS PANELS:							
744							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
LOTOXANE HD		SOLVENT				1.0	
TN10138		COMPOUND CORROSION INHIB*HAZ MATS/L				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
98D27803500001		LOCK				1.0	
PREPARATION							
Job Description							
A. PREPARE FOR TASK ACCOMPLISHMENT AS PER AMM TASK 57-20-00-200-005-A.							
STEP COMPLETION SIGN OFF:							
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date	
				HRS		Day	Month
Mechanic/s	AF/ACFT_TECH			HRS			
Insp.				HRS			
PREPARATION							
Job Description							
B. CLEAN THE REAR SPAR AFT FACE BETWEEN RIB 1 AND RIB 5, USING THE SOLVENTGENERAL PURPOSE WITH							



Task Card Title:

R/H OUTER WING REAR SPAR AFT FACE

Task Card NO:

572007-01-4-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

LINT-FREE COTTON CLOTH.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS				
Insp.				HRS				

TASK INSTRUCTIONS**Job Description**

A. PERFORM A DETAILED VISUAL INSPECTION OF THE R/H OUTER WING, REAR SPAR, AFT FACE, BETWEEN RIB 1 AND GEAR REAR SPAR ANGLE AS PER AMM TASK 57-20-00-200-005-A.

NOTE

Ensure to fill the attached TSV# 92-634 along with this task.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	INSP/II			HRS				

CLOSE UP**Job Description**

A. APPLY A LAYER OF STORAGE PRESERVATION CORROSION TEMPORARY PREVENTIVE COMPOUND TO THE REAR SPAR AFT FACE BETWEEN RIBS 1 AND 5 TOGETHER WITH THE REAR SPAR ANGLE (REF. AMM TASK 51-78-00-916-001).

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS				
Insp.	INSP/II			HRS				

CLOSE UP**Job Description**

B. RETURN THE AIRCRAFT TO ITS NORMAL CONFIGURATION AS PER AMM TASK 57-20-00-200-005-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS				



Task Card Title:

R/H OUTER WING REAR SPAR AFT FACE

Task Card NO:

572007-01-4-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

Insp.

HRS

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

_____, _____, _____, _____, _____, _____, _____, _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 2 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 3 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 4 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 5 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

**Task Completion Close Up And
System Update****Station****Date****Signature**

 MET.25580778		Task Card Title: LH OUTER WNG REAR SPAR FWD FACE INSP					
Task Card NO: 572011-01-4-001		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,II,RII,ACFT_TECH,FT		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 07			
Internal Check:		Check Type:		Work Order NO:			
						Tally Sequence NO: 423	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: DET		Special Code: INSP		MSG Code: ALI		Request: JOB-SETUP,CLEAN-UP,INSPECTION,JOB-CLOSURE,PHASE 1 EUP,JOB-CLOSEUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 540							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
ALI		572011-01-4					
AMM		57-20-00-200-008-A					
AMM		572000-200-008					
ACCESS PANELS:							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
LOTOXANE		NON-AQUEOUS CLEANER				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
98D27803500001		LOCK				1.0	
98D57004014000		HOOK VOVER (RIB 2 SURGE DOORS)				1.0	
PREPARATION							
Job Description							
A. PERFORM JOB SET UP AS PER AMM TASK 57-20-00-200-008-A, REMOVE THE FUEL ACCESS PANELS 540AB, 540BB, 540CB AND OPEN THE RIB 2 SURGE DOORS 540BZ, USING TSV 11-3099.							
STEP COMPLETION SIGN OFF:							
Qualification / Skill		Number of employees		Duration		Number./Signature	
Date							
Day Month Year							
Mechanic/s		ACFT_TECH/FT		HRS			

 MET.25580778	Task Card Title: LH OUTER WNG REAR SPAR FWD FACE INSP						
Task Card NO: 572011-01-4-001		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			

Insp.				HRS			
-------	--	--	--	-----	--	--	--

PREPARATION

Job Description

B. CLEAN THE INSPECTION AREA WITH NON AQUEOUS CLEANER AND A LINT FREE COTTON CLOTH.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	ACFT_TECH/FT			HRS				
Insp.				HRS				

TASK INSTRUCTION

Job Description

A. PERFORM A DETAILED VISUAL INSPECTION OF LH OUTER WING, REAR-SPAR FORWARD FACE, BETWEEN RIB 1 AND RIB 8, INCLUDING THE REGION OF THE JOINT AT RIB 6 AND TOP AND BOTTOM FLANGES AS PER AMM TASK 57-20-00-200-008-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	INSP/II			HRS				

CLOSE UP

Job Description

A. CLOSE THE RIB 2 SURGE DOORS 540BZ AND INSTALL THE ACCESS PANELS 540AB, 540BB, 540CB, USING TSV 11-3101.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	ACFT_TECH/FT			HRS				
Insp.	INSP/RII			HRS				

CLOSE UP

Job Description

B. PERFORM JOB CLOSE UP AS PER AMM TASK 57-20-00-200-008-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	ACFT_TECH/FT			HRS				
Insp.				HRS				



Task Card Title:

LH OUTER WNG REAR SPAR FWD FACE INSP

Task Card NO:

572011-01-4-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

- Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to create the finding Work Order on task card level.

Remark's: _____

(1) If Task card interrupted or performed by different persons updates the system and update the following accordingly (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 2 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 3 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 4 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 5 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

**Task Completion Close Up And
System Update**

Station

Date

Signature

 MET.25523672		Task Card Title: RH OUTER WNG REAR SPAR FWD FACE INSP							
Task Card NO: 572011-01-4-002		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP					
A/C Type: 321		Single Running Taskcard		Main Skill: II,INSP,RII,ACFT_TECH,FT		PROD Final Acceptance:			
Project No: 01BASPC72608		Related Task Card:		A/C Area: 08					
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 424			
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒									
Type Code: DET		Special Code: INSP		MSG Code: ALI		Request: JOB-SETUP,CLEAN-UP,INSPECTION,JOB-CLOSURE,PHASE 1 EUP,JOB-CLOSEUP			
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.									
Zones: 640									
DOCUMENT REFERENCES:									
Doc Typ		Reference							
ALI		572011-01-4							
AMM		57-20-00-200-008-A							
AMM		572000-200-008							
ACCESS PANELS:									
MATERIAL REQUIREMENTS:									
Part Number		Description				Qty.			
LOTOXANE		NON-AQUEOUS CLEANER				1.0			
TOOLING REQUIREMENTS:									
Part Number		Description				Qty.			
98D27803500001		LOCK				1.0			
98D57004014000		HOOK VOVER (RIB 2 SURGE DOORS)				1.0			
PREPARATION									
Job Description									
A. PERFORM JOB SET UP AS PER AMM TASK 57-20-00-200-008-A, REMOVE THE FUEL ACCESS PANELS 640AB, 640BB, 640CB AND OPEN THE RIB 2 SURGE DOORS 640BZ, USING TSV 11-3099.									
STEP COMPLETION SIGN OFF:									
		Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
							Day	Month	Year
Mechanic/s		ACFT_TECH/FT		HRS					

 MET.25523672	Task Card Title: RH OUTER WNG REAR SPAR FWD FACE INSP						
Task Card NO: 572011-01-4-002		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			

Insp.				HRS			
-------	--	--	--	-----	--	--	--

PREPARATION								
Job Description								
B. CLEAN THE INSPECTION AREA WITH NON AQUEOUS CLEANER AND A LINT FREE COTTON CLOTH.								
STEP COMPLETION SIGN OFF:								
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	ACFT_TECH/FT			HRS				
Insp.				HRS				

TASK INSTRUCTION								
Job Description								
A. PERFORM A DETAILED VISUAL INSPECTION OF RH OUTER WING, REAR-SPAR FORWARD FACE, BETWEEN RIB 1 AND RIB 8, INCLUDING THE REGION OF THE JOINT AT RIB 6 AND TOP AND BOTTOM FLANGES AS PER AMM TASK 57-20-00-200-008-A.								
STEP COMPLETION SIGN OFF:								
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	II/INSP			HRS				

CLOSE UP								
Job Description								
A. CLOSE THE RIB 2 SURGE DOORS 640BZ AND INSTALL THE ACCESS PANELS 640AB, 640BB, 640CB, USING TSV 11-3101.								
STEP COMPLETION SIGN OFF:								
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	ACFT_TECH/FT			HRS				
Insp.	INSP/RII			HRS				

CLOSE UP								
Job Description								
B. PERFORM JOB CLOSE UP AS PER AMM TASK 57-20-00-200-008-A.								
STEP COMPLETION SIGN OFF:								
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	ACFT_TECH/FT			HRS				
Insp.				HRS				



Task Card Title:

RH OUTER WNG REAR SPAR FWD FACE INSP

Task Card NO:

572011-01-4-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

- Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to create the finding Work Order on task card level.

Remark's: _____

(1) If Task card interrupted or performed by different persons updates the system and update the following accordingly (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 2 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 3 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 4 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 5 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

**Task Completion Close Up And
System Update**

Station

Date

Signature

 MET.25478500		Task Card Title: L/H WING TOP SKIN UPPER SURFACE INSP					
Task Card NO: 572012-01-2-001		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: IL,INSP,AF,ACFT_TECH		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 07			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 425	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: DET		Special Code: INSP		MSG Code: ALI		Request: EUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 500							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
ALI		ALI 572012-01-2					
AMM		57-20-00-220-001-A					
AMM		572000-220-001					
ACCESS PANELS:							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
AMS3819		CLEAN LINT-FREE CLOTH				1.0	
LOTOXANE		NON-AQUEOUS CLEANER				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
98D27803500001		LOCK				1.0	
PREPARATION							
Job Description							
A. PERFORM JOB SET UP AS PER AMM TASK 57-20-00-220-001-A,INSTALL LOCKING TOOL ZERO POS (98D27803500001) ON THE FLAP/SLAT CONTROL LEVER.							
STEP COMPLETION SIGN OFF:							
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date	
						Day	Month
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				
PREPARATION							
Job Description							
B. CLEAN THE INSPECTION AREA WITH NON AQUEOUS CLEANER AND A LINT FREE COTTON CLOTH.							



Task Card Title:

L/H WING TOP SKIN UPPER SURFACE INSP

Task Card NO:

572012-01-2-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP**STEP COMPLETION SIGN OFF:**

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

TASK INSTRUCTION**Job Description**

A. PERFORM A DETAILED INSPECTION OF THE L/H OUTER WING, TOP SKIN UPPER SURFACE AT ATTACHMENT TO FRONT SPAR AND REAR SPAR, BETWEEN RIB 1 AND RIB 8 AS PER AMM TASK 57-20-00-220-001-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	II/INSP		HRS				

CLOSE UP**Job Description**

A REMOVE THE LOCKING TOOL ZERO POS (98D27803500001) AND RETURN AIRCRAFT BACK TO NORMAL AS PER AMM TASK 57-20-00-220-001A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to create the finding Work Order on task card level.

Remark's: _____



Task Card Title:

L/H WING TOP SKIN UPPER SURFACE INSP

Task Card NO:

572012-01-2-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.19333670		Task Card Title: R/H WING TOP SKIN UPPER SURFACE INSP					
Task Card NO: 572012-01-2-002		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,AF,ACFT_TECH		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 08			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 426	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: DET		Special Code: INSP		MSG Code: ALI		Request: JOB-SETUP,CLEAN-UP,INSPECTION,JOB-CLOSURE Phase: EUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 600							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
ALI		ALI 572012-01-2					
AMM		57-20-00-220-001-A					
AMM		572000-220-001					
ACCESS PANELS:							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
AMS3819		CLEAN LINT-FREE CLOTH				1.0	
LOTOXANE		NON-AQUEOUS CLEANER				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
98D27803500001		LOCK				1.0	
PREPARATION							
Job Description							
A. PERFORM JOB SET UP AS PER AMM TASK 57-20-00-220-001-A,INSTALL LOCKING TOOL ZERO POS (98D27803500001) ON THE FLAP/SLAT CONTROL LEVER.							
STEP COMPLETION SIGN OFF:							
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date	
				HRS		Day	Month
Mechanic/s	AF/ACFT_TECH			HRS			
Insp.				HRS			
PREPARATION							
Job Description							
B. CLEAN THE INSPECTION AREA WITH NON AQUEOUS CLEANER AND A LINT FREE COTTON CLOTH.							



Task Card Title:

R/H WING TOP SKIN UPPER SURFACE INSP

Task Card NO:

572012-01-2-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP**STEP COMPLETION SIGN OFF:**

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

TASK INSTRUCTION**Job Description**

A. PERFORM A DETAILED INSPECTION OF THE R/H OUTER WING, TOP SKIN UPPER SURFACE AT ATTACHMENT TO FRONT SPAR AND REAR SPAR, BETWEEN RIB 1 AND RIB 8 AS PER AMM TASK 57-20-00-220-001-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	INSP/II		HRS				

CLOSE UP**Job Description**

A REMOVE THE LOCKING TOOL ZERO POS (98D27803500001) AND RETURN AIRCRAFT BACK TO NORMAL AS PER AMM TASK 57-20-00-220-001A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [☐] Yes [☐] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to create the finding Work Order on task card level.

Remark's: _____



Task Card Title:

R/H WING TOP SKIN UPPER SURFACE INSP

Task Card NO:

572012-01-2-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following according (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.25516310		Task Card Title: L/H WING TOP SKIN RIB 1 AND 8 INSP							
Task Card NO: 572020-01-6-001		Work Package: ASP/H-26 C7-CHK			A/C Registration: HZ-ASP				
A/C Type: 321		Single Running Taskcard		Main Skill: II,INSP,RII,ACFT_TECH,FT		PROD Final Acceptance:			
Project No: 01BASPC72608		Related Task Card:		A/C Area: 07					
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 427			
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒									
Type Code: DET		Special Code: INSP		MSG Code: ALI		Request: INSPECTION, INSPECTION, JOB-CLOSEUP, JOB-CLOSEUP			
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.									
Zones: 540									
DOCUMENT REFERENCES:									
Doc Typ		Reference							
ALI		572020-01-6							
AMM		57-20-00-200-010-B							
AMM		572000-200-010							
ACCESS PANELS:									
MATERIAL REQUIREMENTS:									
Part Number		Description				Qty.			
AMS3819		CLEAN LINT-FREE CLOTH				1.0			
LOTOXANE		NON-AQUEOUS CLEANER				1.0			
TOOLING REQUIREMENTS:									
Part Number		Description				Qty.			
98D27803500001		LOCK				1.0			
98D57004013000		HOOK COVER (RIB 2 SURGE DOORS)				2.0			
98D57004014000		HOOK COVER (RIB 2 SURGE DOORS)				2.0			
PREPARATION									
Job Description									
A. PERFORM JOB SET UP AS PER AMM TASK 57-20-00-200-010-B, REMOVE THE FUEL ACCESS PANELS 540AB,540BB USING TSV 11-3099, OPEN THE RIB2 SURGE DOORS 540AZ, 540BZ.									
STEP COMPLETION SIGN OFF:									
		Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
							Day	Month	Year
Mechanic/s		ACFT_TECH/FT		HRS					
Insp.				HRS					
PREPARATION									
Job Description									



Task Card Title:

L/H WING TOP SKIN RIB 1 AND 8 INSP



Task Card NO:

572020-01-6-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

B. CLEAN THE INSPECTION AREA WITH NON AQUEOUS CLEANER AND A LINT FREE COTTON CLOTH.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	ACFT_TECH/FT			HRS				
Insp.				HRS				

TASK INSTRUCTION

Job Description

A. PERFORM A VISUAL CHECK OF THE LH OUTER WING, TOP SKIN STRINGERS, BETWEEN RIB 1 AND RIB 8, INCLUDING RUNOUTS AND AIR TRANSFER HOLES, STRINGER JOINTS, AND BUTT STRAP, AT STRINGER 11, EXCLUDING THE AREA INSIDE THE DRY BAY AS PER AMM TASK 57-20-00-200-010-B.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	II/INSP			HRS				

CLOSE UP

Job Description

A. OK TO CLOSE/INSTALL THE RIB2 SURGE DOORS AND THE FUEL ACCESS PANELS.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	INSP/II			HRS				

CLOSE UP

Job Description

B. REMOVE THE HOOK-COVER (RIB 2 SURGE DOORS) 98D57004013000 AND 98D57004014000 AND CLOSE THE RIB2 SURGE DOORS 540AZ, 540BZ.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	ACFT_TECH/FT			HRS				
Insp.	INSP/RII			HRS				

CLOSE UP

Job Description

C. INSTALL THE ACCESS PANELS 540AB,540BB (REF. AMM TASK 57-27-11-400-001-A USING TSV 11-3101.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year



Task Card Title:

L/H WING TOP SKIN RIB 1 AND 8 INSP

Task Card NO:

572020-01-6-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

Mechanic/s	ACFT_TECH/FT			HRS				
Insp.	INSP/RII			HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to create the finding Work Order on task card level.

Remark's: _____

(1) If Task card interrupted or performed by different personals updates the system and update the following according (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
Remark's: _____

Task Completion Close Up And System Update	Station	Date	Signature

Copyright of Saudia Technic - Regeneration is not allowed without prior approval by Saudia Technic.



Task Card Title:

R/H WING TOP SKIN RIB 1 AND 8 INSP

Task Card NO:

572020-01-6-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

B. CLEAN THE INSPECTION AREA WITH NON AQUEOUS CLEANER AND A LINT FREE COTTON CLOTH.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	ACFT_TECH/FT			HRS				
Insp.				HRS				

TASK INSTRUCTION

Job Description

A. PERFORM A VISUAL CHECK OF THE RH OUTER WING, TOP SKIN STRINGERS, BETWEEN RIB 1 AND RIB 8, INCLUDING RUNOUTS AND AIR TRANSFER HOLES, STRINGER JOINTS, AND BUTT STRAP, AT STRINGER 11, EXCLUDING THE AREA INSIDE THE DRY BAY AS PER AMM TASK 57-20-00-200-010-B.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	INSP/II			HRS				

CLOSE UP

Job Description

A. OK TO CLOSE/INSTALL THE RIB2 SURGE DOORS AND THE FUEL ACCESS PANELS.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	INSP/II			HRS				

CLOSE UP

Job Description

B. REMOVE THE HOOK-COVER (RIB 2 SURGE DOORS) 98D57004013000 AND 98D57004014000 AND CLOSE THE RIB2 SURGE DOORS 640AZ, 640BZ.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	ACFT_TECH/FT			HRS				
Insp.	INSP/RII			HRS				

CLOSE UP

Job Description

C. INSTALL THE ACCESS PANELS 640AB,640BB (REF. AMM TASK 57-27-11-400-001-A USING TSV 11-3101.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year



Task Card Title:

R/H WING TOP SKIN RIB 1 AND 8 INSP

Task Card NO:

572020-01-6-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

Mechanic/s	ACFT_TECH/FT			HRS				
Insp.	INSP/RII			HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

_____, _____, _____, _____, _____, _____, _____, _____, _____, _____

Note: Make sure to create the finding Work Order on task card level.

Remark's: _____

_____, _____, _____, _____, _____, _____, _____, _____, _____, _____

(1) If Task card interrupted or performed by different personals updates the system and update the following according (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 2 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 3 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 4 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 5 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

**Task Completion Close Up And
System Update**
Station**Date****Signature**

 MET.25494787		Task Card Title: L/H WNG BOTTOM SKIN/REAR SPAR INSP					
Task Card NO: 572032-01-2-001		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,AF,ACFT_TECH		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 07			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 429	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: DET		Special Code: INSP		MSG Code: ALI		Request: JOB-SETUP,CLEAN-UP,INSPECTION,JOB-CLOSURE EUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 500							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
ALI		572032-01-2					
AMM		57-20-00-200-020-A					
AMM		572000-200-020					
ACCESS PANELS:							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
08BAA9		NON AQUEOUS CLEANER - GENERAL				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
98D27803500001		LOCK				1.0	
PREPARATION							
Job Description							
A. PERFORM JOB SET UP AND INSTALL THE TOOL-ZERO LOCKING, FLAP SLAT CTL LEVER (98D27803500001) ON THE FLAP/SLAT CONTROL LEVER AS PER AMM TASK 57-20-00-200-020-A.							
STEP COMPLETION SIGN OFF:							
Qualification / Skill		Number of employees		Duration		Number./Signature	
Date		Day		Month		Year	
Mechanic/s		AF/ACFT_TECH		HRS			



MET.25494787

Task Card Title:

L/H WNG BOTTOM SKIN/REAR SPAR INSP



Task Card NO:

572032-01-2-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

Insp.

HRS

PREPARATION

Job Description

B. USE A CLEAN LINT FREE COTTON, MADE MOIST WITH 08BAA9 NON AQUEOUS CLEANER TO CLEAN THE LOWER SURFACE OF THE BOTTOM SKIN AT THE ATTACHMENT TO THE REAR SPAR BETWEEN RIB1 AND RIB8 AS PER AMM TASK 57-20-00-200-020-A.

NOTE: DO NOT INCLUDE THE AREAS COVERED BY:

- 1) THE MAIN LANDING GEAR REINFORCING PLATE
- 2) THE FLAP TRACK 2 FAIRING
- 3) THE PYLON FAIRING.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

TASK INSTRUCTION

Job Description

A. PERFORM A DETAILED INSPECTION OF THE LH OUTER WING, BOTTOM SKIN LOWER SURFACE AT ATTACHMENT TO REAR SPAR, BETWEEN RIB 1 AND RIB 8, EXCLUDING AREAS COVERED BY MLG REINFORCING PLATE, FLAP TRACK 2 FAIRING AND PYLON FAIRING AS PER AMM TASK 57-20-00-200-020-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	INSP/II		HRS				

CLOSE UP

Job Description

A. PERFORM JOB CLOSE UP AND REMOVE THE TOOL-ZERO LOCKING, FLAP SLAT CTL LEVER AS PER AMM TASK 57-20-00-200-020-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				



MET.25494787

Task Card Title:

L/H WNG BOTTOM SKIN/REAR SPAR INSP

Task Card NO:

572032-01-2-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

- Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to create the finding Work Order on task card level.

Remark's: _____

(1) If Task card interrupted or performed by different persons updates the system and update the following accordingly (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 2 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 3 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 4 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 5 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

**Task Completion Close Up And
System Update****Station****Date****Signature**

 MET.25494808		Task Card Title: R/H WNG BOTTOM SKIN/REAR SPAR INSP							
Task Card NO: 572032-01-2-002		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP					
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,AF,ACFT_TECH		PROD Final Acceptance:			
Project No: 01BASPC72608		Related Task Card:		A/C Area: 08					
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 430			
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒									
Type Code: DET		Special Code: INSP		MSG Code: ALI		Request: EUP			
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.									
Zones: 600									
DOCUMENT REFERENCES:									
Doc Typ		Reference							
ALI		572032-01-2							
AMM		57-20-00-200-020-A							
AMM		572000-200-020							
ACCESS PANELS:									
MATERIAL REQUIREMENTS:									
Part Number		Description				Qty.			
08BAA9		NON AQUEOUS CLEANER - GENERAL				1.0			
TOOLING REQUIREMENTS:									
Part Number		Description				Qty.			
98D27803500001		LOCK				1.0			
PREPARATION									
Job Description									
A. PERFORM JOB SET UP AND INSTALL THE TOOL-ZERO LOCKING, FLAP SLAT CTL LEVER (98D27803500001) ON THE FLAP/SLAT CONTROL LEVER AS PER AMM TASK 57-20-00-200-020-A.									
STEP COMPLETION SIGN OFF:									
		Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
							Day	Month	Year
Mechanic/s		AF/ACFT_TECH		HRS					



Task Card Title:

R/H WNG BOTTOM SKIN/REAR SPAR INSP



Task Card NO:

572032-01-2-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

Insp.

HRS

PREPARATION

Job Description

B. USE A CLEAN LINT FREE COTTON, MADE MOIST WITH 08BAA9 NON AQUEOUS CLEANER TO CLEAN THE LOWER SURFACE OF THE BOTTOM SKIN AT THE ATTACHMENT TO THE REAR SPAR BETWEEN RIB1 AND RIB8 AS PER AMM TASK 57-20-00-200-020-A.

NOTE: DO NOT INCLUDE THE AREAS COVERED BY:

- 1) THE MAIN LANDING GEAR REINFORCING PLATE
- 2) THE FLAP TRACK 2 FAIRING
- 3) THE PYLON FAIRING.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

TASK INSTRUCTION

Job Description

A. PERFORM A DETAILED INSPECTION OF THE RH OUTER WING, BOTTOM SKIN LOWER SURFACE AT ATTACHMENT TO REAR SPAR, BETWEEN RIB 1 AND RIB 8, EXCLUDING AREAS COVERED BY MLG REINFORCING PLATE, FLAP TRACK 2 FAIRING AND PYLON FAIRING AS PER AMM TASK 57-20-00-200-020-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	INSP/II		HRS				

CLOSE UP

Job Description

A. PERFORM JOB CLOSE UP AND REMOVE THE TOOL-ZERO LOCKING, FLAP SLAT CTL LEVER AS PER AMM TASK 57-20-00-200-020-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				



Task Card Title:

R/H WNG BOTTOM SKIN/REAR SPAR INSP

Task Card NO:

572032-01-2-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

- Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to create the finding Work Order on task card level.

Remark's: _____

(1) If Task card interrupted or performed by different persons updates the system and update the following accordingly (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 2 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 3 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 4 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 5 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

**Task Completion Close Up And
System Update****Station****Date****Signature**

 MET.25531669		Task Card Title: L/H WING BOTOM SKIN LDG PLATE INSP					
Task Card NO: 572034-01-3-001		Work Package: ASP/H-26 C7-CHK			A/C Registration: HZ-ASP		
A/C Type: 321		Single Running Taskcard		Main Skill: IL,INSP,AF,ACFT_TECH		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 07			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 431	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: GVI		Special Code: INSP		MSG Code: ALI		Request: Phase:	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRID OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 500							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
ALI		572034-01-3					
AMM		57-20-00-210-003-A					
AMM		572000-210-003					
ACCESS PANELS:							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
AMS3819		CLEAN LINT-FREE CLOTH				1.0	
LOTOXANE		NON-AQUEOUS CLEANER				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
98D27803500001		LOCK				1.0	
PREPARATION							
Job Description							
A. PERFORM JOB SET UP AS PER AMM TASK 57-20-00-210-003-A.							
STEP COMPLETION SIGN OFF:							
		Qualification / Skill		Number of employees		Duration	
Mechanic/s		AF/ACFT_TECH				HRS	
Insp.						HRS	
PREPARATION							
Job Description							
B. CLEAN THE INSPECTION AREA WITH NON AQUEOUS CLEANER AND A LINT FREE COTTON CLOTH.							
STEP COMPLETION SIGN OFF:							



Task Card Title:

L/H WING BOTOM SKIN LDG PLATE INSP



Task Card NO:

572034-01-3-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

TASK INSTRUCTION

Job Description

A. PERFORM A GENERAL VISUAL INSPECTION OF THE LH OUTER WING BOTTOM SKIN LOWER SURFACE MLG REINFORCING PLATE AS PER AMM TASK 57-20-00-210-003-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	II/INSP		HRS				

CLOSE UP

Job Description

A. MAKE SURE THAT THE WORK AREA IS CLEAN , CLEAR AND REMOVE THE LOCKING TOOL ZERO POS (98D27803500001) FROM THE FLAP/SLAT CONTROL LEVER.AS PER AMM TASK 57-20-210-003A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below
Work order No: _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____



Task Card Title:

L/H WING BOTOM SKIN LDG PLATE INSP

Task Card NO:

572034-01-3-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.25448956		Task Card Title: R/H WING BOTOM SKIN LDG PLATE INSP					
Task Card NO: 572034-01-3-002		Work Package: ASP/H-26 C7-CHK			A/C Registration: HZ-ASP		
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,AF,ACFT_TECH		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 08			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 432	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: GVI		Special Code: INSP		MSG Code: ALI		Request: JOB-SETUP,CLEAN-UP,INSPECTION,JOB-CLOSURE EUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRID OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 600							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
ALI		572036-01-3					
AMM		57-20-00-210-003-A					
AMM		572000-210-003					
ACCESS PANELS:							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
AMS3819		CLEAN LINT-FREE CLOTH				1.0	
LOTOXANE		NON-AQUEOUS CLEANER				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
98D27803500001		LOCK				1.0	
PREPARATION							
Job Description							
A. PERFORM JOB SET UP AS PER AMM TASK 57-20-00-210-003-A.							
STEP COMPLETION SIGN OFF:							
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date	
						Day Month Year	
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				
PREPARATION							
Job Description							
B. CLEAN THE INSPECTION AREA WITH NON AQUEOUS CLEANER AND A LINT FREE COTTON CLOTH.							
STEP COMPLETION SIGN OFF:							



Task Card Title:

R/H WING BOTOM SKIN LDG PLATE INSP

Task Card NO:

572034-01-3-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

TASK INSTRUCTION**Job Description**

A. PERFORM A GENERAL VISUAL INSPECTION OF THE RH OUTER WING BOTTOM SKIN LOWER SURFACE MLG REINFORCING PLATE AS PER AMM TASK 57-20-00-210-003-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	INSP/II		HRS				

CLOSE UP**Job Description**

A. MAKE SURE THAT THE WORK AREA IS CLEAN , CLEAR AND REMOVE THE LOCKING TOOL ZERO POS (98D27803500001) FROM THE FLAP/SLAT CONTROL LEVER.AS PER AMM TASK 57-20-210-003A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below
 Work order No: _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____



MET.25448956

Task Card Title:

R/H WING BOTOM SKIN LDG PLATE INSP

Task Card NO:

572034-01-3-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.19281322		Task Card Title: L/H WING BOTOM SKIN FLAP TRAK2 INSP					
Task Card NO: 572036-01-3-001		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,AF,ACFT_TECH,FT		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 07			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 433	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: DET		Special Code: INSP		MSG Code: ALI		Request: Phase:	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRID OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 531							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
AMM		57-20-00-200-022-A					
AMM		572000-200-022					
ACCESS PANELS:							
531CB, 531EB							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
AMS3819		CLEAN LINT-FREE CLOTH				1.0	
LOTOXANE		NON-AQUEOUS CLEANER				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
98D27803500001		LOCK				1.0	
PREPARATION							
Job Description							
A. PERFORM JOB SET UP AS PER AMM TASK 57-20-00-200-022-A,							
STEP COMPLETION SIGN OFF:							
		Qualification / Skill		Number of employees		Duration	
						Number./Signature	
						Date	
						Day Month Year	
Mechanic/s		ACFT_TECH/FT		HRS			
Insp.				HRS			
PREPARATION							
Job Description							
B. CLEAN THE INSPECTION AREA WITH NON AQUEOUS CLEANER AND A LINT FREE COTTON CLOTH.							
STEP COMPLETION SIGN OFF:							



Task Card Title:

L/H WING BOTOM SKIN FLAP TRAK2 INSP

Task Card NO:

572036-01-3-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/FT		HRS				
Insp.			HRS				

TASK INSTRUCTION**Job Description**

A. PERFORM A DETAILED INSPECTION OF THE LH OUTER WING BOTTOM-SKIN LOWER SURFACE, FORWARD OF REAR SPAR IN AREA COVERED BY FLAP TRACK 2 FAIRINGS, INCLUDING ATTACHMENT TO REAR SPAR AS PER AMM TASK 57-20-00-200-022-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	INSP/II		HRS				

CLOSE UP**Job Description**

A. MAKE SURE THAT THE WORK AREA IS CLEAN,CLEAR OF TOOLS AND REMOVE THE LOCKING TOOL ZERO POS (98D27803500001) FROM THE FLAP/SLAT CONTROL LEVER AS PER AMM TASK 57-20-00-200-022A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated._____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____



MET.19281322

Task Card Title:

L/H WING BOTOM SKIN FLAP TRAK2 INSP

Task Card NO:

572036-01-3-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.19281296		Task Card Title: R/H WING BOTOM SKIN FLAP TRAK2 INSP					
Task Card NO: 572036-01-3-002		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,AF,ACFT_TECH,FT		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 08			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 434	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: DET		Special Code: INSP		MSG Code: ALI		Request: EUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRID OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 631							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
AMM		57-20-00-200-022-A					
AMM		572000-200-022					
ACCESS PANELS:							
631CB, 631EB							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
AMS3819		CLEAN LINT-FREE CLOTH				1.0	
LOTOXANE		NON-AQUEOUS CLEANER				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
98D27803500001		LOCK				1.0	
PREPARATION							
Job Description							
A. PERFORM JOB SET UP AS PER AMM TASK 57-20-00-200-022-A,							
STEP COMPLETION SIGN OFF:							
Qualification / Skill		Number of employees		Duration		Number./Signature	
Date							
Day Month Year							
Mechanic/s		ACFT_TECH/FT		HRS			
Insp.				HRS			
PREPARATION							
Job Description							
B. CLEAN THE INSPECTION AREA WITH NON AQUEOUS CLEANER AND A LINT FREE COTTON CLOTH.							
STEP COMPLETION SIGN OFF:							



Task Card Title:

R/H WING BOTOM SKIN FLAP TRAK2 INSP

Task Card NO:

572036-01-3-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	ACFT_TECH/FT			HRS				
Insp.				HRS				

TASK INSTRUCTION**Job Description**

A. PERFORM A DETAILED INSPECTION OF THE RH OUTER WING BOTTOM-SKIN LOWER SURFACE, FORWARD OF REAR SPAR IN AREA COVERED BY FLAP TRACK 2 FAIRINGS, INCLUDING ATTACHMENT TO REAR SPAR AS PER AMM TASK 57-20-00-200-022-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	INSP/II			HRS				

CLOSE UP**Job Description**

A. MAKE SURE THAT THE WORK AREA IS CLEAN,CLEAR OF TOOLS AND REMOVE THE LOCKING TOOL ZERO POS (98D27803500001) FROM THE FLAP/SLAT CONTROL LEVER AS PER AMM TASK 57-20-00-200-022A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS				
Insp.				HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated._____.

Task card finding (Tick Applicable Box) [☐] Yes [☐] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____



MET.19281296

Task Card Title:

R/H WING BOTOM SKIN FLAP TRAK2 INSP

Task Card NO:

572036-01-3-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.25495005		Task Card Title: L-OUTER WNG BOTTOM SKIN RUNOUTS INSP					
Task Card NO: 572038-01-2-001		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,AF,ACFT_TECH		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 07			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 435	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: DET		Special Code: INSP		MSG Code: ALI		Request: EUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 540,640							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
ALI		572038-01-2					
AMM		57-20-00-200-023-A					
AMM		572000-200-023					
ACCESS PANELS:							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
08BAA9		NON AQUEOUS CLEANER - GENERAL				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
98D27803500001		LOCK				1.0	
PREPARATION							
Job Description							
A. PERFORM JOB SET UP AND INSTALL THE TOOL-ZERO LOCKING, FLAP SLAT CTL LEVER (98D27803500001) ON THE FLAP/SLAT CONTROL LEVER AS PER AMM TASK 57-20-00-200-023-A.							
STEP COMPLETION SIGN OFF:							
Qualification / Skill		Number of employees		Duration		Number./Signature	
Date		Day		Month		Year	
Mechanic/s		AF/ACFT_TECH		HRS			



Task Card Title:

L-OUTER WNG BOTTOM SKIN RUNOUTS INSP

Task Card NO:

572038-01-2-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

Insp.

HRS

PREPARATION**Job Description**

B. USE A CLEAN LINT FREE COTTON, MOIST WITH NON AQUEOUS CLEANER TO CLEAN THE LOWER-SURFACE OF THE BOTTOM SKIN AT THE RUNOUTS OF THE STRINGERS 2, 9, 10, 14 AND 15.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

TASK INSTRUCTION**Job Description**

A. PERFORM A DETAILED INSPECTION OF LH OUTER WING, BOTTOM-SKIN LOWER SURFACE AT RUNOUTS OF STRINGER 15 (RIB BAY 2-3), STRINGER 14 (RIB BAY 3-4), STRINGER 10 (RIB BAYS 2-3 AND 6-7), STRINGER 9 (RIB BAYS 2-3 AND 6-7) AND STRINGER 2 (RIB BAY 5-6) AS PER AMM TASK 57-20-00-200-023-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	INSP/II		HRS				

CLOSE UP**Job Description**

A. PERFORM JOB CLOSE UP AND REMOVE THE TOOL-ZERO LOCKING, FLAP SLAT CTL LEVER AS PER AMM TASK 57-20-00-200-023-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to create the finding Work Order on task card level.

Remark's: _____



MET.25495005

Task Card Title:

L-OUTER WNG BOTTOM SKIN RUNOUTS INSP

Task Card NO:

572038-01-2-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following according (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.25429077		Task Card Title: R-OUTER WNG BOTTOM SKIN RUNOUTS INSP					
Task Card NO: 572038-01-2-002		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,AF,ACFT_TECH		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 08			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 436	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: DET		Special Code: AF, INSP, OSS		MSG Code: ALI		Request: Phase: CLEAN-UP, INSPECTION, JOB-CLOSEUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 640							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
AMM		57-20-00-200-023-A					
AMM		572000-200-023					
ACCESS PANELS:							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
08BAA9		NON AQUEOUS CLEANER - GENERAL				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
98D27803500001		LOCK				1.0	
PREPARATION							
Job Description							
A. PERFORM JOB SET UP AND INSTALL THE TOOL-ZERO LOCKING, FLAP SLAT CTL LEVER (98D27803500001) ON THE FLAP/SLAT CONTROL LEVER AS PER AMM TASK 57-20-00-200-023-A.							
STEP COMPLETION SIGN OFF:							
Qualification / Skill		Number of employees		Duration		Number./Signature	
Date		Day		Month		Year	
Mechanic/s		AF/ACFT_TECH		HRS			
Insp.				HRS			



Task Card Title:

R-OUTER WNG BOTTOM SKIN RUNOUTS INSP

Task Card NO:

572038-01-2-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP**PREPARATION****Job Description**

B. USE A CLEAN LINT FREE COTTON, MOIST WITH NON AQUEOUS CLEANER TO CLEAN THE LOWER-SURFACE OF THE BOTTOM SKIN AT THE RUNOUTS OF THE STRINGERS 2, 9, 10, 14 AND 15.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

TASK INSTRUCTION**Job Description**

A. PERFORM A DETAILED INSPECTION OF RH OUTER WING, BOTTOM-SKIN LOWER SURFACE AT RUNOUTS OF STRINGER 15 (RIB BAY 2-3), STRINGER 14 (RIB BAY 3-4), STRINGER 10 (RIB BAYS 2-3 AND 6-7), STRINGER 9 (RIB BAYS 2-3 AND 6-7) AND STRINGER 2 (RIB BAY 5-6) AS PER AMM TASK 57-20-00-200-023-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	INSP/II		HRS				

CLOSE UP**Job Description**

A. PERFORM JOB CLOSE UP AND REMOVE THE TOOL-ZERO LOCKING, FLAP SLAT CTL LEVER AS PER AMM TASK 57-20-00-200-023-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below
Work order No: _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____



MET.25429077

Task Card Title:

R-OUTER WNG BOTTOM SKIN RUNOUTS INSP

Task Card NO:

572038-01-2-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.25494965		Task Card Title: L/H WNG BOTTOM SKIN LWR SURFACE INSP					
Task Card NO: 572042-01-4-001		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,AF,ACFT_TECH		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 07			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 437	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: GVI		Special Code: INSP		MSG Code: ALI		Request: JOB-SETUP,CLEAN-UP,INSPECTION,JOB-CLOSURE EUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 471							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
ALI		572042-01-4					
AMM		57-20-00-210-005-A					
AMM		572000-210-005					
ACCESS PANELS:							
471AL, 471AR, 471BL, 471BR, 471CL, 471CR, 471DL, 475AL, 475AR, 475BL, 475BR							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
08BAA9		NON AQUEOUS CLEANER - GENERAL				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
98D27803500001		LOCK				1.0	
TASK PREPARATION							
Job Description							
A. PERFORM JOB SET UP AND INSTALL THE TOOL-ZERO LOCKING, FLAP SLAT CTL LEVER (98D27803500001) ON THE FLAP/SLAT CONTROL LEVER AS PER AMM TASK 57-20-00-210-005-A.							
STEP COMPLETION SIGN OFF:							
Qualification / Skill		Number of employees		Duration		Number./Signature	
Date							
Day Month Year							
Mechanic/s		AF/ACFT_TECH		HRS			
Insp.				HRS			
TASK PREPARATION							
Job Description							
B. USE A CLEAN LINT FREE COTTON, MOIST WITH NON AQUEOUS CLEANER TO CLEAN THE APPLICABLE AREA FOR							



Task Card Title:

L/H WNG BOTTOM SKIN LWR SURFACE INSP

Task Card NO:

572042-01-4-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

INSPECTION.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS				
Insp.				HRS				

TASK INSTRUCTION**Job Description**

A. PERFORM A GENERAL VISUAL INSPECTION OF L/H OUTER WING, BOTTOM SKIN, LOWER SURFACE AT ATTACHMENT TO RIBS AND STRINGERS, IN AREA COVERED BY PYLON FAIRING AS PER AMM TASK 57-20-00-210-005-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	INSP/II			HRS				

TASK CLOSE UP**Job Description**

A. PERFORM JOB CLOSE UP AND REMOVE THE TOOL-ZERO LOCKING, FLAP SLAT CTL LEVER AS PER AMM TASK 57-20-00-210-005-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS				
Insp.				HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to create the finding Work Order on task card level.

Remark's: _____



Task Card Title:

L/H WNG BOTTOM SKIN LWR SURFACE INSP

Task Card NO:

572042-01-4-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.25401297		Task Card Title: R/H WNG BOTTOM SKIN LWR SURFACE INSP							
Task Card NO: 572042-01-4-002		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP					
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,AF,ACFT_TECH		PROD Final Acceptance:			
Project No: 01BASPC72608		Related Task Card:		A/C Area: 08					
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 438			
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒									
Type Code: GVI		Special Code: INSP		MSG Code: ALI		Request: EUP			
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRID OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.									
Zones: 481									
DOCUMENT REFERENCES:									
Doc Typ		Reference							
ALI		572042-01-4							
AMM		57-20-00-210-005-A							
AMM		572000-210-005							
ACCESS PANELS:									
481AL, 481AR, 481BL, 481BR, 481CL, 481CR, 481DR, 485AL, 485AR, 485BL, 485BR									
MATERIAL REQUIREMENTS:									
Part Number		Description				Qty.			
08BAA9		NON AQUEOUS CLEANER - GENERAL				1.0			
TOOLING REQUIREMENTS:									
Part Number		Description				Qty.			
98D27803500001		LOCK				1.0			
TASK PREPARATION									
Job Description									
A. PERFORM JOB SET UP AND INSTALL THE TOOL-ZERO LOCKING, FLAP SLAT CTL LEVER (98D27803500001) ON THE FLAP/SLAT CONTROL LEVER AS PER AMM TASK 57-20-00-210-005-A.									
STEP COMPLETION SIGN OFF:									
		Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
							Day	Month	Year
Mechanic/s		AF/ACFT_TECH		HRS					
Insp.				HRS					
TASK PREPARATION									
Job Description									
B. USE A CLEAN LINT FREE COTTON, MOIST WITH NON AQUEOUS CLEANER TO CLEAN THE APPLICABLE AREA FOR									



Task Card Title:

R/H WNG BOTTOM SKIN LWR SURFACE INSP

Task Card NO:

572042-01-4-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

INSPECTION.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS				
Insp.				HRS				

TASK INSTRUCTION**Job Description**

A. PERFORM A GENERAL VISUAL INSPECTION OF R/H OUTER WING, BOTTOM SKIN, LOWER SURFACE AT ATTACHMENT TO RIBS AND STRINGERS, IN AREA COVERED BY PYLON FAIRING AS PER AMM TASK 57-20-00-210-005-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	INSP/II			HRS				

TASK CLOSE UP**Job Description**

A. PERFORM JOB CLOSE UP AND REMOVE THE TOOL-ZERO LOCKING, FLAP SLAT CTL LEVER AS PER AMM TASK 57-20-00-210-005-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS				
Insp.				HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to create the finding Work Order on task card level.

Remark's: _____



MET.25401297

Task Card Title:

R/H WNG BOTTOM SKIN LWR SURFACE INSP

Task Card NO:

572042-01-4-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following according (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.25445926		Task Card Title: L/H WING BOTOM SKIN STRINGERS INSP					
Task Card NO: 572053-01-3-001		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: II,INSP,ACFT_TECH,FT		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 07			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 439	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: DET		Special Code: INSP		MSG Code: ALI		Request: EUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRID OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 540							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
ALI		572053-01-3					
AMM		57-20-00-200-026-A					
SVA		TSV 11-3099 A318 A320 A321 AIRCRAFT FUEL TANK OPEN UP .pdf					
SVA		TSV 11-3101 A318 A320 A321 AIRCRAFT FUEL TANK CLOSE UP AND LEAK CHECK.pdf					
ACCESS PANELS:							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
08BAA9		NON AQUEOUS CLEANER - GENERAL				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
98D27803500001		LOCK				1.0	
98D57004013000		HOOK COVER (RIB 2 SURGE DOORS)				1.0	
98D57004014000		HOOK VOVER (RIB 2 SURGE DOORS)				1.0	
TASK PREPARATION							
Job Description							
A. PERFORM JOB SET UP AS PER AMM TASK 57-20-00-200-026-A AND INSTALL THE ZERO LOCKING TOOL 98D27803500001 ON THE FLAP SLAT CTL LEVER.							
STEP COMPLETION SIGN OFF:							
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date	
						Day	Month
Mechanic/s	ACFT_TECH/FT		HRS				
Insp.			HRS				
TASK PREPARATION							
Job Description							
B. REMOVE THE FUEL ACCESS PANELS 540AB, 540BB AND 540CB (REF. AMM TASK 57-27-11-000-001-A AND							



Task Card Title:

L/H WING BOTOM SKIN STRINGERS INSP



Task Card NO:

572053-01-3-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

28-10-00-910-002-A), USING TSV 11-3099.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/FT		HRS				
Insp.			HRS				

TASK PREPARATION

Job Description

C. OPEN THE RIB2 SURGE DOORS 540AZ, 540BZ AND INSTALL THE HOOK-COVER (RIB 2 SURGE DOORS) (98D57004013000 ON THE FORWARD SURGE DOORS AND 98D57004014000 ON THE AFT SURGE DOORS).

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/FT		HRS				
Insp.			HRS				

TASK PREPARATION

Job Description

D. USE A CLEAN LINT FREE COTTON, MOIST WITH NON AQUEOUS CLEANER, TO CLEAN THE BOTTOM SKIN STRINGERS BETWEEN RIB1 AND RIB8. THIS INCLUDES THE DRAIN HOLES AND THE BUTTSTRAP AT STRINGERS 8 AND 11.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/FT		HRS				
Insp.			HRS				

TASK INSTRUCTIONS

Job Description

A. PERFORM A DETAILED INSPECTION OF L/H OUTER WING, BOTTOM SKIN STRINGERS, BETWEEN RIB1 AND RIB8, INCLUDING DRAIN HOLES IN STRINGERS AND BUTT STRAP AT STRINGER 8 AND STRINGER 11, EXCLUDING THE AREA INSIDE THE DRY BAY AS PER AMM TASK 57-20-00-200-026-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	II/INSP		HRS				

TASK CLOSE UP

Job Description

A. OT TO CLOSE THE RIB2 SURGE DOORS AND TO INSTALL THE FUEL ACCESS PANELS.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year



Task Card Title:

L/H WING BOTOM SKIN STRINGERS INSP



Task Card NO:

572053-01-3-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

Mechanic/s				HRS			
Insp.	INSP/II			HRS			

TASK CLOSE UP

Job Description

B. REMOVE THE HOOK-COVER (RIB 2 SURGE DOORS) 98D57004013000 FROM THE FORWARD SURGE DOORS AND 98D57004014000 FROM THE AFT SURGE DOORS, CLOSE THE RIB2 SURGE DOORS 540AZ AND 540BZ.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/FT			HRS			
Insp.	INSP/II			HRS			

TASK CLOSE UP

Job Description

C. INSTALL THE FUEL ACCESS PANELS 540AB, 540BB AND 540CB (REF. AMM TASK 57-27-11-400-001-A), USING TSV 11-3101.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/FT			HRS			
Insp.	INSP/II			HRS			

TASK CLOSE UP

Job Description

D. PERFORM JOB CLOSE UP AS PER AMM TASK 57-20-00-200-026-A AND REMOVE THE ZERO LOCKING TOOL 98D27803500001 ON THE FLAP SLAT CTL LEVER.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/FT			HRS			
Insp.				HRS			

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____



MET.25445926

Task Card Title:

L/H WING BOTOM SKIN STRINGERS INSP

Task Card NO:

572053-01-3-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.25395708		Task Card Title: R/H WING BOTOM SKIN STRINGERS INSP					
Task Card NO: 572053-01-3-002		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: II,INSP,ACFT_TECH,FT		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 08			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 440	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: DET		Special Code: INSP		MSG Code: ALI		Request: EUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRID OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 640							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
ALI		572053-01-3					
AMM		57-20-00-200-026-A					
SVA		TSV 11-3099 A318 A320 A321 AIRCRAFT FUEL TANK OPEN UP .pdf					
SVA		TSV 11-3101 A318 A320 A321 AIRCRAFT FUEL TANK CLOSE UP AND LEAK CHECK.pdf					
ACCESS PANELS:							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
08BAA9		NON AQUEOUS CLEANER - GENERAL				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
98D27803500001		LOCK				1.0	
98D57004013000		HOOK COVER (RIB 2 SURGE DOORS)				1.0	
98D57004014000		HOOK VOVER (RIB 2 SURGE DOORS)				1.0	
TASK PREPARATION							
Job Description							
A. PERFORM JOB SET UP AS PER AMM TASK 57-20-00-200-026-A AND INSTALL THE ZERO LOCKING TOOL 98D27803500001 ON THE FLAP SLAT CTL LEVER.							
STEP COMPLETION SIGN OFF:							
Qualification / Skill		Number of employees		Duration		Number./Signature	
Date							
Day Month Year							
Mechanic/s		ACFT_TECH/FT		HRS			
Insp.				HRS			
TASK PREPARATION							
Job Description							
B. REMOVE THE FUEL ACCESS PANELS 640AB, 640BB AND 640CB (REF. AMM TASK 57-27-11-000-001-A AND							



Task Card Title:

R/H WING BOTOM SKIN STRINGERS INSP



Task Card NO:

572053-01-3-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

28-10-00-910-002-A), USING TSV 11-3099.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	ACFT_TECH/FT			HRS				
Insp.				HRS				

TASK PREPARATION

Job Description

C. OPEN THE RIB2 SURGE DOORS 640AZ, 640BZ AND INSTALL THE HOOK-COVER (RIB 2 SURGE DOORS) (98D57004013000 ON THE FORWARD SURGE DOORS AND 98D57004014000 ON THE AFT SURGE DOORS).

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	ACFT_TECH/FT			HRS				
Insp.				HRS				

TASK PREPARATION

Job Description

D. USE A CLEAN LINT FREE COTTON, MOIST WITH NON AQUEOUS CLEANER, TO CLEAN THE BOTTOM SKIN STRINGERS BETWEEN RIB1 AND RIB8. THIS INCLUDES THE DRAIN HOLES AND THE BUTTSTRAP AT STRINGERS 8 AND 11.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	ACFT_TECH/FT			HRS				
Insp.				HRS				

TASK INSTRUCTIONS

Job Description

A. PERFORM A DETAILED INSPECTION OF R/H OUTER WING, BOTTOM SKIN STRINGERS, BETWEEN RIB1 AND RIB8, INCLUDING DRAIN HOLES IN STRINGERS AND BUTT STRAP AT STRINGER 8 AND STRINGER 11, EXCLUDING THE AREA INSIDE THE DRY BAY AS PER AMM TASK 57-20-00-200-026-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	II/INSP			HRS				

TASK CLOSE UP

Job Description

A. OT TO CLOSE THE RIB2 SURGE DOORS AND TO INSTALL THE FUEL ACCESS PANELS.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year



Task Card Title:

R/H WING BOTOM SKIN STRINGERS INSP



Task Card NO:

572053-01-3-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

Mechanic/s				HRS			
Insp.	INSP/II			HRS			

TASK CLOSE UP

Job Description

B. REMOVE THE HOOK-COVER (RIB 2 SURGE DOORS) 98D57004013000 FROM THE FORWARD SURGE DOORS AND 98D57004014000 FROM THE AFT SURGE DOORS, CLOSE THE RIB2 SURGE DOORS 640AZ AND 640BZ.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/FT		HRS				
Insp.	II/INSP		HRS				

TASK CLOSE UP

Job Description

C. INSTALL THE FUEL ACCESS PANELS 640AB, 640BB AND 640CB (REF. AMM TASK 57-27-11-400-001-A), USING TSV 11-3101.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/FT		HRS				
Insp.	INSP/II		HRS				

TASK CLOSE UP

Job Description

D. PERFORM JOB CLOSE UP AS PER AMM TASK 57-20-00-200-026-A AND REMOVE THE ZERO LOCKING TOOL 98D27803500001 ON THE FLAP SLAT CTL LEVER.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/FT		HRS				
Insp.			HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____



MET.25395708

Task Card Title:

R/H WING BOTOM SKIN STRINGERS INSP

Task Card NO:

572053-01-3-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.32722066		Task Card Title: LH WING REAR SPAR AFT FACE INSP						
Task Card NO: 572111-01-3-001		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP				
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,AF,ACFT_TECH		PROD Final Acceptance:		
Project No: 01BASPC72608		Related Task Card:		A/C Area: 07				
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 441		
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒								
Type Code: DET		Special Code: INSP		MSG Code: MRB, ALI		Request: Phase: JOB-SETUP,CLEAN-UP,INSPECTION,JOB-CLOSURE EUP		
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.								
Zones: 574,575								
DOCUMENT REFERENCES:								
Doc Typ		Reference						
ALI		572111-01-3						
AMM		57-21-00-200-002-A						
AMM		572100-200-002						
MRB		572111-01-1						
ACCESS PANELS:								
573CB, 573EB, 573FB, 575AB								
MATERIAL REQUIREMENTS:								
Part Number		Description				Qty.		
AMS3819		CLEAN LINT-FREE CLOTH				1.0		
LOTOXANE HD		SOLVENT				1.0		
TOOLING REQUIREMENTS:								
Part Number		Description				Qty.		
98D27604000000		COLLAR-SAFETY, SPOILER (7616 99 90				1.0		
98D27803000000		LOCKING TOOL-FLAP SLAT LEVER, IN (HM				1.0		
TASK PREPARATION								
Job Description								
A. PREPARE THE AIRCRAFT FOR INSPECTION ACCOMPLISHMENT AS PER AMM TASK 57-21-00-200-002-A.								
STEP COMPLETION SIGN OFF:								
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS					
Insp.			HRS					
TASK PREPARATION								
Job Description								



Task Card Title:

LH WING REAR SPAR AFT FACE INSP

Task Card NO:

572111-01-3-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

B. CLEAN THE INSPECTED AREA AS REQUIRED AS PER AMM TASK 57-21-00-200-002-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

TASK INSTRUCTIONS**Job Description**

A. PERFORM A DETAILED VISUAL INSPECTION OF L/H OUTER WING, REAR SPAR AFT FACE, FROM RIB 8 TO RIB 11 AS PER A



Ensure to fill the attached TSV# 92-634 along with this task.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	INSP/II		HRS				

CLOSE UP**Job Description**

A. PERFORM JOB CLOSE-UP AS PER AMM TASK 57-21-00-200-002-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____



Task Card Title:

LH WING REAR SPAR AFT FACE INSP

Task Card NO:

572111-01-3-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following according (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.32722064		Task Card Title: RH WING REAR SPAR AFT FACE INSP						
Task Card NO: 572111-01-3-002		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP				
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,AF,ACFT_TECH		PROD Final Acceptance:		
Project No: 01BASPC72608		Related Task Card:		A/C Area: 08				
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 442		
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒								
Type Code: DET		Special Code: INSP		MSG Code: MRB, ALI		Request: JOB-SETUP,CLEAN-UP,INSPECTION,JOB-CLOSURE EUP		
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.								
Zones: 674,675								
DOCUMENT REFERENCES:								
Doc Typ		Reference						
ALI		572111-01-3						
AMM		57-21-00-200-002-A						
AMM		572100-200-002						
MRB		572111-01-1						
ACCESS PANELS:								
673CB, 673EB, 673FB, 675AB								
MATERIAL REQUIREMENTS:								
Part Number		Description				Qty.		
AMS3819		CLEAN LINT-FREE CLOTH				1.0		
LOTOXANE HD		SOLVENT				1.0		
TOOLING REQUIREMENTS:								
Part Number		Description				Qty.		
98D27604000000		COLLAR-SAFETY, SPOILER (7616 99 90				1.0		
98D27803000000		LOCKING TOOL-FLAP SLAT LEVER, IN (HM				1.0		
TASK PREPARATION								
Job Description								
A. PREPARE THE AIRCRAFT FOR INSPECTION ACCOMPLISHMENT AS PER AMM TASK 57-21-00-200-002-A.								
STEP COMPLETION SIGN OFF:								
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS					
Insp.			HRS					
TASK PREPARATION								
Job Description								



Task Card Title:

RH WING REAR SPAR AFT FACE INSP

Task Card NO:

572111-01-3-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

B. CLEAN THE INSPECTED AREA AS REQUIRED AS PER AMM TASK 57-21-00-200-002-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS				
Insp.				HRS				

TASK INSTRUCTIONS**Job Description**

A. PERFORM A DETAILED VISUAL INSPECTION OF R/H OUTER WING, REAR SPAR AFT FACE, FROM RIB 8 TO RIB 11 AS PER A



Ensure to fill the attached TSV# 92-634 along with this task.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	INSP/II			HRS				

CLOSE UP**Job Description**

A. PERFORM JOB CLOSE-UP AS PER AMM TASK 57-21-00-200-002-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS				
Insp.				HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____



MET.32722064

Task Card Title:

RH WING REAR SPAR AFT FACE INSP

Task Card NO:

572111-01-3-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following according (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.25383063		Task Card Title: L-OUTER WING REAR SPAR FWD FACE INSP										
Task Card NO: 572115-01-3-001		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP								
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,RIL,ACFT_TECH,FT		PROD Final Acceptance:						
Project No: 01BASPC72608		Related Task Card:		A/C Area: 07								
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 443						
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒												
Type Code: DET		Special Code: INSP		MSG Code: ALI		Request: JOB-SETUP,CLEAN-UP,INSPECTION,JOB-CLOSEUP,JOB-CLOSEUP						
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.												
Zones: 540,550,560												
DOCUMENT REFERENCES:												
Doc Typ		Reference										
ALI		572115-01-3										
AMM		57-21-00-200-011-A										
AMM		572100-200-011										
SVA		TSV 11-3099 A318 A320 A321 AIRCRAFT FUEL TANK OPEN UP .pdf										
SVA		TSV 11-3101 A318 A320 A321 AIRCRAFT FUEL TANK CLOSE UP AND LEAK CHECK.pdf										
ACCESS PANELS:												
MATERIAL REQUIREMENTS:												
Part Number		Description				Qty.						
LOTOXANE		NON-AQUEOUS CLEANER				1.0						
TOOLING REQUIREMENTS:												
Part Number		Description				Qty.						
98D27803500001		LOCK				1.0						
PREPARATION												
Job Description												
A. PERFORM JOB SET UP AS PER AMM TASK 57-21-00-200-011-A, REMOVE THE FUEL ACCESS PANELS 540FB; 540GB; 540HB; 540JB; 540KB; 540LB; 540MB; 540NB; 540PB; 540QB; 540RB; 550AB, 550BB; 550CB; 550DB AND 560AB USING TSV 11-3099.												
STEP COMPLETION SIGN OFF:												
		Qualification / Skill		Number of employees		Duration		Number./Signature		Date		
Mechanic/s		ACFT_TECH/FT				HRS						



Task Card Title:

L-OUTER WING REAR SPAR FWD FACE INSP

Task Card NO:

572115-01-3-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

Insp.

HRS

PREPARATION**Job Description**

B. CLEAN THE INSPECTION AREA WITH NON AQUEOUS CLEANER AND A LINT FREE COTTON CLOTH.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/FT		HRS				
Insp.			HRS				

TASK INSTRUCTION**Job Description**

A. PERFORM A DETAILED VISUAL INSPECTION OF L/H OUTER WING, REAR SPAR FORWARD FACE, BETWEEN RIB11 AND RIB27, INCLUDING JOINT AT RIB22 AND TOP AND BOTTOM FLANGES AS PER AMM TASK 57-21-00-200-011-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	INSP/II		HRS				

CLOSE UP**Job Description**

A. INSTALL THE ACCESS PANELS 540FB; 540GB; 540HB; 540JB; 540KB; 540LB; 540MB; 540NB; 540PB; 540QB; 540RB; 550AB, 550BB; 550CB; 550DB AND 560AB (REF. AMM TASKS 57-27-11-400-001-A, 57-27-11-400-002-A, 28-12-45-400-002-A, 28-12-46-400-001-A OR 28-12-47-400-001-A), USING TSV 11-3101.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/FT		HRS				
Insp.	INSP/RII		HRS				

CLOSE UP**Job Description**

B. PERFORM JOB CLOSE UP AS PER AMM TASK 57-21-00-200-011-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/FT		HRS				



Task Card Title:

L-OUTER WING REAR SPAR FWD FACE INSP

Task Card NO:

572115-01-3-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

Insp.

HRS

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
Remark's: _____

**Task Completion Close Up And
System Update**

Station

Date

Signature

 MET.25383680		Task Card Title: R-OUTER WING REAR SPAR FWD FACE INSP					
Task Card NO: 572115-01-3-002		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: II,INSP,RII,ACFT_TECH,FT		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 08			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 444	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: DET		Special Code: INSP		MSG Code: ALI		Request: JOB-SETUP,CLEAN-UP,INSPECTION,JOB-CLOSEUP,JOB-CLOSEUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 640,650,660							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
ALI		572115-01-3					
AMM		57-21-00-200-011-A					
AMM		572100-200-011					
SVA		TSV 11-3099 A318 A320 A321 AIRCRAFT FUEL TANK OPEN UP .pdf					
SVA		TSV 11-3101 A318 A320 A321 AIRCRAFT FUEL TANK CLOSE UP AND LEAK CHECK.pdf					
ACCESS PANELS:							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
LOTOXANE		NON-AQUEOUS CLEANER				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
98D27803500001		LOCK				1.0	
PREPARATION							
Job Description							
A. PERFORM JOB SET UP AS PER AMM TASK 57-21-00-200-011-A, REMOVE THE FUEL ACCESS PANELS 640FB; 640GB; 640HB; 640JB; 640KB; 640LB; 640MB; 640NB; 640PB; 640QB; 640RB; 650AB, 650BB; 650CB; 650DB AND 660AB USING TSV 11-3099.							
STEP COMPLETION SIGN OFF:							
Qualification / Skill		Number of employees		Duration		Number./Signature	
Date							
Day Month Year							
Mechanic/s		ACFT_TECH/FT		HRS			



Task Card Title:

R-OUTER WING REAR SPAR FWD FACE INSP

Task Card NO:

572115-01-3-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

Insp.

HRS

PREPARATION**Job Description**

B. CLEAN THE INSPECTION AREA WITH NON AQUEOUS CLEANER AND A LINT FREE COTTON CLOTH.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/FT		HRS				
Insp.			HRS				

TASK INSTRUCTION**Job Description**

A. PERFORM A DETAILED VISUAL INSPECTION OF R/H OUTER WING, REAR SPAR FORWARD FACE, BETWEEN RIB11 AND RIB27, INCLUDING JOINT AT RIB22 AND TOP AND BOTTOM FLANGES AS PER AMM TASK 57-21-00-200-011-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	II/INSP		HRS				

CLOSE UP**Job Description**

A. INSTALL THE ACCESS PANELS 640FB; 640GB; 640HB; 640JB; 640KB; 640LB; 640MB; 640NB; 640PB; 640QB; 640RB; 650AB, 650BB; 650CB; 650DB AND 660AB (REF. AMM TASKS 57-27-11-400-001-A, 57-27-11-400-002-A, 28-12-45-400-002-A, 28-12-46-400-001-A OR 28-12-47-400-001-A), USING TSV 11-3101.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/FT		HRS				
Insp.	INSP/RII		HRS				

CLOSE UP**Job Description**

B. PERFORM JOB CLOSE UP AS PER AMM TASK 57-21-00-200-011-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/FT		HRS				



Task Card Title:

R-OUTER WING REAR SPAR FWD FACE INSP

Task Card NO:

572115-01-3-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

Insp.

HRS

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
Remark's: _____

**Task Completion Close Up And
System Update**

Station

Date

Signature

 MET.19492905		Task Card Title: L/W BOTOM SKIN JOINTS RIB 11-13 INSP					
Task Card NO: 572150-01-4-001		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,AF,ACFT_TECH		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area:		Phase:	
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 445	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: DET		Special Code: INSP		MSG Code: ALI		Request: JOB-SETUP,CLEAN-UP,INSPECTION,JOB-CLOSURE	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRID OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 500							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
ALI		572150-01-4					
AMM		57-21-00-200-023-A					
AMM		572100-200-023					
ACCESS PANELS:							
532CB, 532EB							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
08BAA9		NON AQUEOUS CLEANER - GENERAL				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
98D27803500001		LOCK				1.0	
TASK PREPARATION							
Job Description							
A. PERFORM JOB SET UP AND INSTALL THE TOOL-ZERO LOCKING, FLAP SLAT CTL LEVER (98D27803500001) ON THE FLAP/SLAT CONTROL LEVER AS PER AMM TASK 57-21-00-200-023-A.							
STEP COMPLETION SIGN OFF:							
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date	
				HRS		Day	Month
Mechanic/s	AF/ACFT_TECH			HRS			
Insp.				HRS			
TASK PREPARATION							
Job Description							
B. USE A CLEAN LINT FREE COTTON, MOIST WITH NON AQUEOUS CLEANER TO CLEAN THE APPLICABLE AREA FOR INSPECTION.							



Task Card Title:

L/W BOTOM SKIN JOINTS RIB 11-13 INSP



Task Card NO:

572150-01-4-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

TASK INSTRUCTIONS

Job Description

A. PERFORM A DETAILED VISUAL INSPECTION OF THE LEFT OUTER WING, BOTTOM-SKIN LOWER SURFACE, SPANWISE SKIN JOINTS AT STRINGER 8 AND STRINGER 11, BETWEEN RIB 11 AND RIB 13 IN AREAS COVERED BY FLAP TRACK 3 FAIRING AS PER AMM TASK 57-21-00-200-023-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	INSP/II		HRS				

TASK CLOSE UP

Job Description

A. PERFORM JOB CLOSE UP AND REMOVE THE TOOL-ZERO LOCKING, FLAP SLAT CTL LEVER AS PER AMM TASK 57-21-00-200-023-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____



MET.19492905

Task Card Title:

L/W BOTOM SKIN JOINTS RIB 11-13 INSP

Task Card NO:

572150-01-4-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following according (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.19492932		Task Card Title: R/W BOTOM SKIN JOINTS RIB 11-13 INSP					
Task Card NO: 572150-01-4-002		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,AF,ACFT_TECH		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area:			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 446	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: DET		Special Code: INSP		MSG Code: ALI		Request: JOB-SETUP,CLEAN-UP,INSPECTION,JOB-CLOSURE Phase: EUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRID OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 600							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
ALI		572150-01-4					
AMM		57-21-00-200-023-A					
AMM		572100-200-023					
ACCESS PANELS:							
632CB, 632EB							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
08BAA9		NON AQUEOUS CLEANER - GENERAL				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
98D27803500001		LOCK				1.0	
TASK PREPARATION							
Job Description							
A. PERFORM JOB SET UP AND INSTALL THE TOOL-ZERO LOCKING, FLAP SLAT CTL LEVER (98D27803500001) ON THE FLAP/SLAT CONTROL LEVER AS PER AMM TASK 57-21-00-200-023-A.							
STEP COMPLETION SIGN OFF:							
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date	
				HRS		Day	Month
Mechanic/s	AF/ACFT_TECH			HRS			
Insp.				HRS			
TASK PREPARATION							
Job Description							
B. USE A CLEAN LINT FREE COTTON, MOIST WITH NON AQUEOUS CLEANER TO CLEAN THE APPLICABLE AREA FOR INSPECTION.							

 MET.19492932	Task Card Title: R/W BOTOM SKIN JOINTS RIB 11-13 INSP						
Task Card NO: 572150-01-4-002		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			

STEP COMPLETION SIGN OFF:							
Qualification / Skill	Number of employees	Duration	Number./Signature	Date			
				Day	Month	Year	
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

TASK INSTRUCTIONS
Job Description A. PERFORM A DETAILED VISUAL INSPECTION OF THE RIGHT OUTER WING, BOTTOM-SKIN LOWER SURFACE, SPANWISE SKIN JOINTS AT STRINGER 8 AND STRINGER 11, BETWEEN RIB 11 AND RIB 13 IN AREAS COVERED BY FLAP TRACK 3 FAIRING AS PER AMM TASK 57-21-00-200-023-A.

STEP COMPLETION SIGN OFF:							
Qualification / Skill	Number of employees	Duration	Number./Signature	Date			
				Day	Month	Year	
Mechanic/s			HRS				
Insp.	INSP/II		HRS				

TASK CLOSE UP
Job Description A. PERFORM JOB CLOSE UP AND REMOVE THE TOOL-ZERO LOCKING, FLAP SLAT CTL LEVER AS PER AMM TASK 57-21-00-200-023-A.

STEP COMPLETION SIGN OFF:							
Qualification / Skill	Number of employees	Duration	Number./Signature	Date			
				Day	Month	Year	
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [☐] Yes [☐] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____



MET.19492932

Task Card Title:

R/W BOTOM SKIN JOINTS RIB 11-13 INSP

Task Card NO:

572150-01-4-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.28342348		Task Card Title: OUTER WING BOTTOM SKIN RUNOUT					
Task Card NO: 572157-01-8		Work Package: ASP/H-26 C7-CHK			A/C Registration: HZ-ASP		
A/C Type: 321		Single Running Taskcard		Main Skill: STR,IL,INSP,NDT_INSP,ACFT_TECH		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area:			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 447	
ENCLOSURE: ☐ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: SDI		Special Code:		MSG Code: ALI		Request: INSPECTION, INSPECTION, JOB-CLOSEUP, JOB-CLOSEUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 540,640							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
AMM		57-21-00-200-027-A					
AMTOSS		572100-200-027					
ACCESS PANELS:							
540PB, 540QB, 540RB, 640PB, 640QB, 640RB							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
14SBA1		TEXTILE - LINT FREE COTTON AMS3819				1.0	
08BAA9		NON AQUEOUS CLEANER - GENERAL				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
No tools assigned to this Task Item							
TASK PREPARATION							
Job Description							
A. PERFORM JOB SETUP FOR A SPECIAL DETAILED INSPECTION OF OUTER WING, BOTTOM SKIN, RUNOUT OF BUTTSTRAP AT STRINGER 8, BETWEEN RIB 20 AND RIB 21, ADJACENT TO FRONT SPAR AND RUNOUT OF BUTTSTRAP, AT STRINGER 11, ADJACENT TO RIB 21 AT REAR SPAR. AS PER AMM TASK 57-21-00-200-027-A.							
STEP COMPLETION SIGN OFF:							
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date	
				HRS		Day	Month
Mechanic/s	STR/ACFT_TECH			HRS			
Insp.				HRS			
TASK PREPARATION							
Job Description							
B. CLEAN THE INSPECTION AREA AS REQUIRED AS PER AMM 57-21-00-200-027-A.							



Task Card Title:

OUTER WING BOTTOM SKIN RUNOUT



Task Card NO:

572157-01-8

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

NOTE: IF NECESSARY, REMOVE THE SEALANT BASED ON AIRBUS MESSAGEAS.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	STR/ACFT_TECH			HRS				
Insp.				HRS				

TASK INSTRUCTIONS

Job Description

C. PERFORM A SPECIAL DETAILED INSPECTION OF OUTER WING, BOTTOM SKIN, RUNOUT OF BUTTSTRAP AT STRINGER 8, BETWEEN RIB 20 AND RIB 21, ADJACENT TO FRONT SPAR AND RUNOUT OF BUTTSTRAP, AT STRINGER 11, ADJACENT TO RIB 21 AT REAR SPAR AS PER AMM TASK 57-21-00-200-027-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	II/NDT_INSP			HRS				

TASK CLOSE UP

Job Description

D. OK TO INSTALL THE OVERPRESSURE PROTECTOR OUTLET (REF. AMM TASK 57-21-00-200-027-A).

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	II/INSP			HRS				

TASK CLOSE UP

Job Description

E. INSTALL THE OVERPRESSURE PROTECTOR OUTLET (REF. AMM TASK 57-21-00-200-027-A).

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	STR/ACFT_TECH			HRS				
Insp.	INSP/II			HRS				

TASK CLOSE UP

Job Description

F. PERFORM CLOSE-UP AND RETURN THE AIRCRAFT BACK TO NORMAL CONFIGURATION AS PER AMM TASK 57-21-00-200-027-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year



MET.28342348

Task Card Title:

OUTER WING BOTTOM SKIN RUNOUT



Task Card NO:

572157-01-8

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

Mechanic/s	STR/ACFT_TECH			HRS				
Insp.				HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

_____, _____, _____, _____, _____, _____, _____, _____, _____, _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 2 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 3 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 4 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 5 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

Task Completion Close Up And
System Update

Station

Date

Signature

 MET.25444761		Task Card Title: L/H WING BOTOM SKIN/REAR SPAR INSP					
Task Card NO: 575159-01-2-001		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,AF,ACFT_TECH		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 07			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 448	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☐							
Type Code: DET		Special Code: INSP		MSG Code: ALI		Request: JOB-SETUP,CLEAN-UP,INSPECTION,JOB-CLOSURE EUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRID OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 500							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
AMM		57-51-00-200-007-A					
AMM		575100-200-007					
ACCESS PANELS:							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
08BAA9		NON AQUEOUS CLEANER - GENERAL				1.0	
LOTOXANE		NON-AQUEOUS CLEANER				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
98D27803500001		LOCK				1.0	
TASK PREPARATION							
Job Description							
A. PERFORM JOB SET UP AND INSTALL THE ZERO LOCKING TOOL 98D27803500001, ON FLAP SLAT CTL LEVER AS PER AMM TASK 57-51-00-200-007-A.							
STEP COMPLETION SIGN OFF:							
Qualification / Skill		Number of employees		Duration		Number./Signature	
Date							
Day		Month		Year			
Mechanic/s		AF/ACFT_TECH		HRS			
Insp.				HRS			
TASK PREPARATION							
Job Description							
B. CLEAN THE CURVED EDGE OF THE WING BOTTOM-SKIN LOWER-SURFACE AND THE AFT OF THE REAR SPAR, IMMEDIATELY INBOARD OF THE MLG SUPPORT RIB 5 AS REQUIRED.							



Task Card Title:

L/H WING BOTOM SKIN/REAR SPAR INSP



Task Card NO:

575159-01-2-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

TASK INSTRUCTIONS

Job Description

A. PERFORM A DETAILED VISUAL INSPECTION OF L/H OUTER WING, BOTTOM SKIN, LOWER-SURFACE CURVED-SKIN EDGE, AFT OF THE REAR SPAR JUST INBOARD OF THE MLG SUPPORT RIB 5 AS PER AMM TASK 57-51-00-200-007-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	INSP/II		HRS				

TASK CLOSE UP

Job Description

A. PERFORM JOB CLOSE UP AND REMOVE THE ZERO LOCKING TOOL 98D27803500001.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____



MET.25444761

Task Card Title:

L/H WING BOTOM SKIN/REAR SPAR INSP



Task Card NO:

575159-01-2-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station

Date

Signature

 MET.25410465		Task Card Title: R/H WING BOTOM SKIN/REAR SPAR INSP					
Task Card NO: 575159-01-2-002		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,AF,ACFT_TECH		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 08			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 449	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☐							
Type Code: DET		Special Code: INSP		MSG Code: ALI		Request: EUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRID OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 600							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
AMM		57-51-00-200-007-A					
AMM		575100-200-007					
ACCESS PANELS:							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
08BAA9		NON AQUEOUS CLEANER - GENERAL				1.0	
LOTOXANE		NON-AQUEOUS CLEANER				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
98D27803500001		LOCK				1.0	
TASK PREPARATION							
Job Description							
A. PERFORM JOB SET UP AND INSTALL THE ZERO LOCKING TOOL 98D27803500001, ON FLAP SLAT CTL LEVER AS PER AMM TASK 57-51-00-200-007-A.							
STEP COMPLETION SIGN OFF:							
Qualification / Skill		Number of employees		Duration		Number./Signature	
Date		Day		Month		Year	
Mechanic/s		AF/ACFT_TECH		HRS			
Insp.				HRS			
TASK PREPARATION							
Job Description							
B. CLEAN THE CURVED EDGE OF THE WING BOTTOM-SKIN LOWER-SURFACE AND THE AFT OF THE REAR SPAR, IMMEDIATELY INBOARD OF THE MLG SUPPORT RIB 5 AS REQUIRED.							



Task Card Title:

R/H WING BOTOM SKIN/REAR SPAR INSP

Task Card NO:

575159-01-2-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP**STEP COMPLETION SIGN OFF:**

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

TASK INSTRUCTIONS**Job Description**

A. PERFORM A DETAILED VISUAL INSPECTION OF R/H OUTER WING, BOTTOM SKIN, LOWER-SURFACE CURVED-SKIN EDGE, AFT OF THE REAR SPAR JUST INBOARD OF THE MLG SUPPORT RIB 5 AS PER AMM TASK 57-51-00-200-007-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	INSP/II		HRS				

TASK CLOSE UP**Job Description**

A. PERFORM JOB CLOSE UP AND REMOVE THE ZERO LOCKING TOOL 98D27803500001.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____



MET.25410465

Task Card Title:

R/H WING BOTOM SKIN/REAR SPAR INSP

Task Card NO:

575159-01-2-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

Copyright of Saudia Technic - Regeneration is not allowed without prior approval by Saudia Technic.



Task Card Title:

LH T/E BOTTOM SKN REAR SPAR NDT INSP

Task Card NO:

575160-01-3-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP**STEP COMPLETION SIGN OFF:**

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS			
Insp.				HRS			

INSPECTION**Job Description**

C. PERFORM A SPECIAL DETAILED INSPECTION (X-RAY AND HFEC) OF L/H OUTER WING, TRAILING EDGE BOTTOM SKIN AFT OF REAR SPAR, ABOVE MLG REINFORCING (REF. NTM 575160) AS PER AMM TASK 57-51-00-200-008-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s				HRS			
Insp.	II/NDT_INSP			HRS			

OK TO INSTALL**Job Description**

D. OK TO INSTALL THE SECONDARY HINGED FAIRING.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s				HRS			
Insp.	INSP/II			HRS			

CLOSE UP**Job Description**

E. INSTALL THE SECONDARY HINGED FAIRING (REF. AMM TASK 32-12-13-400-002-A).

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS			
Insp.	II/INSP			HRS			

RETURN TO NORMAL**Job Description**

F. PERFORM JOB CLOSE UP AND REMOVE THE ZERO LOCKING TOOL 98D27803500001.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS			



MET.25495041

Task Card Title:

LH T/E BOTTOM SKN REAR SPAR NDT INSP

Task Card NO:

575160-01-3-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

Insp.

HRS

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____, _____, _____, _____, _____, _____, _____, _____, _____, _____

_____, _____, _____, _____, _____, _____, _____, _____, _____, _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 2 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 3 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 4 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 5 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

**Task Completion Close Up And
System Update****Station****Date****Signature**

Copyright of Saudia Technic - Regeneration is not allowed without prior approval by Saudia Technic.



MET.25495052

Task Card Title:

RH T/E BOTTOM SKN REAR SPAR NDT INSP

Task Card NO:

575160-01-3-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP**STEP COMPLETION SIGN OFF:**

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

INSPECTION**Job Description**

C. PERFORM A SPECIAL DETAILED INSPECTION (X-RAY AND HFEC) OF R/H OUTER WING, TRAILING EDGE BOTTOM SKIN AFT OF REAR SPAR, ABOVE MLG REINFORCING (REF. NTM 575160) AS PER AMM TASK 57-51-00-200-008-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	II/NDT_INSP		HRS				

OK TO INSTALL**Job Description**

D. OK TO INSTALL THE SECONDARY HINGED FAIRING.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	INSP/II		HRS				

CLOSE UP**Job Description**

E. INSTALL THE SECONDARY HINGED FAIRING (REF. AMM TASK 32-12-13-400-002-A).

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.	INSP/II		HRS				

RETURN TO NORMAL**Job Description**

F. PERFORM JOB CLOSE UP AND REMOVE THE ZERO LOCKING TOOL 98D27803500001.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				



MET.25495052

Task Card Title:

RH T/E BOTTOM SKN REAR SPAR NDT INSP

Task Card NO:

575160-01-3-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

Insp.

HRS

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

_____, _____, _____, _____, _____, _____, _____, _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 2 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 3 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 4 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

- Interruption No. 5 [] Task card [] AMM [] Other specify. _____

Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____

Remark's: _____

**Task Completion Close Up And
System Update****Station****Date****Signature**

 MET.25495053		Task Card Title: L/H WING T/E BOTTOM SKIN INSPECTION					
Task Card NO: 575161-01-2-001		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,AF,ACFT_TECH		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 07			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 452	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: GVI		Special Code: INSP		MSG Code: ALI		Request: JOB-SETUP,INSPECTION, JOB-CLOSEUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 500							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
AMM		57-51-00-210-004-A					
AMM		575100-210-004					
ACCESS PANELS:							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
AMS3819		CLEAN LINT-FREE CLOTH				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
98D27803500001		LOCK				1.0	
PREPARATION							
Job Description							
LEFT OUTER WING TRAILING EDGE BOTTOM SKIN LOWER SURFACE INSPECTION (ALI REQUIREMENT)							
A. PREPARE FOR THE INSPECTION AS PER AMM TASK 57-51-00-210-004-A.							
STEP COMPLETION SIGN OFF:							
		Qualification / Skill		Number of employees		Duration	
Mechanic/s		AF/ACFT_TECH					
Insp.							
INSPECTION							
Job Description							
B. PERFORM GENERAL VISUAL INSPECTION OF OUTER WING, TRAILING EDGE BOTTOM SKIN LOWER							

 MET.25495053	Task Card Title: L/H WING T/E BOTTOM SKIN INSPECTION						
Task Card NO: 575161-01-2-001	Work Package: ASP/H-26 C7-CHK	A/C Registration: HZ-ASP					
SURFACE AFT OF REAR SPAR FROM RIB 9 TO RIB 12 INCLUDING JACKING FITTING HOLE AT RIB 9 AND SIGHTING ROD HOLE AT AT RIB 10 AS PER AMM TASK 57-51-00-210-004-A.							
STEP COMPLETION SIGN OFF:							
	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s				HRS			
Insp.	INSP/II			HRS			
RETURN TO NORMAL							
Job Description							
C. RETURN THE AIRCRAFT BACK TO NORMAL CONFIGURATION AS PER AMM TASK 57-51-00-210-004-A.							
STEP COMPLETION SIGN OFF:							
	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS			
Insp.				HRS			
-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____. Task card finding (Tick Applicable Box) [☐] Yes [☐] No. If yes update the system and list Task card finding WO below Work order No: _____ _____ Note: Make sure to creat the finding Work Order on task card level. Remark's: _____ _____							



MET.25495053

Task Card Title:

L/H WING T/E BOTTOM SKIN INSPECTION**Task Card NO:****575161-01-2-001****Work Package:****ASP/H-26 C7-CHK****A/C Registration:****HZ-ASP**

(1) If Task card interrupted or performed by different personals updates the system and update the following according (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.25495046		Task Card Title: R/H WING T/E BOTTOM SKIN INSPECTION							
Task Card NO: 575161-01-2-002		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP					
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,AF,ACFT_TECH		PROD Final Acceptance:			
Project No: 01BASPC72608		Related Task Card:		A/C Area: 08					
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 453			
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒									
Type Code: GVI		Special Code: INSP		MSG Code: ALI		Request: JOB-SETUP,INSPECTION, JOB-CLOSEUP			
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.									
Zones: 600									
DOCUMENT REFERENCES:									
Doc Typ		Reference							
AMM		57-51-00-210-004-A							
AMM		575100-210-004							
ACCESS PANELS:									
MATERIAL REQUIREMENTS:									
Part Number		Description				Qty.			
AMS3819		CLEAN LINT-FREE CLOTH				1.0			
TOOLING REQUIREMENTS:									
Part Number		Description				Qty.			
98D27803500001		LOCK				1.0			
PREPARATION									
Job Description									
RIGHT OUTER WING TRAILING EDGE BOTTOM SKIN LOWER SURFACE INSPECTION (ALI REQUIREMENT)									
A. PREPARE FOR THE INSPECTION AS PER AMM TASK 57-51-00-210-004-A.									
STEP COMPLETION SIGN OFF:									
		Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
							Day	Month	Year
Mechanic/s		AF/ACFT_TECH		HRS					
Insp.				HRS					
INSPECTION									
Job Description									
B. PERFORM GENERAL VISUAL INSPECTION OF OUTER WING, TRAILING EDGE BOTTOM SKIN LOWER									



MET.25495046

Task Card Title:

R/H WING T/E BOTTOM SKIN INSPECTION

Task Card NO:

575161-01-2-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

SURFACE AFT OF REAR SPAR FROM RIB 9 TO RIB 12 INCLUDING JACKING FITTING HOLE AT RIB 9 AND
SIGHTING ROD HOLE AT AT RIB 10 AS PER AMM TASK 57-51-00-210-004-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	INSP/II			HRS				

RETURN TO NORMAL**Job Description**

C. RETURN THE AIRCRAFT BACK TO NORMAL CONFIGURATION AS PER AMM TASK 57-51-00-210-004-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS				
Insp.				HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____



MET.25495046

Task Card Title:

R/H WING T/E BOTTOM SKIN INSPECTION

Task Card NO:

575161-01-2-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following according (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.25494963		Task Card Title: LH WNG BOTOM SKN FLAP TRK 2 NDT INSP					
Task Card NO: 575164-01-4-001		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,II,NDT_INSP,AF,ACFT_TEC H,NDT		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 07			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 454	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: SDI		Special Code: NDT		MSG Code: ALI		Request: CLEAN-UP,X-RAY / NDT,JOBCLOSEUP,JOBCLOSEUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRID OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 531,574							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
AMM		57-51-00-220-012-A					
AMM		575100-220-012					
ACCESS PANELS:							
531CB, 531EB							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
LOTOXANE		NON-AQUEOUS CLEANER				1.0	
P.S 890A1/2		SEALANT **HAZ MAT ** S/L 9MON MRP#P				1.0	
MIL-PRF-81733 TYPE I		POLYSULFIDE SEALANT BRUSH(TYPE I)				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
98D27803500001		LOCK				1.0	
PREPARATION							
Job Description							
A. PERFORM JOB SET UP AND INSTALL THE ZERO LOCKING TOOL 98D27803500001, ON FLAP SLAT CTL LEVER AS PER AMM TASK 57-51-00-220-012-A.							
STEP COMPLETION SIGN OFF:							
Qualification / Skill		Number of employees		Duration		Number./Signature	
Date							
Day Month Year							
Mechanic/s		AF/ACFT_TECH		HRS			
Insp.				HRS			
PREPARATION							



Task Card Title:

LH WNG BOTOM SKN FLAP TRK 2 NDT INSP



Task Card NO:

575164-01-4-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

Job Description

B. USE A SCRAPER - NON METALLIC TO REMOVE ALL SEALANT FROM THE WING BOTTOM SKIN, AFT OF THE REAR SPAR, AROUND THE FLAP TRACK 2 FORWARD FITTING.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS				
Insp.				HRS				

PREPARATION

Job Description

C. USE A LINT FREE COTTON MOIST WITH 08BAA9 NON AQUEOUS CLEANER TO CLEAN THE WING BOTTOM SKIN, AFT OF THE REAR SPAR, AROUND THE FLAP TRACK 2 FORWARD FITTINGS.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS				
Insp.				HRS				

TASK INSTRUCTION

Job Description

A. PERFORM A SPECIAL DETAILED INSPECTION OF L/H OUTER WING BOTTOM SKIN LOWER SURFACE, AFT OF THE REAR SPAR AROUND THE FLAP TRACK 2 FORWARD FITTINGS (REF. NTM 575164) AS PER AMM TASK 57-51-00-220-012-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.	NDT_INSP/NDT			HRS				

CLOSE UP

Job Description

A. APPLY A LAYER OF 06ABA1 POLYSULFIDE SEALANT-FUEL TANK BRUSHABLE, OR SEALANTS AMSS8802 TO THE SURFACE AROUND THE FLAP TRACK 2 FORWARD FITTINGS.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS				
Insp.	INSP/II			HRS				

 MET.25494963	Task Card Title: LH WNG BOTOM SKN FLAP TRK 2 NDT INSP							
Task Card NO: 575164-01-4-001	Work Package: ASP/H-26 C7-CHK	A/C Registration: HZ-ASP						
CLOSE UP								
Job Description								
B. PERFORM JOB CLOSE UP AS PER AMM TASK 57-51-00-220-012-A AND REMOVE THE ZERO LOCKING TOOL 98D27803500001.								
STEP COMPLETION SIGN OFF:								
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	AF/ACFT_TECH			HRS				
Insp.				HRS				
-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____. Task card finding (Tick Applicable Box) [☐] Yes [☐] No. If yes update the system and list Task card finding WO below Work order No: _____ _____ Note: Make sure to creat the finding Work Order on task card level. Remark's: _____ _____								



Task Card Title:

LH WNG BOTOM SKN FLAP TRK 2 NDT INSP

Task Card NO:

575164-01-4-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.25419465	Task Card Title: RH WNG BOTOM SKN FLAP TRK 2 NDT INSP							
Task Card NO: 575164-01-4-002		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP				
A/C Type: 321		Single Running Taskcard		Main Skill: IL,INSP,NDT_INSP,AF,ACFT_TEC H,AP,NDT		PROD Final Acceptance:		
Project No: 01BASPC72608		Related Task Card:		A/C Area: 08				
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 455		
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒								
Type Code: SDI		Special Code: NDT		MSG Code: ALI		Request: CLEAN-UP,X-RAY / NDT,JOBCLOSEUP,JOBCLOSEUP		
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRID OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.								
Zones: 631,674								
DOCUMENT REFERENCES:								
Doc Typ		Reference						
AMM		57-51-00-220-012-A						
AMM		575100-220-012						
ACCESS PANELS:								
631CB, 631EB								
MATERIAL REQUIREMENTS:								
Part Number		Description				Qty.		
LOTOXANE		NON-AQUEOUS CLEANER				1.0		
P.S 890A1/2		SEALANT **HAZ MAT ** S/L 9MON MRP#P				1.0		
MIL-PRF-81733 TYPE I		POLYSULFIDE SEALANT BRUSH(TYPE I)				1.0		
TOOLING REQUIREMENTS:								
Part Number		Description				Qty.		
98D27803500001		LOCK				1.0		
PREPARATION								
Job Description								
A. PERFORM JOB SET UP AND INSTALL THE ZERO LOCKING TOOL 98D27803500001, ON FLAP SLAT CTL LEVER AS PER AMM TASK 57-51-00-220-012-A.								
STEP COMPLETION SIGN OFF:								
	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	ACFT_TEC/AP			HRS				
Insp.				HRS				
PREPARATION								



MET.25419465

Task Card Title:

RH WNG BOTOM SKN FLAP TRK 2 NDT INSP



Task Card NO:

575164-01-4-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

Job Description

B. USE A SCRAPER - NON METALLIC TO REMOVE ALL SEALANT FROM THE WING BOTTOM SKIN, AFT OF THE REAR SPAR, AROUND THE FLAP TRACK 2 FORWARD FITTING.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/AP		HRS				
Insp.			HRS				

PREPARATION

Job Description

C. USE A LINT FREE COTTON MOIST WITH 08BAA9 NON AQUEOUS CLEANER TO CLEAN THE WING BOTTOM SKIN, AFT OF THE REAR SPAR, AROUND THE FLAP TRACK 2 FORWARD FITTINGS.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

TASK INSTRUCTION

Job Description

A. PERFORM A SPECIAL DETAILED INSPECTION OF R/H OUTER WING BOTTOM SKIN LOWER SURFACE, AFT OF THE REAR SPAR AROUND THE FLAP TRACK 2 FORWARD FITTINGS (REF. NTM 575164) AS PER AMM TASK 57-51-00-220-012-A.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	NDT_INSP/NDT		HRS				

CLOSE UP

Job Description

A. APPLY A LAYER OF 06ABA1 POLYSULFIDE SEALANT-FUEL TANK BRUSHABLE, OR SEALANTS AMSS8802 TO THE SURFACE AROUND THE FLAP TRACK 2 FORWARD FITTINGS.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.	II/INSP		HRS				

CLOSE UP

Job Description



Task Card Title:

RH WNG BOTOM SKN FLAP TRK 2 NDT INSP



Task Card NO:

575164-01-4-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

B. PERFORM JOB CLOSE UP AS PER AMM TASK 57-51-00-220-012-A AND REMOVE THE ZERO LOCKING TOOL
98D27803500001.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	ACFT_TECH/AP		HRS				
Insp.			HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
Remark's: _____

 MET.25419465	Task Card Title: RH WNG BOTOM SKN FLAP TRK 2 NDT INSP			
Task Card NO: 575164-01-4-002	Work Package: ASP/H-26 C7-CHK	A/C Registration: HZ-ASP		
Task Completion Close Up And System Update	Station	Date	Signature	

Copyright of Saudia Technic - Regeneration is not allowed without prior approval by Saudia Technic.

 MET.25383239		Task Card Title: LH WING BOTTOM SKIN & FLAP2 FAIR INSP					
Task Card NO: 575165-01-2-001		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,AF,ACFT_TECH		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 07			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 456	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: DET		Special Code: INSP		MSG Code: ALI		Request: JOB-SETUP,CLEAN-UP,INSPECTION,JOB-CLOSURE EUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 531,574							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
AMM		57-51-00-200-009-A01					
AMM		575100-200-009					
ACCESS PANELS:							
531EB, 535DB							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
AMS3819		CLEAN LINT-FREE CLOTH				1.0	
LOTOXANE		NON-AQUEOUS CLEANER				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
98D27803500001		LOCK				1.0	
PREPARATION							
Job Description							
A. PREPARE OUTER WING BOTTOM SKIN AND FLAP 2 FAIR FOR INSPECTION, AS PER AMM TASK 57-51-00-200-009-A01							
STEP COMPLETION SIGN OFF:							
Qualification / Skill		Number of employees		Duration		Number./Signature	
Date							
Day Month Year							
Mechanic/s		AF/ACFT_TECH		HRS			
Insp.				HRS			
PREPARATION							
Job Description							
B. CLEAN THE INSPECTION AREA PER AMM TASK 57-51-00-200-009-A01							
STEP COMPLETION SIGN OFF:							
Qualification / Skill		Number of employees		Duration		Number./Signature	
Date							
Day Month Year							



Task Card Title:

LH WING BOTTOM SKIN & FLAP2 FAIR INSP

Task Card NO:

575165-01-2-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

Mechanic/s

AF/ACFT_TECH

HRS

Insp.

HRS

TASK INSTRUCTION**Job Description**

A. PERFORM A DETAILED VISUAL INSPECTION OF L/H OUTER WING, BOTTOM SKIN, LOWER SURFACE, AFT OF REAR SPAR UNDER FLAP TRACK 2 FAIRING AND FLAP TAB DRIVE 1A FAIRING AS PER AMM TASK 57-51-00-200-009-A01.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	INSP/II		HRS				

CLOSE UP**Job Description**

A. PERFORM JOB CLOSE UP PER AMM TASK 57-51-00-200-009-A01.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to create the finding Work Order on task card level.

Remark's: _____



Task Card Title:

LH WING BOTTOM SKIN & FLAP2 FAIR INSP

Task Card NO:

575165-01-2-001

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.25383838		Task Card Title: RH WING BOTTOM SKIN & FLAP2 FAIR INSP					
Task Card NO: 575165-01-2-002		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: INSP,IL,AF,ACFT_TECH		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area: 08			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 457	
ENCLOSURE: ☒ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☒							
Type Code: DET		Special Code: INSP		MSG Code: ALI		Request: JOB-SETUP,CLEAN-UP,INSPECTION,JOB-CLOSURE EUP	
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 631,674							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
AMM		57-51-00-200-009-A01					
AMM		575100-200-009					
ACCESS PANELS:							
631EB, 635DB							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
AMS3819		CLEAN LINT-FREE CLOTH				1.0	
LOTOXANE		NON-AQUEOUS CLEANER				1.0	
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
98D27803500001		LOCK				1.0	
PREPARATION							
Job Description							
A. PREPARE OUTER WING BOTTOM SKIN AND FLAP 2 FAIR FOR INSPECTION, AS PER AMM TASK 57-51-00-200-009-A01							
STEP COMPLETION SIGN OFF:							
Qualification / Skill		Number of employees		Duration		Number./Signature	
Date		Day		Month		Year	
Mechanic/s		AF/ACFT_TECH		HRS			
Insp.				HRS			
PREPARATION							
Job Description							
B. CLEAN THE INSPECTION AREA PER AMM TASK 57-51-00-200-009-A01							
STEP COMPLETION SIGN OFF:							
Qualification / Skill		Number of employees		Duration		Number./Signature	
Date		Day		Month		Year	



Task Card Title:

RH WING BOTTOM SKIN & FLAP2 FAIR INSP

Task Card NO:

575165-01-2-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

Mechanic/s

AF/ACFT_TECH

HRS

Insp.

HRS

TASK INSTRUCTION**Job Description**

A. PERFORM A DETAILED VISUAL INSPECTION OF R/H OUTER WING, BOTTOM SKIN, LOWER SURFACE, AFT OF REAR SPAR UNDER FLAP TRACK 2 FAIRING AND FLAP TAB DRIVE 1A FAIRING AS PER AMM TASK 57-51-00-200-009-A01.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s			HRS				
Insp.	INSP/II		HRS				

CLOSE UP**Job Description**

A. PERFORM JOB CLOSE UP PER AMM TASK 57-51-00-200-009-A01.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	AF/ACFT_TECH		HRS				
Insp.			HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to create the finding Work Order on task card level.

Remark's: _____



Task Card Title:

RH WING BOTTOM SKIN & FLAP2 FAIR INSP

Task Card NO:

575165-01-2-002

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following according (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.25383783		Task Card Title: DETAILED INSPECTION OF TRU STRUTS.					
Task Card NO: 783000-C9-1		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP			
A/C Type: 321		Single Running Taskcard		Main Skill: PP,II,INSP,ACFT_TECH		PROD Final Acceptance:	
Project No: 01BASPC72608		Related Task Card:		A/C Area:			
Internal Check:		Check Type:		Work Order NO:		Tally Sequence NO: 458	
ENCLOSURE: ☐ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☐							
Type Code: DET		Special Code: INSP, PP		MSG Code: 8, MRB		Request: 	
Phase:							
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.							
Zones: 400							
DOCUMENT REFERENCES:							
Doc Typ		Reference					
AMM		78-32-00-210-829-B					
AMM		783200-210-829					
ACCESS PANELS:							
MATERIAL REQUIREMENTS:							
Part Number		Description				Qty.	
No parts assigned to this Task Item							
TOOLING REQUIREMENTS:							
Part Number		Description				Qty.	
No tools assigned to this Task Item							
1. JOB SET-UP:							
Job Description							
A. PERFORM A JOB SET UP A DETAILED INSPECTION FOR TRU STRUTS AS PER AMM TASK 783200-210-829-B.							
STEP COMPLETION SIGN OFF:							
		Qualification / Skill	Number of employees	Duration	Number./Signature	Date	
						Day	Month
Mechanic/s		PP/ACFT_TECH		HRS			
Insp.				HRS			
2. INSPECTION:							
Job Description							
A. PERFORM A DETAILED VISUAL INSPECTION FOR TRU STRUTS AS PER AMM TASK 783200-210-829-B.							
STEP COMPLETION SIGN OFF:							
		Qualification / Skill	Number of employees	Duration	Number./Signature	Date	
						Day	Month

 MET.25383783	Task Card Title: DETAILED INSPECTION OF TRU STRUTS.						
Task Card NO: 783000-C9-1		Work Package: ASP/H-26 C7-CHK			A/C Registration: HZ-ASP		
Mechanic/s				HRS			
Insp.	II/INSP			HRS			
3. CLOSE UP:							
Job Description							
A. PERFORM AIRCRAFT CLOSE UP PER AMM TASK 78-32-200-210-829-B.							
STEP COMPLETION SIGN OFF:							
	Qualification / Skill	Number of employees	Duration	Number./Signature	Date		
					Day	Month	Year
Mechanic/s	PP/ACFT_TECH			HRS			
Insp.				HRS			
-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____. Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below Work order No: _____ _____ Note: Make sure to creat the finding Work Order on task card level. Remark's: _____ _____							



Task Card Title:

DETAILED INSPECTION OF TRU STRUTS.

Task Card NO:

783000-C9-1

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following according (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

Copyright of Saudia Technic - Regeneration is not allowed without prior approval by Saudia Technic.



MET.29461955

Task Card Title:

SCRATCH FOUND AT FR56 AND 50MM BELOW STGR 31RH

Task Card NO:

104751

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

- Threshold Inspection (FROM AIRCRAFT FIRST FLIGHT): 1100 FC (FH not relevant)
- Subsequent Inspection Intervals: 1100 FC.
- Inspection Method: GVI.

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.				HRS				

Job Description

GVI THE REPAIRED AREA AS PER SRM 53-41-11-205-143

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	INSP			HRS				
Insp.	INSP			HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

Note: Make sure to creat the finding Work Order on task card level.

Remark's: _____



MET.29461955

Task Card Title:

SCRATCH FOUND AT FR56 AND 50MM BELOW STGR 31RH

Task Card NO:

104751

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following accord (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**

 MET.29466565		Task Card Title: R 53A STGR40-41 RH SCRATCH ON FUS SKIN CGO DOOR SU				
ROUND 321 RH FUSELAGE						
Task Card NO: 104871		Work Package: ASP/H-26 C7-CHK		A/C Registration: HZ-ASP		
A/C Type: 321		Single Running Taskcard		Main Skill: INSP		
Project No: 01BASPC72608		Related Task Card:		A/C Area:		
Internal Check:		Check Type:		Work Order NO:		
				Tally Sequence NO: 580		
ENCLOSURE: ☐ CMR: ☐ CPCP: ☐ ETOPS: ☐ CDCCL: ☐ AD: ☐ ALI: ☐						
Type Code:		Special Code:		MSG Code:		
				Request:		
				Phase:		
I HEREBY CERTIFY THAT ALL WARNINGS AND CAUTIONS HAVE BEEN READ AND THE WORK HAS BEEN CARRIED OUT IN ACCORDING WITH ALL LAID DOWN PROCEDURES, ATTACHED NOTES AND INFORMATION.						
Zones:						
DOCUMENT REFERENCES:						
Doc Typ		Reference				
WO		26129147				
ACCESS PANELS:						
MATERIAL REQUIREMENTS:						
Part Number		Description			Qty.	
No parts assigned to this Task Item						
TOOLING REQUIREMENTS:						
Part Number		Description			Qty.	
No tools assigned to this Task Item						
Job Description						
! WARNING						
This ADHOC is related to CAT B repair and should not be de-assigned or de-initialized						
FR 53A STGR40-41 RH SCRATCH ON FUS SKIN CGO DOOR SURROUND 321-RH FUSELAGE THIS ADL IS REPAIR CATEGORY "B" AND REQUIRE REPEAT INSPECTIONS I.A.W. SRM TASK 53-41-11-205-143 REV.146						
<u>Repeat Inspection Requirements</u>						
• Threshold Inspection (FROM AIRCRAFT FIRST FLIGHT): 1100 FC (FH not relevant) • Subsequent Inspection Intervals: 1100 FC. • Inspection Method: GVI.						



Task Card Title:

R 53A STGR40-41 RH SCRATCH ON FUS SKIN CGO DOOR SU**ROUND 321 RH FUSELAGE**

Task Card NO:

104871

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP**STEP COMPLETION SIGN OFF:**

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s				HRS				
Insp.				HRS				

Job Description

GVI THE REPAIRED AREA AS PER SRM 53-41-11-205-143

STEP COMPLETION SIGN OFF:

	Qualification / Skill	Number of employees	Duration		Number./Signature	Date		
						Day	Month	Year
Mechanic/s	INSP			HRS				
Insp.	INSP			HRS				

-Aircraft Maintenance Manual used: Revision No. _____ Dated. _____.

Task card finding (Tick Applicable Box) [] Yes [] No. If yes update the system and list Task card finding WO below

Work order No: _____

_____, _____, _____, _____, _____, _____, _____, _____, _____, _____

Note: Make sure to create the finding Work Order on task card level.

Remark's: _____

_____, _____, _____, _____, _____, _____, _____, _____, _____, _____



Task Card Title:

R 53A STGR40-41 RH SCRATCH ON FUS SKIN CGO DOOR SU**ROUND 321 RH FUSELAGE**

Task Card NO:

104871

Work Package:

ASP/H-26 C7-CHK

A/C Registration:

HZ-ASP

(1) If Task card interrupted or performed by different personals updates the system and update the following according (Tick Applicable Box)

- Interruption No. 1 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 2 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 3 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 4 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____
- Interruption No. 5 [] Task card [] AMM [] Other specify. _____
 Performed by: _____ Page No. _____ Step From _____ To _____

(2) Record any dimension or torque through the performed steps and sign-off as applicable:

- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____
- Dimension/torque: _____ Mech _____ INSP _____ Page No. _____ Step _____
 Remark's: _____

**Task Completion Close Up And
System Update**

Station**Date****Signature**