






Approach temperature = 20°F HU=120





$$A = \frac{Q}{U \Delta T_{lm}}$$

$$\frac{1}{U} = \sum_i \frac{1}{h_i}$$

