MCUXpresso SDK Release Notes for EVK-MIMX8ULP and EVK9-MIMX8ULP

Rev. 1 — 20 June 2022 Release notes

Document Information

| Information | Content |
|-------------|---|
| Keywords | EVK-MIMX8ULP, EVK9-MIMX8ULP, 8ULP, MIMX8ULP |
| Abstract | This document describes the MCUXpresso SDK release notes for EVKMIMX8ULP and EVK9-MIMX8ULP. |



1 Overview

The MCUXpresso Software Development Kit (SDK) is a collection of software enablement for microcontrollers that includes peripheral drivers, high-level stacks including other middleware packages. In addition to the base enablement, the MCUXpresso SDK is augmented with demo applications, driver example projects, and API documentation to help the customers quickly leverage the support of the MCUXpresso SDK. For details on MCUXpresso SDK, see MCUXpresso-SDK: Software Development Kit for MCUXpresso.

2 MCUXpresso SDK

As part of the MCUXpresso software and tools, MCUXpresso SDK is the evolution of Kinetis SDK v2.10.0, includes support for LPC, DSC, and i.MX System-on-Chip (SoC). The same drivers, APIs, and middleware are still available with support for Kinetis, LPC, DSC, and i.MX silicon. The MCUXpresso SDK adds support for the MCUXpresso IDE, an Eclipse-based toolchain that works with all MCUXpresso SDKs. Easily import your SDK into the new toolchain to access all of the available components, examples, and demos for your target silicon. In addition to the MCUXpresso IDE, support for the MCUXpresso Config Tools allows easy cloning of existing SDK examples and demos, allowing users to leverage the existing software examples provided by the SDK for their own projects.

In order to maintain compatibility with legacy Freescale code, the filenames and source code in MCUXpresso SDK containing the legacy Freescale prefix FSL have been left as is. The FSL prefix has been redefined as the NXP Foundation Software Library.

3 Development tools

The MCUXpresso SDK is compiled and tested with these development tools:

- GCC Arm Embedded, version is 10-2021.10.
- IAR Embedded Workbench for Arm. version is 9.32.1.

4 Supported development systems

This release supports boards and devices listed in table below. The boards and devices in bold were tested in this release.

Table 1. Supported boards and devices

| Development boards | MCU devices |
|--------------------|-----------------|
| EVK-MIMX8ULP | MIMX8UD7DVP10SA |
| EVK9-MIMX8ULP | MIMX8UD5DVK10SA |

5 MCUXpresso SDK release package

The MCUXpresso DSC SDK release package content is aligned with the silicon subfamily it supports. This includes the boards, devices, documentation, and middleware.

5.1 Device support

The device folder contains the whole software enablement available for the specific System-on-Chip (SoC) subfamily. This folder includes clock-specific implementation, device register header files, device register feature header files, and the system configuration source files. Included with the standard SoC support are

MCUXSDKIMX8ULPRN

All information provided in this document is subject to legal disclaimers.

folders containing peripheral drivers, toolchain support, and a standard debug console. The device-specific header files provide a direct access to the microcontroller peripheral registers. The device header file provides an overall SoC memory mapped register definition. The folder also includes the feature header file for each peripheral on the microcontroller. The toolchain folder contains the startup code and linker files for each supported toolchain. The startup code efficiently transfers the code execution to the main() function.

5.1.1 Board support

The boards folder provides the board-specific demo applications, driver examples, and middleware examples.

5.1.2 Demo application and other examples

The demo applications demonstrate the usage of the peripheral drivers to achieve a system level solution. Each demo application contains a readme file that describes the operation of the demo and required setup steps. The driver examples demonstrate the capabilities of the peripheral drivers. Each example implements a common use case to help demonstrate the driver functionality.

5.2 CMSIS DSP Lib

5.2.1 CMSIS DSP Library

The MCUXpresso SDK is shipped with the standard CMSIS development pack, including the prebuilt libraries.

5.3 Operating system

5.3.1 FreeRTOS

The MCUXpresso SDK is integrated with FreeRTOS OS.

5.4 Middleware

5.4.1 Multicore

Multicore Software Development Kit

6 Release contents

Table 2 provides an overview of the MCUXpresso SDK release package contents and locations.

Table 2. MCUXpresso SDK release package contents and locations

| Deliverable | Location |
|--|--|
| Boards | INSTALL_DIR/boards |
| Demo Applications | INSTALL_DIR/boards/ <board_name>/demo_apps</board_name> |
| Driver Examples | INSTALL_DIR/boards/ <board_name>/driver_examples</board_name> |
| Driver, SoC header files, extension header files and feature header files, utilities | INSTALL_DIR/devices/ <device_name></device_name> |
| CMSIS drivers | INSTALL_DIR/devices/ <device_name>/cmsis_drivers</device_name> |
| Peripheral drivers | INSTALL_DIR/devices/ <device_name>/drivers</device_name> |
| Toolchain linker files and startup code | INSTALL_DIR/devices/ <device_name>/<toolchain_name></toolchain_name></device_name> |

MCUXSDKIMX8ULPRN

All information provided in this document is subject to legal disclaimers.

Table 2. MCUXpresso SDK release package contents and locations...continued

| Deliverable | Location |
|---|--|
| Utilities such as debug console | INSTALL_DIR/devices/ <device_name>/utilities</device_name> |
| CMSIS Arm Cortex-M header files, DSP library source | INSTALL_DIR/CMSIS |
| Components and board device drivers | INSTALL_DIR/components |
| Documents | INSTALL_DIR/docs |
| RTOS | INSTALL_DIR/rtos |
| Release Notes, Getting Started Document and other documents | INSTALL_DIR/docs |
| Tools such as shared cmake files | INSTALL_DIR/tools |

7 MISRA compliance

All MCUXpresso SDK drivers comply to MISRA 2012 rules with exceptions in Table 3.

Table 3. MISRA exception rules

| Exception rules | Description |
|-----------------|---|
| Directive 4.4 | Sections of code should not be commented out. |
| Directive 4.5 | Identifiers in the same namespace with overlapping visibility should be typographically unambiguous. |
| Directive 4.6 | Typedefs that indicate size and signedness should be used in place of the basic numerical types. |
| Directive 4.8 | If a pointer to a structure or union is never dereferenced within a translation unit, then the implementation of the object should be hidden. |
| Directive 4.9 | A function should be used in preference to a function-like macro where they are interchangeable. |
| Directive 4.13 | Functions which are designed to provide operations on a resource should be called in an appropriate sequence. |
| Rule 1.2 | Language extensions should not be used. |
| Rule 2.3 | A project should not contain unused type declarations. |
| Rule 2.4 | A project should not contain unused tag declarations. |
| Rule 2.5 | A project should not contain unused macro declarations. |
| Rule 2.6 | A function should not contain unused label declarations. |
| Rule 2.7 | There should be no unused parameters in functions. |
| Rule 4.2 | Trigraphs should not be used. |
| Rule 5.1 | External identifiers shall be distinct. |
| Rule 5.4 | Macro identifiers shall be distinct. |
| Rule 5.9 | Identifiers that define objects or functions with internal linkage should be unique. |
| Rule 8.7 | Functions and objects should not be defined with external linkage if they are referenced in only one translation unit. |

MCUXpresso SDK Release Notes for EVK-MIMX8ULP and EVK9-MIMX8ULP

Table 3. MISRA exception rules...continued

| Table 3. WISKA exception rulescontinued | |
|---|---|
| Exception rules | Description |
| Rule 8.9 | An object should be defined at block scope if its identifier only appears in a single function. |
| Rule 8.11 | When an array with external linkage is declared, its size should be explicitly specified. |
| Rule 8.13 | A pointer should point to a const-qualified type whenever possible. |
| Rule 10.5 | The value of an expression should not be cast to an inappropriate essential type. |
| Rule 11.4 | A conversion should not be performed between a pointer to object and an integer type. |
| Rule 11.5 | A conversion should not be performed from pointer to void into pointer to object. |
| Rule 12.1 | The precedence of operators within expressions should be made explicit. |
| Rule 12.3 | The comma operator should not be used. |
| Rule 12.4 | Evaluation of constant expressions should not lead to unsigned integer wrap-around. |
| Rule 13.3 | A full expression containing an increment (++) or decrement (-) operator should have no other potential side effects other than that caused by the increment or decrement operator. |
| Rule 15.4 | There should be no more than one break or go to statement used to terminate any iteration statement. |
| Rule 17.5 | The function argument corresponding to a parameter declared to have an array type shall have an appropriate number of elements. |
| Rule 17.8 | A function parameter should not be modified. |
| Rule 19.2 | The union keyword should not be used. |
| Rule 20.1 | #include directives should only be preceded by preprocessor directives or comments. |
| Rule 20.10 | The # and ## preprocessor operators should not be used. |
| Rule 21.1 | #define and #undef shall not be used on a reserved identifier or reserved macro name. |
| Rule 21.2 | A reserved identifier or macro name shall not be declared. |
| Rule 21.12 | The exception handling features of <fenv.h> should not be used.</fenv.h> |
| | - I |

8 Known issues

This section lists the known issues, limitations, and/or workarounds.

8.1 Maximum file path length in Windows 7 operating system

The Windows 7 operating system imposes a 260-character maximum length for file paths. When installing the MCUXpresso SDK, place it in a directory close to the root to prevent file paths from exceeding the maximum character length specified by the Windows operating system. The recommended location is the C:\<folder>.

8.2 Fusion DSP may load wrong data from shared SRAM on Silicon A0.1 with specific command sequence

There is issue in the shared SRAM controller prefetch logic for silicon A0.1.

A back-2-back access to the same memory location without any "nop" cycle in between corrupts the prefetch buffer under the following conditions.

First cycle access is a read to address N, immediately followed by the second cycle-partial write (1 byte or halfword (16-bits)) to address N.

The partial write is not updated to prefetch buffer. Subsequent reading from the Shared SRAM address N returns incorrect data.

8.3 Real-Time Domain cannot normally resume from the power-down mode due to EdgeLock secure enclave (S400) failure

There is an issue in EdgeLock secure enclave (S400) during state restoring phase for silicon A0.1. When Real Time Domain (RTD) is about to enter the power-down mode, S400 is promoted to save the current state to the memory. However, once RTD wakes up, S400 encounters an error when trying to restore the state.

This error can cause S400 decide to reset RTD, which means RTD cannot normally resume from the power-down mode.

8.4 Cortex-M33 cannot exit from upower IRQ handler

The Cortex-M33 cannot exit from upower IRQ handler because the upower interrupt occurs before setting the global variable mu_tx_pend in upwr_tx(upower_api.c).

To fix the issue, apply the patch below.

```
diff --git a/MIMX8UD7/drivers/upower/upower api.c b/MIMX8UD7/drivers/upower/
upower api.c
index 464581ad7d..d95e1adaa7 100644
--- a/MIMX8UD7/drivers/upower/upower api.c
+++ b/MIMX8UD7/drivers/upower/upower_api.c
@@ -3115,10 +3115,10 @@ int upwr tx(const uint32 t*
                                                              msg,
        mu tx callb = callback;
        upwr copy2tr(mu, msg, size);
        mu tx pend = 1UL;
        mu \rightarrow TCR.R = 1UL \ll (size - 1UL);
        mu tx pend = 1UL;
       upwr copy2tr(mu, msg, size); /* Will generate upower tx interrupt after
TR is full when with interrupt mode */
        return 0;
 }
```

MCUXSDKIMX8ULPRN

All information provided in this document is subject to legal disclaimers.

8.5 Flexcan_ping_pong_buffer_transfer case loses first 8 bytes data for armgcc flash_debug

To prevent flexcan_ping_pong_buffer_transfer case from losing the first 8 bytes data for armgcc flash_debug, apply the fix below.

8.6 LPSPI b2b examples transfer fail on iar/armgcc flash target

Due to the latency of instruction retrieval (XiP), LPSPI-related flash target examples may fail. The failure happens because the data is not retrieved in time from FIFO on the receiving end.

To prevent the failure, place the fsl_lpspi.c file in TCM to boost the instruction fetch performance.

Apply the patch as below,

```
diff --qit a/MIMX8UD7/qcc/MIMX8UD7xxxxx cm33 flash.ld b/MIMX8UD7/qcc/
MIMX8UD7xxxxx cm33 flash.ld
index 02b76a8ea3..709e1c73d5 100644
--- a/MIMX8UD7/gcc/MIMX8UD7xxxxx cm33 flash.ld
+++ b/MIMX8UD7/gcc/MIMX8UD7xxxxx cm33 flash.ld
@@ -85,18 +85,22 @@ SECTIONS
     * (EXCLUDE FILE (
         /* Exclude flash and frequently executed functions from XIP */
         */fsl_flexspi.c.obj
         */fsl lpspi.c.obj
+
                               /* .text sections (code) */
       .text)
     *(EXCLUDE FILE(
         /* Exclude flash and frequently executed functions from XIP */
         */fsl flexspi.c.obj
         */fsl lpspi.c.obj
                               /* .text* sections (code) */
     ) .text*)
     *(EXCLUDE FILE(
         /* Exclude flash and frequently executed functions from XIP */
         */fsl_flexspi.c.obj
*/fsl_lpspi.c.obj
+
                               /* .rodata sections (constants, strings, etc.) */
     ) .rodata)
     *(EXCLUDE FILE(
         /* Exclude flash and frequently executed functions from XIP */
         */fsl flexspi.c.obj
         */fsl lpspi.c.obj
```

MCUXSDKIMX8ULPRN

All information provided in this document is subject to legal disclaimers.

MCUXpresso SDK Release Notes for EVK-MIMX8ULP and EVK9-MIMX8ULP

9 Change log

Change log of software components included in the package, see MCUXpresso SDK ChangeLog MIMX8ULP.pdf.

10 Revision history

Table 4 below summarizes the revisions to this document.

Table 4. Revision history

| Revision number | Date | Substantive changes |
|-----------------|--------------|------------------------|
| 1 | 20 June 2023 | Initial public release |

11 Legal information

11.1 Definitions

Draft — A draft status on a document indicates that the content is still under internal review and subject to formal approval, which may result in modifications or additions. NXP Semiconductors does not give any representations or warranties as to the accuracy or completeness of information included in a draft version of a document and shall have no liability for the consequences of use of such information.

11.2 Disclaimers

Limited warranty and liability — Information in this document is believed to be accurate and reliable. However, NXP Semiconductors does not give any representations or warranties, expressed or implied, as to the accuracy or completeness of such information and shall have no liability for the consequences of use of such information. NXP Semiconductors takes no responsibility for the content in this document if provided by an information source outside of NXP Semiconductors.

In no event shall NXP Semiconductors be liable for any indirect, incidental, punitive, special or consequential damages (including - without limitation - lost profits, lost savings, business interruption, costs related to the removal or replacement of any products or rework charges) whether or not such damages are based on tort (including negligence), warranty, breach of contract or any other legal theory.

Notwithstanding any damages that customer might incur for any reason whatsoever, NXP Semiconductors' aggregate and cumulative liability towards customer for the products described herein shall be limited in accordance with the Terms and conditions of commercial sale of NXP Semiconductors.

Right to make changes — NXP Semiconductors reserves the right to make changes to information published in this document, including without limitation specifications and product descriptions, at any time and without notice. This document supersedes and replaces all information supplied prior to the publication hereof.

Suitability for use — NXP Semiconductors products are not designed, authorized or warranted to be suitable for use in life support, life-critical or safety-critical systems or equipment, nor in applications where failure or malfunction of an NXP Semiconductors product can reasonably be expected to result in personal injury, death or severe property or environmental damage. NXP Semiconductors and its suppliers accept no liability for inclusion and/or use of NXP Semiconductors products in such equipment or applications and therefore such inclusion and/or use is at the customer's own risk

Applications — Applications that are described herein for any of these products are for illustrative purposes only. NXP Semiconductors makes no representation or warranty that such applications will be suitable for the specified use without further testing or modification.

Customers are responsible for the design and operation of their applications and products using NXP Semiconductors products, and NXP Semiconductors accepts no liability for any assistance with applications or customer product design. It is customer's sole responsibility to determine whether the NXP Semiconductors product is suitable and fit for the customer's applications and products planned, as well as for the planned application and use of customer's third party customer(s). Customers should provide appropriate design and operating safeguards to minimize the risks associated with their applications and products.

NXP Semiconductors does not accept any liability related to any default, damage, costs or problem which is based on any weakness or default in the customer's applications or products, or the application or use by customer's third party customer(s). Customer is responsible for doing all necessary testing for the customer's applications and products using NXP Semiconductors products in order to avoid a default of the applications and the products or of the application or use by customer's third party customer(s). NXP does not accept any liability in this respect.

Terms and conditions of commercial sale — NXP Semiconductors products are sold subject to the general terms and conditions of commercial sale, as published at http://www.nxp.com/profile/terms, unless otherwise agreed in a valid written individual agreement. In case an individual agreement is concluded only the terms and conditions of the respective agreement shall apply. NXP Semiconductors hereby expressly objects to applying the customer's general terms and conditions with regard to the purchase of NXP Semiconductors products by customer.

Export control — This document as well as the item(s) described herein may be subject to export control regulations. Export might require a prior authorization from competent authorities.

Suitability for use in non-automotive qualified products — Unless this data sheet expressly states that this specific NXP Semiconductors product is automotive qualified, the product is not suitable for automotive use. It is neither qualified nor tested in accordance with automotive testing or application requirements. NXP Semiconductors accepts no liability for inclusion and/or use of non-automotive qualified products in automotive equipment or applications.

In the event that customer uses the product for design-in and use in automotive applications to automotive specifications and standards, customer (a) shall use the product without NXP Semiconductors' warranty of the product for such automotive applications, use and specifications, and (b) whenever customer uses the product for automotive applications beyond NXP Semiconductors' specifications such use shall be solely at customer's own risk, and (c) customer fully indemnifies NXP Semiconductors for any liability, damages or failed product claims resulting from customer design and use of the product for automotive applications beyond NXP Semiconductors' standard warranty and NXP Semiconductors' product specifications.

Translations — A non-English (translated) version of a document, including the legal information in that document, is for reference only. The English version shall prevail in case of any discrepancy between the translated and English versions.

Security — Customer understands that all NXP products may be subject to unidentified vulnerabilities or may support established security standards or specifications with known limitations. Customer is responsible for the design and operation of its applications and products throughout their lifecycles to reduce the effect of these vulnerabilities on customer's applications and products. Customer's responsibility also extends to other open and/or proprietary technologies supported by NXP products for use in customer's applications. NXP accepts no liability for any vulnerability. Customer should regularly check security updates from NXP and follow up appropriately. Customer shall select products with security features that best meet rules, regulations, and standards of the intended application and make the ultimate design decisions regarding its products and is solely responsible for compliance with all legal, regulatory, and security related requirements concerning its products, regardless of any information or support that may be provided by NXP.

NXP has a Product Security Incident Response Team (PSIRT) (reachable at PSIRT@nxp.com) that manages the investigation, reporting, and solution release to security vulnerabilities of NXP products.

NXP B.V. - NXP B.V. is not an operating company and it does not distribute or sell products.

11.3 Trademarks

Notice: All referenced brands, product names, service names, and trademarks are the property of their respective owners.

NXP — wordmark and logo are trademarks of NXP B.V.

MCUXSDKIMX8ULPRN

All information provided in this document is subject to legal disclaimers.

MCUXpresso SDK Release Notes for EVK-MIMX8ULP and EVK9-MIMX8ULP

AMBA, Arm, Arm7, Arm7TDMI, Arm9, Arm11, Artisan, big.LITTLE, Cordio, CoreLink, CoreSight, Cortex, DesignStart, DynamIQ, Jazelle, Keil, Mali, Mbed, Mbed Enabled, NEON, POP, RealView, SecurCore, Socrates, Thumb, TrustZone, ULINK, ULINK2, ULINK-ME, ULINK-PLUS, ULINKpro, µVision, Versatile — are trademarks and/or registered trademarks of Arm Limited (or its subsidiaries or affiliates) in the US and/or elsewhere. The related technology may be protected by any or all of patents, copyrights, designs and trade secrets. All rights reserved.

MCUXpresso SDK Release Notes for EVK-MIMX8ULP and EVK9-MIMX8ULP

Contents

| 1 | Overview | 2 |
|-------|--|---|
| 2 | MCUXpresso SDK | 2 |
| 3 | Development tools | 2 |
| 4 | Supported development systems | 2 |
| 5 | MCUXpresso SDK release package | 2 |
| 5.1 | Device support | 2 |
| 5.1.1 | Board support | 3 |
| 5.1.2 | Demo application and other examples | 3 |
| 5.2 | CMSIS DSP Lib | |
| 5.2.1 | CMSIS DSP Library | 3 |
| 5.3 | Operating system | 3 |
| 5.3.1 | FreeRTOS | 3 |
| 5.4 | Middleware | 3 |
| 5.4.1 | Multicore | 3 |
| 6 | Release contents | 3 |
| 7 | MISRA compliance | 4 |
| 8 | Known issues | 5 |
| 8.1 | Maximum file path length in Windows 7 | |
| | operating system | 6 |
| 8.2 | Fusion DSP may load wrong data from | |
| | shared SRAM on Silicon A0.1 with specific | |
| | command sequence | 6 |
| 8.3 | Real-Time Domain cannot normally resume | |
| | from the power-down mode due to | |
| | EdgeLock secure enclave (S400) failure | 6 |
| 8.4 | Cortex-M33 cannot exit from upower IRQ | |
| | handler | 6 |
| 8.5 | Flexcan_ping_pong_buffer_transfer case | |
| | loses first 8 bytes data for armgcc flash_ | |
| | debug | 7 |
| 8.6 | LPSPI b2b examples transfer fail on iar/ | |
| | armgcc flash target | 7 |
| 9 | Change log | |
| 10 | Revision history | |
| 11 | Legal information | 9 |

Please be aware that important notices concerning this document and the product(s) described herein, have been included in section 'Legal information'.