AwanSolveAi

Technician Repair Narrative

Synthetic technician narrative

Field	Value
Claim ID	DEMO-017
Technician	Technician Q
Equipment	Forklift

Complaint

Intermittent loss of traction.

Diagnosis

Performed Traction supply voltage.

Cause

Traction motor encoder failure

Correction

Replaced traction motor encoder. Installed part TRM-30.

Final Note

Repair completed and machine returned to service.

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD