AwanSolveAi

Technician Repair Narrative

Synthetic technician narrative

Field	Value
Claim ID	DEMO-026
Technician	Technician F
Equipment	Agricultural

Complaint

PTO disengages under load.

Diagnosis

Performed PTO hydraulic pressure.

Cause

PTO control solenoid sticking

Correction

Replaced PTO control solenoid. Installed part SOL-150P.

Final Note

Repair completed and machine returned to service.

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD