AwanSolveAi

Repair Work Order

Synthetic dealer work order

Field	Value
Work Order	WO-00028
Claim ID	DEMO-028
Model	LD950
Serial	LDR-950-2207
Operating Hours	4980
Opened	2026-09-09
Closed	2026-09-10

Complaint

Bucket tilt cylinder leaks externally.

Technician Findings

Tilt circuit pressure checked during diagnosis.

Repair

Resealed tilt cylinder

Technician

Technician H

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD