AwanSolveAi

Warranty Claim Cover Sheet

General heavy-equipment synthetic claim form

Field	Value
Claim ID	DEMO-029
Equipment	Loader
Model	LD950
Serial	LDR-950-2207
Operating Hours	4980
Claim Date	2026-09-12

Customer Complaint

Bucket tilt cylinder leaks externally.

Failure / Fault Code

HYD-LK

Claimed Cause

Tilt cylinder rod seal damaged

Correction

Resealed tilt cylinder

Claimed Part

TSK-950

Claimed Labor

5.0 h

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD