# Technician Findings

AwanSolveAi validation corpus

| Field | Value |
|---|---|
| Claim ID | A-006 |
| Technician | Validation Technician |

## Reported Complaint

Truck loses drive intermittently after 20 minutes.

## Test Performed

Traction bus voltage

## Confirmed Cause

Loose traction controller power terminal

## Repair Action

Repaired and torqued power terminal

## Installed Part

TERM-45

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD