Technician Findings

AwanSolveAi validation corpus

Field	Value
Claim ID	A-007
Technician	Validation Technician

Reported Complaint

Compressor cycles excessively at steady demand.

Test Performed

Receiver pressure decay

Confirmed Cause

Possible issue; cause not confirmed.

Repair Action

Replaced receiver check valve

Installed Part

CV-110

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD