Warranty Repair Claim Summary

AwanSolveAi validation corpus

Field	Value
Claim Number	A-008
Equipment Type	Agricultural
Asset Model	T190
Asset Serial Number	AG-190-7008
Meter Hours	1796
Customer Concern	Hydraulic remotes lose pressure under load.
Diagnostic Code	HYD-70
Root Cause	Remote valve spool leakage
Corrective Action	Replaced remote valve cartridge
Replacement Part	RVC-190
Labor Claimed	4.5 hours

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD