Technician Findings

AwanSolveAi validation corpus

Field	Value
Claim ID	A-008
Technician	Validation Technician

Reported Complaint

Hydraulic remotes lose pressure under load.

Test Performed

Remote hydraulic pressure

Confirmed Cause

Remote valve spool leakage

Repair Action

Replaced remote valve cartridge

Installed Part

RVC-190

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD