Warranty Repair Claim Summary

AwanSolveAi validation corpus

Field	Value
Claim Number	A-009
Equipment Type	Industrial Engine
Asset Model	E67
Asset Serial Number	EN-67-7009
Meter Hours	1833
Customer Concern	Engine hunts at low idle after warm-up.
Diagnostic Code	ECM-88
Root Cause	Fuel metering actuator sticking
Corrective Action	Replaced fuel metering actuator
Replacement Part	FMA-67
Labor Claimed	3.5 hours

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD