Technician Findings

AwanSolveAi validation corpus

Field	Value
Claim ID	A-017
Technician	Validation Technician

Reported Complaint

Generator starts but voltage is unstable under load.

Test Performed

AC output stability test

Confirmed Cause

Automatic voltage regulator feedback connector had high resistance

Repair Action

Repaired AVR feedback connector and verified output

Installed Part

CONN-AVR

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD