# Warranty Repair Claim Summary

AwanSolveAi validation corpus

| Field | Value |
|---|---|
| Claim Number | A-021 |
| Equipment Type | Generator |
| Asset Model | G141 |
| Asset Serial Number | GN-9021 |
| Meter Hours | 2277 |
| Customer Concern | Generator starts but voltage is unstable under load. |
| Diagnostic Code | AVR-21 |
| Root Cause | Automatic voltage regulator feedback connector had high resistance |
| Corrective Action | Repaired AVR feedback connector and verified output |
| Replacement Part | CONN-AVR |
| Labor Claimed | 2.8 hours |

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD