# Mechanic Diagnostic Report

AwanSolveAi External Validation Pack V1

| Field | Value |
| --- | --- |
| Claim Number | EXT-001 |
| Technician | External Validation Technician |

## Customer Concern

Hydraulic/output performance becomes unstable after sustained operation.

## Diagnostic Procedure

Control signal and output stability test

## Confirmed Cause

Electrical feedback connector resistance caused unstable control signal.

## Corrective Action

Connector repaired, terminals secured, and system retested.

## Installed Part

CN-4421

SYNTHETIC EXTERNAL-VALIDATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD