Agricultural Warranty Claim Request

AwanSolveAi External Validation Pack V1

Field	Value
Claim Reference	EXT-009
Equipment / Machine Type	Agricultural
Equipment Model #	HS-RT200
Serial #	HS200-8209
Machine Hours	2749
Machine Description / Reported Problem	Hydraulic/output performance becomes unstable after sustained operation.
Failure Code	EXT-42
Technician Diagnosis	Electrical feedback connector resistance caused unstable control signal.
Repair Performed	Connector repaired, terminals secured, and system retested.
Part Number	CN-4421
Labor Hours	3.5 hours

SYNTHETIC EXTERNAL-VALIDATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD