Attachment Warranty Claim

AwanSolveAi External Validation Pack V1

Field	Value
Claim Reference	EXT-011
Equipment / Machine Type	Excavator
Equipment Model #	RZ-RW55
Serial #	RZ55-8211
Excavator Hours	2871
Issue	Hydraulic/output performance becomes unstable after sustained operation.
Failure Code	EXT-42
Failure Analysis	Electrical feedback connector resistance caused unstable control signal.
Repair Information	Connector repaired, terminals secured, and system retested.
Parts Used for Repair	CN-4421
Total Shop Labor Hours	3.5 hours
Excavator Make/Model	EX-220
Install Date	2026-03-01
Commissioning Form Completed	Yes
Flow Setting	165 L/min
Relief Pressure	24.6 MPa

SYNTHETIC EXTERNAL-VALIDATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD