Construction Equipment Warranty Claim

AwanSolveAi External Validation Pack V1

Field	Value
Claim Reference	EXT-015
Equipment / Machine Type	Loader
Equipment Model #	KT-SC40
Serial #	KT40-8215
Machine Meter	3115
Description of Warranty Issue	Hydraulic/output performance becomes unstable after sustained operation.
Failure Code	EXT-42
Mechanic Findings	Electrical feedback connector resistance caused unstable control signal.
Parts Replaced or Repaired	Connector repaired, terminals secured, and system retested.
Replacement Part Number	CN-4421
Mechanic Labor Hours	3.5 hours
Product Number	P-20488
In-Service Date	2026-02-12
Date of Occurrence	2026-09-15
Mechanic in Charge	Synthetic Technician

SYNTHETIC EXTERNAL-VALIDATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD