Heavy Attachment Warranty Claim

AwanSolveAi External Set C

Field	Value
Dealer Claim Number	EXTC-001
Equipment Type	Excavator Attachment
Machine Model	PL-JRB90
Serial Number	PAL90-1201
Hours	1567
Details of Failure	Intermittent loss of performance occurs after extended operation.
Failure Code	C-88
Failure Cause Assessment	Control feedback connection developed intermittent resistance.
Corrective Action	Connection repaired, terminals secured, and operation retested.
Parts Used in Repair	PT-8842
Total Labor Hours	3.0 hours
Failure Date	2026-09-23
Repair Date	2026-09-26
PCN Number	PCN-4012
RGA Number	RGA-2981
Total Parts Cost	325.00
Total Claim Cost	685.00

SYNTHETIC EXTERNAL HOLDOUT DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD