# Technician Diagnostic Report

AwanSolveAi External Set C

| Field | Value |
|---|---|
| Claim ID | EXTC-006 |
| Technician | External Set C Technician |

## Customer Concern

Intermittent loss of performance occurs after extended operation.

## Diagnostic Procedure

System operating performance test

## Confirmed Cause

Control feedback connection developed intermittent resistance.

## Corrective Action

Connection repaired, terminals secured, and operation retested.

## Installed Part

PT-8842

SYNTHETIC EXTERNAL HOLDOUT DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD