Aerial Lift Warranty Claim

AwanSolveAi External Set C

Field	Value
Warranty Case	EXTC-013
Equipment Type	Aerial Work Platform
Model Number	MEC-4555
Serial Number	MEC45-1213
Hour Meter	2371
Failure Description	Intermittent loss of performance occurs after extended operation.
Failure Code	C-88
Root Cause Determination	Control feedback connection developed intermittent resistance.
Repairs Completed	Connection repaired, terminals secured, and operation retested.
Part Number	PT-8842
Repair Labor Time	3.0 hours
Date of Repair	2026-09-26
Service Call Address	Synthetic Service Site

SYNTHETIC EXTERNAL HOLDOUT DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD