Warranty Repair Claim Summary

AwanSolveAi validation corpus

Field	Value
Claim Number	A-001
Equipment Type	Excavator
Asset Model	ZX210
Asset Serial Number	HX-210-7001
Meter Hours	1537
Customer Concern	Hydraulic response becomes slow when warm.
Diagnostic Code	HYD-18
Root Cause	Main hydraulic pump internal leakage
Corrective Action	Overhauled main hydraulic pump
Replacement Part	PMP-210
Labor Claimed	5.5 hours

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD