# Technician Findings

AwanSolveAi validation corpus

| Field | Value |
|---|---|
| Claim ID | A-009 |
| Technician | Validation Technician |

## Reported Complaint

Generator starts but voltage is unstable under load.

## Test Performed

AC output stability test

## Confirmed Cause

Automatic voltage regulator feedback connector had high resistance

## Repair Action

Repaired AVR feedback connector and verified output

## Installed Part

CONN-AVR

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD