Technician Findings

AwanSolveAi validation corpus

Field	Value
Claim ID	A-019
Technician	Validation Technician

Reported Complaint

Hydraulic response becomes slow when warm.

Test Performed

Pump case pressure

Confirmed Cause

Main hydraulic pump internal leakage

Repair Action

Overhauled main hydraulic pump

Installed Part

PMP-210

SYNTHETIC DEMONSTRATION DOCUMENT - NOT AN ACTUAL OEM OR CUSTOMER RECORD