

Title	Report and Tracking of Illegal Ship To Ship Activity						
Date	02 nd June 2025						
Time	0601 hrs						
Prepared by	Muhammad Shohel Bin Abdul Aziz						

Incident Report								
Type of activity Suspected there is Ship to Ship activity going on								
Area	Area 1 (Mersing)							
Vessels Involved	1. KATORIN_1 (533133481)							
	2. PP 5711 (677052800)							
Description	The ships are located very close to each other							



Information	×	Information	2
Name	KATORIN_1	Name	PP 5711
MMSI	533133481	MMSI	677052800
OMI	8537358	IMO	9132351
Country	Malaysia	Country	Tanzania
Call Sign	9M3862	Call Sign	5IM628
Туре	Tanker	Type	Tanker
Length x Beam	91m x 13m	Length x Beam	78m x 5m
Max.Draught	5.4m	Max.Draught	4.8m
Nav. Status	Under way sailing	Nav. Status	Under way using engine
Last Seen UTC	2025-06-01 21:59	Last Seen UTC	2025-06-01 21:59
Last Seen Loc	2025-06-02 05:59	Last Seen Loc	2025-06-02 05:59
Latitude	1°51.128'N	Latitude	1°51.131'N
Longitude	104°44.538'E	Longitude	104°44.544'E
Speed	0.3knt	Speed	0knt
Course	6.1°	Course	79.3°
Heading		Heading	175°
Rate of Turn		Rate of Turn	
Destination	EOPL	Destination	E OPL
ETA	2025-05-31 04:00	ETA	2025-04-29 07:00
Pos. Fix. Dev.	GPS	Pos. Fix. Dev.	Undefined

Figure 2: KATORIN_1 & PP 5711 Details



Name	MMSI	IMO	Call Sign	Туре	Last	Seen	Outside	First 5	Seen	Inside	Last	Seen	Inside	First See	en Outside	Time I	n Zone	Average Speed	Destination	ETA
KATORIN_	1 533133481	8537358	9M3862	Tanker	2025	-05-2	7 04:55	2025-0	05-27	04:56	2025-	05-28	14:03	2025-05	-28 14:20	1d 9h	7m	1.2	PASIRGUDANG	2025-05-06 23:30
KATORIN_	1 533133481	8537358	9M3862	Tanker	2025	-05-3	1 03:41	2025-0	05-31	03:43	2025-	06-02	05:59			2d 2h	16m	1.1	PTP MALAYSIA	2025-05-29 10:00
PP 5711	677052800	9132351	5IM628	Tanker				2025-0	05-26	06:01	2025-	05-31	10:29	2025-05	-31 10:32	5d 4h	28m	0.7	E OPL	2025-04-29 07:00
PP 5711	677052800	9132351	5IM628	Tanker	2025	-06-0	1 06:12	2025-0	06-01	06:13	2025-	06-02	05:59			23h 46	5m	0.7	E OPL	2025-04-29 07:00

Figure 2 : Report Zone Details for 7 days

Remarks

As per checking we can conclude that there is suspicious activity between this 2 vessels.