

| Title | Report and Tracking of Illegal Ship To Ship Activity | | | |
|-------------|--|--|--|--|
| Date | 02 nd June 2025 | | | |
| Time | 0000 hrs | | | |
| Prepared by | Muhammad Shohel Bin Abdul Aziz | | | |

| Incident Report | | | | |
|------------------|---|--|--|--|
| Type of activity | Suspected there is Ship to Ship activity going on | | | |
| Area | Area 1 (Mersing) | | | |
| Vessels Involved | 1. GENEVIEVE 88 (533133444) | | | |
| | 2. MEWAH SEJATI (533000089) | | | |
| Description | The ships are located very close to each other | | | |



| momation | | - 67 | | | - |
|----------------|------------------|------|-------------------|-----------------------|---|
| Name | GENEVIEVE 88 | | Name | MEWAH SEJATI | |
| MMSI | 533133444 | | MMSI | 533000089 | |
| | | | IMO | 8801761 | |
| IMO | 856377300 | | Country | Malaysia 9MGE5 | |
| Country | Malaysia | | Call Sign Type | Tanker | |
| Call Sign | 9M3906 | | Length x Beam | | |
| Type | Tanker | | Max.Draught | 3.5m | |
| Length x Beam | 123m x 18m | | Nav. Status | Under way using engin | е |
| - | | | Last Seen UTC | 2025-06-01 15:53 | |
| Max.Draught | 7m | | Last Seen Loc | 2025-06-01 23:53 | |
| Nav. Status | At anchor | | Latitude | 1°54.807'N | |
| Last Seen UTC | 2025-06-01 15:58 | | Longitude | 104°44.926′E | |
| Last Seen Loc | 2025-06-01 23:58 | | Speed | 0.6knt 322.9° | |
| Latitude | 1°54.807'N | | Heading | 322.9 | |
| | | | Rate of Turn | | |
| Longitude | 104°44.908'E | | Destination | HIGH SEA EOPL | |
| Speed | 0.1knt | | ETA | 2025-05-15 15:25 | |
| Course | 249° | | Pos. Fix. Dev. | GPS | |
| Heading | 145° | | | | |
| Rate of Turn | | | | 7 | |
| Destination | VT | | 14 | A lan | |
| ETA | 2025-05-26 16:00 | | 4 | | |
| Pos. Fix. Dev. | GPS | | | SECOND SECOND | |

Figure 2: GENEVIEVE 88 & MEWAH SEJATI Details



Remarks

As per checking we can conclude that there is suspicious activity between this 2 vessels.