

Title	Report and Tracking of Illegal Ship To Ship Activity
Date	28 th June 2025
Time	1104 hrs
Prepared by	Muhammad Shohel Bin Abdul Aziz

Incident Report							
Type of activity	Suspected there is Ship to Ship activity going on						
Area	Area 1 (Mersing)						
Vessels Involved	1. HERA (312272000)						
	2. SILVER ELITE (533045400)						
Description	The ships are located very close to each other						



Information	×	Information		×
Name	HERA	Name	SILVER ELITE	
MMSI	312272000	MMSI	533045400	
IMO	1075375	IMO	9072484	
Country	Belize	Country	Malaysia	
Call Sign	V3NM4	Call Sign	9MLJ6	
Туре	Tanker	Туре	Tanker	
Length x Beam	104m x 15m	Length x Beam	73m x 11m	
Max.Draught	6m	Max.Draught	3.2m	
Nav. Status	At anchor	Nav. Status	Under way using engine	
Last Seen UTC	2025-06-28 03:06	Last Seen UTC	2025-06-28 03:02	
Last Seen Loc	2025-06-28 11:06	Last Seen Loc	2025-06-28 11:02	
Latitude	1°50.706'N	Latitude	1°50.707'N	
Longitude	104°44.262'E	Longitude	104°44.251'E	
Speed	0.1knt	Speed	0.1knt	
Course	160.3°	Course	318.7°	
Heading	149°	Heading	60°	
Rate of Turn		Rate of Turn		
Destination	EOPL	Destination	EOPL	
ETA	2025-06-23 02:00	ETA	2025-02-06 22:00	
AIS UTC Time	2025-06-28 03:06	AIS UTC Time	2025-06-28 03:02	
AIS Latitude	1°50.706'N	AIS Latitude	1°50.707'N	
AIS Longitude	104°44.262'E	AIS Longitude	104°44.251'E	
Sat UTC Time	2025-06-22 16:58	Sat UTC Time	2025-06-25 16:59	
Sat Latitude	1°51.548'N	Sat Latitude	1°57.849'N	
Sat Longitude	104°42.578'E	Sat Longitude	104°42.231'E	
Pos. Fix. Dev.	GPS	Pos. Fix. Dev.	GPS	

Figure 2: HERA & SILVER ELITE Details



Name	MMSI	IMO	Call Sign	Type	Last Seen Outside	First Seen	Inside	Last Seen Inside	First Seen Outside	Time In Zone	Average Speed	Destination	ETA
HERA	312272000	1075375	V3NM4	Tanker	2025-06-22 22:37	2025-06-22	22:41	2025-06-28 11:06		5d 12h 25m	0.6	BATAM	2025-06-22 16:00
SILVER ELITE	533045400	9072484	9MLJ6	Tanker		2025-06-21	17:06	2025-06-28 11:02		6d 17h 56m	1.7	EOPL	2025-02-06 22:00

Figure 2 :Report Zone Details for 7 days

Remarks

As per checking we can conclude that there is suspicious activity between this 2 vessels.