

Action	Object	Change Document	Status
Remove Pins From Nets			
Remove	C7-1 from +5V	In PCB1Ard.PcbDoc	
Remove	C7-2 from GND	In PCB1Ard.PcbDoc	
Remove	C9-2 from GND	In PCB1Ard.PcbDoc	
Remove	C11-2 from GND	In PCB1Ard.PcbDoc	
Remove	D3-C from +5V	In PCB1Ard.PcbDoc	
Remove	GROUND-1 from GND	In PCB1Ard.PcbDoc	
Remove	ICSP1-2 from +5V	In PCB1Ard.PcbDoc	
Remove	ICSP1-6 from GND	In PCB1Ard.PcbDoc	
Remove	RN1-3 from +5V	In PCB1Ard.PcbDoc	
Remove	RN2-2 from +5V	In PCB1Ard.PcbDoc	
Remove	RN2-3 from +5V	In PCB1Ard.PcbDoc	
Remove	RN2-4 from DTR	In PCB1Ard.PcbDoc	
Remove	RN2-5 from GND	In PCB1Ard.PcbDoc	
Remove	U3-3 from GND	In PCB1Ard.PcbDoc	
Remove	U3-4 from +5V	In PCB1Ard.PcbDoc	
Remove	U3-13 from DTR	In PCB1Ard.PcbDoc	
Remove	U3-32 from +5V	In PCB1Ard.PcbDoc	
Remove	U3-33 from GND	In PCB1Ard.PcbDoc	
Remove Nets			
Remove	M8RXD	From PCB1Ard.PcbDoc	
Remove	M8TXD	From PCB1Ard.PcbDoc	
Remove	MISO2	From PCB1Ard.PcbDoc	
Remove	MOSI2	From PCB1Ard.PcbDoc	
Remove	NetC8_1	From PCB1Ard.PcbDoc	
Remove	PB4	From PCB1Ard.PcbDoc	
Remove	PB5	From PCB1Ard.PcbDoc	
Remove	PB6	From PCB1Ard.PcbDoc	
Remove	PB7	From PCB1Ard.PcbDoc	
Remove	RD-	From PCB1Ard.PcbDoc	
Remove	RD+	From PCB1Ard.PcbDoc	
Remove	RESET2	From PCB1Ard.PcbDoc	
Remove	RXLED	From PCB1Ard.PcbDoc	
Remove	SCK2	From PCB1Ard.PcbDoc	
Remove	TXLED	From PCB1Ard.PcbDoc	
Remove	UGND	From PCB1Ard.PcbDoc	
Remove	XT1	From PCB1Ard.PcbDoc	
Remove	XT2	From PCB1Ard.PcbDoc	
Remove Components			
Remove	C7	From PCB1Ard.PcbDoc	
Remove	C8	From PCB1Ard.PcbDoc	
Remove	C9	From PCB1Ard.PcbDoc	
Remove	C11	From PCB1Ard.PcbDoc	
Remove	D3	From PCB1Ard.PcbDoc	
Remove	GROUND	From PCB1Ard.PcbDoc	
Remove	ICSP1	From PCB1Ard.PcbDoc	
Remove	JP2	From PCB1Ard.PcbDoc	
Remove	R1	From PCB1Ard.PcbDoc	
Remove	U3	From PCB1Ard.PcbDoc	
Remove	Y1	From PCB1Ard.PcbDoc	
Add Components			
Add	C20	To PCB1Ard.PcbDoc	
Add	USB SERIAL CONVERTER	To PCB1Ard.PcbDoc	

Action	Object	Change Document	Status
Add Pins To Nets			
Add	C20-2 to GND	In PCB1Ard.PcbDoc	
Add	J?-4 to GND	In PCB1Ard.PcbDoc	
Add	L1-1 to GND	In PCB1Ard.PcbDoc	
Add	RN2-2 to IO1	In PCB1Ard.PcbDoc	
Add	RN2-3 to IO0	In PCB1Ard.PcbDoc	
Add	RX-C to GND	In PCB1Ard.PcbDoc	
Add	TX-C to GND	In PCB1Ard.PcbDoc	
Add	USB SERIAL CONVERTER-1 to GND	In PCB1Ard.PcbDoc	
Add	USB SERIAL CONVERTER-13 to DTR	In PCB1Ard.PcbDoc	
Add	USB SERIAL CONVERTER-16 to +5V	In PCB1Ard.PcbDoc	
Change Net Names			
Modify	XUSB -> NetF1_2	In PCB1Ard.PcbDoc	
Add Nets			
Add	NetC20_1	To PCB1Ard.PcbDoc	
Add	NetRN3_1	To PCB1Ard.PcbDoc	
Add	NetRN3_4	To PCB1Ard.PcbDoc	
Add	NetRN4_7	To PCB1Ard.PcbDoc	
Add	NetRN4_8	To PCB1Ard.PcbDoc	
Add Component Class Members			
Add	C20 to UNO-TH_Rev3e	In PCB1Ard.PcbDoc	
Add	USB SERIAL CONVERTER to UNO-TH_Rev3e	In PCB1Ard.PcbDoc	