Input

4 bits: Sensores

1 = Patedó ubstando

0 = No detecta obstando

4 Sensores

So

Si

Si

Output

4 bits: Monmantes

0000 - We

0001 - Frv

0010 - Back

0011 - Right



