



Part 1.6 — kinematic-metric blind spot to smooth-but-wrong perturbations


P1 — constant-velocity drift



P2 — constant angular bias



P3 — constant-acceleration drift



P4 — sine bump (smooth, bounded)

