

Estimate Comparison Report

run_id: 8051c3f9-6e69-43f0-bfb7-046d7d6031a1

green: 7 orange: 32 blue: 78

A total (matched): \$7,227.38 B total (matched): \$8,108.45

This report groups items by room mapping and labels:

GREEN = matched + within $\pm 2\%$

ORANGE = matched but cost differs $> 2\%$ or scope differs

BLUE = contractor-only (nugget)

Room-by-room detail

run_id: 8051c3f9-6e69-43f0-bfb7-046d7d6031a1

green: 7 orange: 32 blue: 78

A total (matched): \$7,227.38 B total (matched): \$8,108.45

Bedroom 1 ↔ Bedroom

status | A description (A\$) -> B description (B\$) [why]

- **BLUE** Batt insulation replacement per LF - 4" - up to 2' tall (\$11.13) -> (-)
No direct match for batt insulation replacement in B.
- **BLUE** 1/2" - drywall per LF - up to 2' tall (\$170.43) -> (-)
No specific match for drywall replacement per LF in B.
- **BLUE** Seal/prime (1 coat) then paint (2 coats) the walls (\$828.58) -> (-)
Painting walls not explicitly mentioned in B.
- **BLUE** Outlet or switch cover (\$4.53) -> (-)
No mention of outlet or switch cover in B.
- **BLUE** Baseboard - 3 1/4" (\$54.06) -> (-)
Baseboard work not specifically covered in B.
- **BLUE** Seal (1 coat) & paint (1 coat) baseboard (\$107.80) -> (-)
No item related to sealing and painting baseboards in B.
- **BLUE** Door stop - wall or floor mounted (\$18.04) -> (-)
No item on door stop in B.
- **BLUE** Paint door/window trim & jamb - Large - 2 coats (per ... (\$61.55) -> (-)
Painting door/window trim & jamb not clearly matched.
- **BLUE** Door opening (jamb & casing) - 32"to36"wide - paint g... (\$227.44) -> (-)
Painting jamb & casing not explicitly listed in B.
- **BLUE** Seal & paint door/window trim & jamb - (per side) (\$104.76) -> (-)
Seal & Paint of door trim & jamb not directly found in B.
- **BLUE** Door hinges (set of 3) and slab - Detach & reset (\$35.92) -> (-)
Door hinges detach & reset not found in B.
- **BLUE** On site door prep. for full mortised hinges - Labor only (\$122.73) -> (-)
No matching item for door prep work in B.
- **BLUE** Interior door - Reset - slab only (\$16.53) -> (-)
No mention of resetting door slab itself in B.
- **BLUE** Mask wall - plastic, paper, tape (per LF) (\$90.83) -> (-)
Wall masking not mentioned in B.
- **BLUE** Floor protection - plastic and tape - 10 mil (\$20.08) -> (-)
Floor protection not specified in B.
- **BLUE** Cold air return cover - Detach & reset (\$25.32) -> (-)
No specific item for cold air return cover detach & reset in B.
- **BLUE** Remove Carpet pad - Remove carpet pad that was not to... (\$15.38) -> (-)
Carpet pad removal not separately listed in B.
- **BLUE** Content Manipulation charge - per hour (\$137.30) -> (-)
No reference to content manipulation charges in B.
- **BLUE** Final cleaning - construction - Residential (\$57.72) -> (-)
Final cleaning not explicitly mentioned in B.
- **BLUE** R&R Carpet pad (\$63.85) -> (-)
No direct matching item for R&R Carpet pad in B.
- **BLUE** Remove Carpet (\$22.68) -> (-)
Carpet removal component matches with broad scope.
- **BLUE** Carpet - Carpet is continuous with Living Room, 15 % ... (\$358.70) -> (-)
Matches broader description of carpet with waste.
- **BLUE** Content Manipulation charge - per hour (\$68.65) -> (-)
Content Manipulation not explicitly covered in B.
- **BLUE** Baseboard, drywall, carpet and door jamb were partial... (-) -> (-)
Descriptive overview, but no direct match found.
- **BLUE** Cold air return cover will need to be detached and re... (-) -> (-)
Described action not separately listed in B.
- **ORANGE** Paint door slab only - 2 coats (per side) (\$123.09) -> Paint door slab only - 2 coats (per side) (\$61.26)
Direct match for painting door slab only.

Room-by-room detail

run_id: 8051c3f9-6e69-43f0-bfb7-046d7d6031a1

green: 7 orange: 32 blue: 78

A total (matched): \$7,227.38 B total (matched): \$8,108.45

- **ORANGE** Remove Carpet - Remove carpet that was not torn out d... (\$35.50) -> Remove Carpet (Some carpet and pad was remove... (\$
Match for carpet removal, scope matches mitigation remark.
- **ORANGE** Carpet pad (\$103.00) -> Carpet pad - per specs from independent pad a... (\$19.29)
Carpet pad matches with spec detail from B.
- **ORANGE** Carpet - Includes 15% waste (\$683.85) -> Carpet - per specs from independent carpet an... (\$967.48)
Carpet replacement with independent spec analysis matches.

Bedroom 1 Closet ↔ BRM Closet

status | A description (A\$) -> B description (B\$) [why]

- **BLUE** R&R Carpet pad (\$12.33) -> (-)
No direct match for 'R&R Carpet pad' identified in insurance's item list.
- **BLUE** Content Manipulation charge per hour (\$68.65) -> (-)
Content Manipulation is not addressed in insurance items; no match found.
- **ORANGE** Remove Carpet (\$4.39) -> Remove Carpet (\$6.01)
Exact match with 'Remove Carpet' in Doc B.
- **ORANGE** Carpet (\$69.26) -> Carpet - per specs from independent carpet an... (\$228.66)
Both items refer to providing or addressing the carpet itself, despite the additional note on specs in Doc B.

Coat Closet ↔ Hall Closet

status | A description (A\$) -> B description (B\$) [why]

- **BLUE** R&R Carpet pad (\$10.45) -> (-)
No specific item in B matches 'R&R Carpet pad'. No mention of pad installation in B.
- **BLUE** Content Manipulation charge (\$68.65) -> (-)
No matching line item in B for 'Content Manipulation charge'. This appears as an unrelated service.
- **ORANGE** Remove Carpet (\$3.71) -> Remove Carpet (Some carpet and pad was remove... (\$3.12)
Both A and B describe the removal of carpet. Although B mentions previous removal by another company, the core a...
- **ORANGE** Carpet (\$58.67) -> Carpet - per specs from independent carpet an... (\$170.86)
Both A and B specify carpet installation. The description in B references specs but fundamentally covers carpet ...

Formal Dining Room ↔ Dining Room

status | A description (A\$) -> B description (B\$) [why]

- **BLUE** R&R Carpet pad (\$143.99) -> (-)
No direct match in B for R&R Carpet pad. Only carpet removal and installation listed.
- **ORANGE** Remove Carpet (\$51.14) -> Remove Carpet (\$52.92)
Both items are specifically for carpet removal, indicating a match in scope.
- **ORANGE** Carpet (\$809.00) -> Carpet - per specs from independent carpet an... (\$1,021.27)
Both involve carpet installation, even if descriptions vary slightly.
- **ORANGE** Content Manipulation charge (\$68.65) -> Contents - move out then reset (\$100.75)
Both involve handling/moving contents, indicating similar scope of work.

Garage ↔ Garage

status | A description (A\$) -> B description (B\$) [why]

- **BLUE** Seal/prime (1 coat) then paint (2 coats) the walls (\$1,746.02) -> (-)
Item A involves sealing, priming, and painting, but B only mentions painting.
- **BLUE** Seal (1 coat) & paint (1 coat) baseboard (\$227.15) -> (-)
No exact match for sealing and painting baseboard found.
- **BLUE** Seal & paint door/window trim & jamb - (per side) (\$104.76) -> (-)
No exact match for sealing & painting door/window trim & jamb noted.
- **BLUE** Door hinges (set of 3) and slab - Detach & reset (\$35.92) -> (-)
No exact match for detaching and resetting door hinges found.
- **BLUE** On site door prep. for full mortised hinges - Labor only (\$122.73) -> (-)
No exact match for mortised hinges prep work.
- **BLUE** Mask wall - plastic, paper, tape (per LF) (\$191.39) -> (-)
No match found for masking wall.
- **BLUE** Floor protection - plastic and tape - 10 mil (\$190.54) -> (-)
No match found for floor protection.

Room-by-room detail

run_id: 8051c3f9-6e69-43f0-bfb7-046d7d6031a1

green: 7 orange: 32 blue: 78

A total (matched): \$7,227.38 B total (matched): \$8,108.45

- **BLUE** Final cleaning - construction - Residential (\$195.74) -> (-)
No specific match for final cleaning found.
- **BLUE** Baseboard is 3.25" tall (-) -> (-)
Descriptive note, no direct match.
- **BLUE** Drywall on water heater riser and insulation in wall ... (-) -> (-)
Descriptive note about previous work, no direct match.
- **BLUE** Remove and replace drywall on water heater riser and ... (-) -> (-)
General note about prior work, does not match specific items.
- **BLUE** Door that was detached during mitigation (-) -> (-)
Descriptive note, no direct match.
- **BLUE** Doors that were detached during mitigation (-) -> (-)
Descriptive note, no direct match.
- **GREEN** Door opening (jamb & casing) - 32"to36"wide - paint g... (\$227.44) -> Door opening (jamb & casing) - 32"to36"wide -... (\$227.3)
- **GREEN** Interior door - Reset - slab only (\$16.53) -> Interior door - Reset - slab only (\$16.51)
Both involve resetting the interior door slab.
- **ORANGE** Batt insulation replacement per LF - 4" - up to 2' tall (\$59.39) -> Batt insulation - 4" - R11- unfaced batt (\$6.66)
Both deal with replacing batt insulation.
- **ORANGE** 1/2" - drywall per LF - up to 2' tall (\$220.80) -> 1/2" - drywall per LF - up to 2' tall (\$262.61)
Both involve installing 1/2 inch drywall up to 2 feet tall.
- **ORANGE** Texture drywall - light hand texture (\$53.72) -> Texture drywall - light hand texture (\$102.55)
Both are for texture drywall with a light hand texture.
- **ORANGE** Baseboard - 3 1/4" (\$70.05) -> Baseboard - 3 1/4" MDF w/profile (\$81.35)
Both reference installing baseboard of 3.25".
- **ORANGE** Paint door slab only - 2 coats (per side) (\$123.09) -> Paint door slab only - 2 coats (per side) (\$61.26)
Both are for painting the door slab - 2 coats.
- **ORANGE** Content Manipulation charge - per hour (\$137.30) -> Contents - move out then reset - Large room (\$151.10)
Both involve content manipulation or moving.

Laundry Room ↔ Laundry Room

status | A description (A\$) -> B description (B\$) [why]

- **BLUE** Batt insulation replacement per LF - 4" - up to 2' tall (\$40.64) -> (-)
No direct match for insulation replacement per LF.
- **BLUE** Seal/prime (1 coat) then paint (2 coats) the walls (\$479.12) -> (-)
Scope is similar but coat numbers differ. Item A specifies 3 coats total, B specifies 1.
- **BLUE** HEPA Vacuuming - Light - (PER SF) (\$23.94) -> (-)
No clear match for HEPA vacuuming scope.
- **BLUE** Mortar bed for tile floors (\$220.42) -> (-)
Both involve floor preparation, but distinct methods.
- **BLUE** Grout sealer (\$55.34) -> (-)
No matching item in list B for grout sealer.
- **BLUE** Door stop - wall or floor mounted (\$18.04) -> (-)
No equivalent item for door stop.
- **BLUE** Door hinges (set of 3) and slab - Detach & reset (\$35.92) -> (-)
No specific match for door hinge work.
- **BLUE** On site door prep. for full mortised hinges - Labor only (\$122.73) -> (-)
No equivalent task for on site door prep.
- **BLUE** Mask wall - plastic, paper, tape (per LF) (\$52.51) -> (-)
No match found for masking walls.
- **BLUE** Floor protection - plastic and tape - 10 mil (\$17.61) -> (-)
Floor protection with plastic not found in B.
- **BLUE** Content Manipulation charge - per hour (\$68.65) -> (-)
Content manipulation charge not specific item in list B.
- **BLUE** Baseboard and drywall behind washer and dryer removed... (-) -> (-)
Descriptive statement with no match in B.

Room-by-room detail

run_id: 8051c3f9-6e69-43f0-bfb7-046d7d6031a1
green: 7 orange: 32 blue: 78
A total (matched): \$7,227.38 B total (matched): \$8,108.45

- **BLUE** Door jamb removed during mitigation (-) -> (-)
Statement of removed item, no match needed in B.
- **GREEN** 1/2" - drywall per LF - up to 2' tall (\$384.73) -> 1/2" - drywall per LF - up to 2' tall (\$381.05)
Both items describe drywall per LF work.
- **GREEN** Door opening (jamb & casing) - 32" to 36" wide - pain... (\$227.44) -> Door opening (jamb & casing) - 32"to36"wide -... (\$227.36)
Both detail door jamb and casing paint work.
- **GREEN** Interior door - Reset - slab only (\$16.53) -> Interior door - Reset - slab only (\$16.51)
Both describe resetting interior door slab.
- **GREEN** Washer/Washing machine - Remove & reset (\$71.65) -> Detach & Reset Washer/Washing Machine - Front... (\$71.64)
Matching description and amount for washer reset.
- **GREEN** Dryer - Remove & reset (\$55.24) -> Detach & Reset Dryer - Electric (\$55.23)
Matching description and amount for dryer reset.
- **ORANGE** Texture drywall - light hand texture (\$93.61) -> Texture drywall - light hand texture (\$147.79)
Both items involve light hand texturing drywall.
- **ORANGE** Concrete grinding (\$171.59) -> Floor leveling cement - Average (\$118.10)
Concrete grinding vs floor leveling cement are related but distinct tasks.
- **ORANGE** Tile floor covering (\$515.72) -> Tile floor covering (\$502.13)
Both describe tile floor covering.
- **ORANGE** Baseboard - 3 1/4" (\$122.04) -> Baseboard - 3 1/4" MDF w/profile (\$118.03)
Both refer to 3 1/4" baseboard.
- **ORANGE** Seal (1 coat) & paint (1 coat) baseboard (\$62.34) -> Paint baseboard - two coats (For replace base... (\$59.59)
Both involve painting baseboards, based on usual repair phases.
- **ORANGE** Seal & paint door/window trim & jamb - (per side) (\$104.76) -> Paint door or window opening - 2 coats (per s... (\$52.08)
Different door elements, similar work but not a perfect match.
- **ORANGE** Paint door slab only - 2 coats (per side) (\$123.09) -> Paint door slab only - 2 coats (per side) (\$61.26)
Both detail painting door slab per side.
- **ORANGE** Final cleaning - construction - Residential (\$18.08) -> Final cleaning - construction - Residential (\$17.63)
Both describe final cleaning scope.

Living Room ↔ Living Room

status | A description (A\$) -> B description (B\$) [why]

- **BLUE** 1/2" - drywall per LF - up to 2' tall (\$18.12) -> (-)
No matching description in items_b corresponds to drywall activities.
- **BLUE** Seal/prime (1 coat) then paint (2 coats) the walls (\$1,035.30) -> (-)
No matching painting activities found in items_b.
- **BLUE** Baseboard - 3 1/4" (\$5.75) -> (-)
No matching description in items_b corresponds to baseboard installation.
- **BLUE** Seal (1 coat) & paint (1 coat) baseboard (\$139.73) -> (-)
No matching painting activities found for baseboards in items_b.
- **BLUE** Mask wall - plastic, paper, tape (per LF) (\$120.92) -> (-)
No masking or preparation activities found in items_b.
- **BLUE** Floor protection - plastic and tape - 10 mil (\$26.07) -> (-)
No floor protection activities found in items_b.
- **BLUE** Window drapery - hardware - Detach & reset (\$126.91) -> (-)
No matching description for window drapery handling found in items_b.
- **BLUE** Content Manipulation (Bid Item) - Bid item to remove ... (\$0.00) -> (-)
Specific bid item for piano not directly matched; general content move covered by another entry.
- **BLUE** Final cleaning - construction - Residential (\$134.20) -> (-)
Final cleaning not mentioned in items_b.
- **ORANGE** R&R Carpet pad (\$282.98) -> Carpet pad - per specs from independent pad a... (\$12.39)
Both involve carpet pad handling, though descriptions vary.
- **ORANGE** Remove Carpet (\$100.53) -> Remove Carpet (Some carpet and pad was remove... (\$115.56)
Direct match for carpet removal.
- **ORANGE** Carpet - Carpet is continuous with Hallway, 15 % wast... (\$1,589.84) -> Carpet - per specs from independent carpet an... (\$2,200.00)
Both refer to carpet installation, though detail levels differ.

Room-by-room detail

run_id: 8051c3f9-6e69-43f0-bfb7-046d7d6031a1

green: 7 orange: 32 blue: 78

A total (matched): \$7,227.38 B total (matched): \$8,108.45

■ **ORANGE** Content Manipulation charge - per hour (\$137.30) -> Contents - move out then reset - Large room (... (\$151.10)

Content manipulation matches with moving contents, including piano.

Main Level ↔ Main Level

status | A description (A\$) -> B description (B\$) [why]

■ **BLUE** Residential Supervision / Project Management - per hour (\$1,734.96) -> (-)

Supervision/Project Management does not match any listed tasks in B.

■ **BLUE** Megohmmeter check electrical circuits - average resid... (\$1,168.65) -> (-)

Megohmmeter check on electrical circuits has no matching electrical item in B.

■ **BLUE** Respirator - Half face - multi-purpose resp. (per day) (\$4.00) -> (-)

Respirator rental does not align with any specific task in B.

■ **BLUE** Respirator cartridge - HEPA only (per pair) (\$43.95) -> (-)

Respirator cartridge purchase does not align with any specific task in B.

■ **BLUE** Add for HEPA filter (for canister/backpack vacuums) (\$115.11) -> (-)

HEPA filter addition does not align with any specific task in B.

■ **BLUE** Bathtub (B1) (-) -> (-)

Bathtub (B1) does not match any general haul, insulation, cleaning, or cabinetry tasks.

Stair Closet ↔ Stair Closet

status | A description (A\$) -> B description (B\$) [why]

■ **BLUE** Door hinges (set of 3) and slab (\$35.92) -> (-)

Hinges and door slabs are not addressed in insurance items.

■ **BLUE** On site door prep. for full mortised hinges - Labor only (\$122.73) -> (-)

Door preparation labor not clearly matched to any insurance scope.

■ **BLUE** Interior door - Reset - slab only (\$16.53) -> (-)

No specific item for door reset in insurance list.

■ **BLUE** Paint door slab only - 2 coats (per side) (\$123.09) -> (-)

Paint for door slab not mentioned in insurance items.

■ **BLUE** Mask wall - plastic, paper, tape (per LF) (\$49.33) -> (-)

Masking mentioned but no detailed match with insurance items.

■ **BLUE** Floor protection - plastic and tape - 10 mil (\$11.63) -> (-)

Floor protection not matched or detailed in insurance.

■ **BLUE** Final cleaning - construction - Residential (\$11.94) -> (-)

Final cleaning not explicitly detailed in insurance list.

■ **ORANGE** Carpet pad (\$21.29) -> Carpet pad - per specs from independent pad a... (\$1.23)

Both refer to carpet pad, albeit with different specifications.

■ **ORANGE** Carpet (\$141.39) -> Carpet - per specs from independent carpet an... (\$54.10)

Both items specify carpet, noted with analysis requirements.

■ **ORANGE** Content Manipulation charge - per hour (\$68.65) -> Contents - move out then reset - Small room (\$75.62)

Content manipulation and reset/move matched in scope.