

Estimate Comparison Report

run_id: 0f475b52-e256-4ad9-bc45-aa3ba480aa2a

green: 7 orange: 25 blue: 56

A total (matched): \$6,520.48 B total (matched): \$6,871.52

This report groups items by room mapping and labels:

GREEN = matched + within $\pm 2\%$

ORANGE = matched but cost differs $> 2\%$ or scope differs

BLUE = contractor-only (nugget)

Room-by-room detail

run_id: 0f475b52-e256-4ad9-bc45-aa3ba480aa2a

green: 7 orange: 25 blue: 56

A total (matched): \$6,520.48 B total (matched): \$6,871.52

Bedroom 1 Closet ↔ BRM Closet

status | A description (A\$) -> B description (B\$) [why]

BLUE | R&R Carpet pad (\$12.33) -> (-)

The item 'R&R Carpet pad' does not have a direct comparable item in Doc B.

BLUE | Content Manipulation charge - per hour (\$68.65) -> (-)

'Content Manipulation charge' does not match any other scope in Doc B.

ORANGE | Remove Carpet (\$11.11) -> Remove Carpet (\$11.11)

Both items describe the removal of carpet.

ORANGE | Carpet (\$69.26) -> Carpet - per specs from independent carpet an... (\$228.66)

Both items relate to the replacement/installation of carpet.

Formal Dining Room ↔ Dining Room

status | A description (A\$) -> B description (B\$) [why]

BLUE | R&R Carpet pad (\$143.99) -> (-)

No direct match for 'R&R Carpet pad'. Doc B items do not mention carpet pad separately.

ORANGE | Remove Carpet (\$51.14) -> Remove Carpet (\$52.92)

Both items are for 'Remove Carpet', they match in scope.

ORANGE | Carpet (\$809.00) -> Carpet - per specs from independent carpet an... (\$1,021.27)

Both items are for 'Carpet', the B item's description includes more detail but the core scope is matched.

ORANGE | Content Manipulation charge per hour (\$68.65) -> Contents - move out then reset (\$100.75)

'Content Manipulation' matches 'Contents - move out then reset'. Both involve handling contents, albeit with dif...

Garage ↔ Garage

status | A description (A\$) -> B description (B\$) [why]

BLUE | Batt insulation replacement per LF - 4" - up to 2' tall (\$59.39) -> (-)

No matching LF insulation replacement item in Doc B.

BLUE | 1/2" - drywall per LF - up to 2' tall (\$220.80) -> (-)

No direct drywall installation match in Doc B.

BLUE | Texture drywall - light hand texture (\$53.72) -> (-)

No item in Doc B matches 'Texture drywall'.

BLUE | Seal/prime (1 coat) then paint (2 coats) the walls (\$1,746.02) -> (-)

Seal and paint walls in Doc A has no direct equivalent in Doc B.

BLUE | Door hinges (set of 3) and slab - Detach & reset (\$35.92) -> (-)

No match for 'Detach & reset door hinges' in Doc B.

BLUE | On site door prep. for full mortised hinges - Labor only (\$122.73) -> (-)

No match for 'On site door prep' in Doc B.

BLUE | Mask wall - plastic, paper, tape (per LF) (\$191.39) -> (-)

No masking wall item in Doc B.

BLUE | Floor protection - plastic and tape - 10 mil (\$190.54) -> (-)

No floor protection item in Doc B.

BLUE | Content Manipulation charge - per hour (\$137.30) -> (-)

No content manipulation charge equivalent in Doc B.

BLUE | Final cleaning - construction - Residential (\$195.74) -> (-)

No final cleaning item in Doc B.

BLUE | Baseboard, drywall and insulation removed during miti... (-) -> (-)

Item in A documents removed items, not directly restorable or replaceable.

BLUE | Drywall on water heater riser and insulation in wall ... (-) -> (-)

Removal during mitigation, no corresponding restoration in Doc B.

BLUE | Tub and toilet that were detached during mitigation (-) -> (-)

Detached tub/toilet, no match in Doc B.

BLUE | Door that was detached during mitigation (-) -> (-)

Detached door during mitigation, no direct match.

BLUE | Doors that were detached during mitigation (-) -> (-)

Documenting mitigation, not repair or replacement task.

Room-by-room detail

run_id: 0f475b52-e256-4ad9-bc45-aa3ba480aa2a

green: 7 orange: 25 blue: 56

A total (matched): \$6,520.48 B total (matched): \$6,871.52

GREEN | Door opening (jamb & casing) - 32"to36"wide - paint g... (\$227.44) -> Door opening (jamb & casing) - 32"to36"wide -... (\$227.36)

Door opening paint grade specification matches closely.

GREEN | Interior door - Reset - slab only (\$16.53) -> Interior door - Reset - slab only (\$16.51)

Direct match for interior door reset, slab only.

ORANGE | Baseboard - 3 1/4" (\$70.05) -> Baseboard - 3 1/4" MDF w/profile (\$81.35)

Baseboard installation matches in item description and scope.

ORANGE | Seal (1 coat) & paint (1 coat) baseboard (\$227.15) -> Paint baseboard - one coat (\$88.39)

Both items describe one coat paint on baseboards.

ORANGE | Seal & paint door/window trim & jamb - (per side) (\$104.76) -> Paint door or window opening - 2 coats (per s... (\$52.08)

Seal and paint door jamb/trim matches 2 coat painting of openings.

ORANGE | Paint door slab only - 2 coats (per side) (\$123.09) -> Paint door slab only - 2 coats (per side) (\$61.26)

Both items describe painting door slab 2 coats per side.

Labor Minimums Applied ↔ Labor Minimums Applied

status | A description (A\$) -> B description (B\$) [why]

BLUE | Mirror/shower door labor minimum (\$112.31) -> (-)

No matching item found for mirror/shower door labor minimum in Doc B.

BLUE | Heat, vent, & air cond. labor minimum (\$259.23) -> (-)

No matching item found for heat, vent, & air cond. labor minimum in Doc B.

BLUE | Window treatment repair (\$50.65) -> (-)

No matching item found for window treatment repair in Doc B.

ORANGE | Insulation labor minimum (\$156.86) -> Insulation labor minimum (\$216.51)

Both items describe insulation labor minimum work, with slightly different costs.

ORANGE | Cabinetry labor minimum (\$80.59) -> Cabinetry labor minimum (\$83.35)

Both items describe cabinetry labor minimum work, with slightly different costs.

Laundry Room ↔ Laundry Room

status | A description (A\$) -> B description (B\$) [why]

BLUE | Batt insulation replacement per LF - 4" - up to 2' tall (\$40.64) -> (-)

No specific match for insulation replacement in items_b.

BLUE | Concrete grinding (\$171.59) -> (-)

Concrete grinding does not have a direct match.

BLUE | HEPA Vacuuming - Light - (PER SF) (\$23.94) -> (-)

No HEPA vacuuming mentioned in items_b.

BLUE | Mortar bed for tile floors (\$220.42) -> (-)

No mortar bed or related flooring prep found in items_b.

BLUE | Grout sealer (\$55.34) -> (-)

Grout sealer not specifically listed in items_b.

BLUE | Door stop - wall or floor mounted (\$18.04) -> (-)

No door stop related work in items_b.

BLUE | Seal & paint door/window trim & jamb - (per side) (\$104.76) -> (-)

No clear direct match for trim painting.

BLUE | Door hinges (set of 3) and slab - Detach & reset (\$35.92) -> (-)

'Detach & reset door hinges' does not match with items_b.

BLUE | On site door prep. for full mortised hinges - Labor only (\$122.73) -> (-)

Door prep labor does not have equivalent in items_b.

BLUE | Mask wall - plastic, paper, tape (per LF) (\$52.51) -> (-)

Masking materials not specifically mentioned in items_b.

BLUE | Floor protection - plastic and tape - 10 mil (\$17.61) -> (-)

No floor protection match found in items_b.

BLUE | Content Manipulation charge - per hour (\$68.65) -> (-)

Content manipulation doesn't have an equivalent in items_b.

BLUE | Baseboard, drywall, insulation and ceramic tile floor... (-) -> (-)

No items in items_b describe removal during mitigation.

Room-by-room detail

run_id: 0f475b52-e256-4ad9-bc45-aa3ba480aa2a

green: 7 orange: 25 blue: 56

A total (matched): \$6,520.48 B total (matched): \$6,871.52

BLUE | Baseboard, drywall and ceramic tile flooring removed ... (-) -> (-)

No items in items_b describe removal during mitigation.

GREEN | 1/2" - drywall per LF - up to 2' tall (\$384.73) -> 1/2" - drywall per LF - up to 2' tall (\$381.05)

Matching 1/2" drywall per LF, up to 2' tall.

GREEN | Door opening (jamb & casing) - 32" to 36" wide - pain... (\$227.44) -> Door opening (jamb & casing) - 32" to 36" wid... (\$227.36)

Matching 'Door opening (jamb & casing)', paint grade.

GREEN | Interior door - Reset - slab only (\$16.53) -> Interior door - Reset - slab only (\$16.51)

Direct match for 'Interior door - Reset - slab only'.

GREEN | Washer/Washing machine - Remove & reset (\$71.65) -> Detach & Reset Washer/Washing Machine - Front... (\$71.64)

Remove & reset washer matches directly.

GREEN | Dryer - Remove & reset (\$55.24) -> Detach & Reset Dryer - Electric (\$55.23)

Remove & reset dryer matches directly.

ORANGE | Texture drywall - light hand texture (\$93.61) -> Texture drywall - light hand texture (\$147.79)

Matching 'Texture drywall - light hand texture' scope.

ORANGE | Seal/prime (1 coat) then paint (2 coats) the walls (\$479.12) -> Paint the walls and ceiling - one coat (\$276.74)

Seal/prime and paint vs paint the walls - one coat; partial match.

ORANGE | Tile floor covering (\$515.72) -> Tile floor covering (\$502.13)

Direct match for 'Tile floor covering'.

ORANGE | Baseboard - 3 1/4" (\$122.04) -> Baseboard - 3 1/4" MDF w/profile (\$118.03)

Both list 'Baseboard - 3 1/4"', match on baseboard.

ORANGE | Seal (1 coat) & paint (1 coat) baseboard (\$62.34) -> Paint baseboard - two coats (For replace base... (\$59.59)

Seal and paint baseboard vs paint baseboard.

ORANGE | Paint door slab only - 2 coats (per side) (\$123.09) -> Paint door slab only - 2 coats (per side) (\$61.26)

Paint door slab only - 2 coats, matches with lower cost.

ORANGE | Final cleaning - construction - Residential (\$18.08) -> Final cleaning - construction - Residential (\$17.63)

Final cleaning construction matches closely.

Living Room ↔ Living Room

status | A description (A\$) -> B description (B\$) [why]

BLUE | 1/2" - drywall per LF - up to 2' tall (\$18.12) -> (-)

No relevant match for drywall per LF found in document B.

BLUE | Seal/prime (1 coat) then paint (2 coats) the walls (\$1,035.30) -> (-)

No specific match for wall painting in document B.

BLUE | Baseboard - 3 1/4" (\$5.75) -> (-)

No match for baseboard installation in document B.

BLUE | Seal (1 coat) & paint (1 coat) baseboard (\$139.73) -> (-)

No specific match for baseboard painting in document B.

BLUE | Mask wall - plastic, paper, tape (per LF) (\$120.92) -> (-)

No specific match for masking listed in document B.

BLUE | Floor protection - plastic and tape (\$26.07) -> (-)

No direct match for floor protection in document B.

BLUE | Window drapery - hardware - Detach & reset (\$126.91) -> (-)

No mention of window drapery in document B.

BLUE | Content Manipulation (Bid Item) - Bid item to remove ... (\$0.00) -> (-)

No specific bid item match for piano removal in document B.

BLUE | Final cleaning - construction - Residential (\$134.20) -> (-)

Final cleaning not mentioned in document B.

ORANGE | R&R Carpet pad (\$282.98) -> Carpet pad - per specs from independent pad a... (\$12.39)

Item A refers to R&R of carpet pad which loosely matches B's specification on carpet pad.

ORANGE | Remove Carpet (\$100.53) -> Remove Carpet (Some carpet and pad was remove... (\$115.56)

Both items describe the scope of removing carpet.

ORANGE | Carpet (\$1,589.84) -> Carpet - per specs from independent carpet an... (\$2,290.14)

Both items reference providing new carpet, although B specifies independent analysis.

ORANGE | Content Manipulation charge - per hour (\$137.30) -> Contents - move out then reset - Large room (... (\$151.10)

A deals with hourly content manipulation; B covers moving contents including a piano.

Room-by-room detail

run_id: 0f475b52-e256-4ad9-bc45-aa3ba480aa2a

green: 7 orange: 25 blue: 56

A total (matched): \$6,520.48 B total (matched): \$6,871.52

Main Level ↔ Main Level

status | A description (A\$) -> B description (B\$) [why]

BLUE | Residential Supervision / Project Management - per hour (\$1,734.96) -> (-)

No related project management or supervision task found in Doc B.

BLUE | Megohmmeter check electrical circuits - average resid... (\$1,168.65) -> (-)

Electrical circuit check not mentioned in Doc B.

BLUE | Respirator - Half face - multi-purpose resp. (per day) (\$4.00) -> (-)

Respirator item not related to any current insurance items.

BLUE | Respirator cartridge - HEPA only (per pair) (\$43.95) -> (-)

No matching respirator cartridge item in Doc B.

BLUE | Add for HEPA filter (for canister/backpack vacuums) (\$115.11) -> (-)

HEPA filter addition not scoped in insurance list.

Stair Closet ↔ Stair Closet

status | A description (A\$) -> B description (B\$) [why]

BLUE | Door hinges (set of 3) and slab - Detach & reset (\$35.92) -> (-)

No specific match for detaching and resetting hinges and slab in items_b.

BLUE | On site door prep. for full mortised hinges - Labor only (\$122.73) -> (-)

No matching detailed labor for door hinge preparation.

BLUE | Interior door - Reset - slab only (\$16.53) -> (-)

Resetting door slab has no direct match in items_b.

BLUE | Paint door slab only - 2 coats (per side) (\$123.09) -> (-)

Painting door slab is not mentioned in items_b.

BLUE | Mask wall - plastic, paper, tape (per LF) (\$49.33) -> (-)

No matching protection/masking task in items_b.

BLUE | Floor protection - plastic and tape - 10 mil (\$11.63) -> (-)

Floor protection task does not directly translate to items_b scope.

BLUE | Final cleaning - construction - Residential (\$11.94) -> (-)

Final cleaning task does not match any item in items_b explicitly.

ORANGE | Carpet pad (\$21.29) -> Carpet pad - per specs from independent pad a... (\$1.23)

Both describe carpet pad work, with similar descriptions.

ORANGE | Carpet (15 % waste added for Carpet) (\$141.39) -> Carpet - per specs from independent carpet an... (\$54.10)

Both involve carpet replacement, matching the general carpet scope.

ORANGE | Content Manipulation charge - per hour (\$68.65) -> Contents - move out then reset - Small room (\$75.62)

Content manipulation is similar to moving contents out and resetting them.