-	/h					Project						
GENIUS										SUMMARY Subtotal Overhead	\$ 94,938.26 \$ 20,886.42	
E	STIMA	TE .						Total		Total Total	\$ 115,824.67	
n#	CSI	Description	Unit	Quantity	Wastage	Quantity w/wastage	Unit material cost	material	Unit Labor Cost	Labor	Total Item cost	Trade Cost
	_	PRELIMINARIES						cost		Cost		\$ 5,584
	1		EA	1	0%	1		0	178.707	178.707	178.707	\$ 5,584
		PERMIT SUPERVISION	EA	1	0%	1		0	1965.780	1965.780	1965.780	
		FINAL CLEANUP	EA	1	0%	1		0	536.122	536.122	536.122	
	1. 4	MOBILIZATION COST	EA	1	0%	1		0	1072.244	1072.244	1072.244	
		PROJECT OVERHEADS	EA	1	0%	1		0		0.000	0.000	
		FEE (Architect & Engineer)	EA EA	1	0%	1		0	491.445	0.000 491.445	0.000 491.445	
		TEMPERORY CONTROL & ACTIVITIES BONDS	EA	1	0%	1		0	1340.305	1340.305	1340.305	
		B DRY WALLS WITH INT.FRAMING AND INSULATIO										\$ 72,000.
		1st Floor Walls & Drywall										
	3.1		LF	86	00/	C.F.	40.00	700 ***	20.010	1945 505	2054 740	
	3. 2		EA SF	65 860	0% 5%	65 903	10.92 1.00	706.105 902.650	20.810 0.400	1345.635 361.381	2051.740 1264.031	
	3. 4		SF	860	5%	903	1.36	1228.927	0.600	542.071	1770.997	
	3. 5		SF	860	5%	903	1.49	1345.470	0.920	831.175	2176.645	
	3. 6		SF	860	5%	903	2.83	2557.953	2.138	1930.433	4488.386	
	3. 7	5/8" Gypsum Wall Board	SF	860	5%	903	0.33	297.990	0.680	614.347	912.337	
	3. 9	Mall Translation (401 0ll LIT)	LF	51								
	3. 10	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	EA	38	0%	38	10.92	418.737	20.810	797.993	1216.730	
		1 2" X 4" Sill Plate	LF	51	5%	54	1.09	58.477	2.081	111.440	169.916	
	3. 12	² 5/8" Gypsum Wall Board	SF	1020	5%	1071	0.33	353.430	0.680	728.644	1082.074	
	3. 13	3	LF	8			1.15					
	3. 14		EA	6	0%	6	10.92	65.684	20.810	125.175	190.860	
	3. 15		LF	8	5%	8	1.09	9.173	2.081	17.481	26.654	
	3. 16	5/8" Fire Backer Wall Board	SF	160	5%	168	0.38	64.470	0.680	114.297	178.767	
	3 17											
	3. 18	Wall Type Existing 3 5/8" Gypsum Wall Board	SF	8900	5%	9345	0.33	3083.850	0.680	6357.777	9441.627	
		5/6 Gypsuiii Wali Boalu										
		Wall Type Existing			U		109					
	3. 20	5/8" Cement Backer Board	SF	250	5%	ESTIM	1.10	289.570	0.920	241.621	531.191	
		2nd Floor Wall & Drywall										
		Wall Type Exterior (10'-0" HT)	LF	210								
	3. 22		EA	158	0%	158	10.92	1724.211	20.810	3285.853	5010.063	
	3. 23	R-19 Batt Wall Insulation 1" Rigid Insulation	SF SF	2100 2100	5% 5%	2205 2205	1.00 1.36	2204.146 3000.867	0.400	882.441 1323.662	3086.587 4324.529	
	3. 25		SF	2100	5%	2205	1.49	3285.450	0.920	2029.614	5315.064	
	3. 26	Siding To Match Exisitng	SF	2100	5%	2205	2.83	6246.164	2.138	4713.849	10960.013	
	3. 27	5/8" Gypsum Wall Board	SF	2100	5%	2205	0.33	727.650	0.680	1500.150	2227.800	
	3. 28	³ Wall Type Exterior (4'-0" HT)	LF	12								
		2x4 Wood Stud Wall @ 16" O.C.	EA	9	0%	9	8.74	78.821	16.648	150.210	229.031	
	3. 30		SF	48	5%	50	1.00	50.380	0.360	18.153	68.534	
	3. 31	1" Rigid Insulation	SF	48	5%	50	1.36	68.591	0.600	30.255	98.846	
		2 3/4" Exterior Plyood Sheathing	SF	48	5%	50	1.49	75.096	0.840	42.357	117.453	
		Siding To Match Existing	SF SF	48 48	5% 5%	50 50	2.83 0.33	142.769 16.632	2.138 0.600	107.745 30.255	250.515 46.887	
	J. J4	5/8" Gypsum Wall Board	31	48	3%	30	0.33	10.032	0.000	30.233	40.55/	
	3. 35	Wall Type Exterior (4'-6" HT)	LF	23								
	3. 36		EA	17	0%	17	8.74	151.074	16.648	287.903	438.977	
	3. 37		SF	104	5%	109	1.00	108.633	0.360	39.143	147.775	
		3 1" Rigid Insulation	SF	104	5%	109	1.36	147.900	0.600	65.238	213.137	
		3/4" Exterior Plyood Sheathing	SF SF	104 104	5% 5%	109 109	1.49 2.83	161.926 307.847	0.840 2.138	91.333 232.325	253.258 540.172	
		Siding To Match Exisitng S/8" Gypsum Wall Board	SF	104	5%	109	0.33	35.863	0.600	65.238	101.100	
		Wall Type Interior (8'-0" HT)	LF	34								
		3 2x4 Wood Stud Wall @ 16" O.C.	EA	26	0%	26	10.92	279.158	20.810	531.995	811.153	
		2" X 4" Sill Plate	LF SF	34 544	5% 5%	36 571	1.09 0.33	38.984 188.496	2.081 0.680	74.293 388.610	113.278 577.106	
	J. 45	5 5/8" Gypsum Wall Board	31	J44	3/0	3/1	0.55	100.430	0.060	J00.01U	3//.100	
	3. 46	Wall Type Interior (9'-0" HT)	LF	125								
		7 2x4 Wood Stud Wall @ 16" O.C.	EA	94	0%	94	10.92	1026.316	20.810	1955.865	2982.180	
	3. 48		LF SF	125 2250	5% 5%	131 2363	1.09 0.33	143.325 779.625	2.081	273.137	416.462 2386 928	
	J. 49	5/8" Gypsum Wall Board	21-	2250	5%	2303	U.33	779.625	0.680	1607.303	2386.928	
	3. 50	Wall Type Interior (9'-0" HT)	LF	62			1.					
		2x4 Wood Stud Wall @ 16" O.C.	EA	47	0%	47	10.92	509.053	20.810	970.109	1479.162	
	3. 52	2" X 4" Sill Plate	LF	62	5%	65	1.09	71.089	2.081	135.476	206.565	

	SF SF	1116 1116	5% 5%	1172 1172	0.33 0.41	386.694 485.198	0.680 0.680	797.222 797.222	1183.916 1282.421		
	SF	1536	5%	1613	0.33	532.224	0.680	1097.252	1629.476		
4 CEILINGS				TO THE						\$	12,478.57
Cellar Floor Ceiling											
1 5/8" Gypsum Board Ceiling	SF	3551	5%	3729	A 0.34	1272.368	0.800	2984.331	4256.699		
	_										
1st Floor Ceiling											
3 Soffit (Assume)	SF	391	5%	411	0.33	135.738	0.740	303.959	439.697		
5/8" Gypsum Board Ceiling	SF	1936	5%	2033	0.34	693.693	0.800	1627.053	2320.746		
6 TAPING										\$	4,874.74
1 TAPING OF DRYWALLS	LF	7402	5%	7772	0.01	93.265	0.400	3110.394	3203.660		
2 TAPING OF GYPSUM BOARD CEILING	LF	3861	5%	4054	0.01	48.649	0.400	1622.431	1671.079		
					TOTAL		A 50 705 10				
					TOTAL MATERIAL COST TOTAL COST						
							\$ 94,938.26				
					INSURANCE		\$ 4,746.91				
					TOTAL BID		\$ 14,240.74				
	Cellar Floor Ceiling 1 5/8" Gypsum Board Ceiling 2 5/8" Gypsum Board Ceiling 3 Soffit (Assume) 2nd Floor Ceiling 4 5/8" Gypsum Board Ceiling 6 TAPING	3/8 cypsum wait board 3/8 "Water Resistance Wall Board 55 Wall Type Existing 55 S/8" Gypsum Wall Board 57 Cellar Floor Ceiling 58" Gypsum Board Ceiling 58" Gypsum Board Ceiling 59" GYPSUM BOARD G	3/8 cylysum wall board 3/8 cylysum wall board 5/8 wall Type Existing 5/8 wall Type Existing 5/8 cylysum Wall Board 5/8 cylsum Wall Board 5/8 cylsum Wall Board 5/8 cylsum Wall Board 5/8 cylsum Board Celling 5/8 cylsum C	System S	1116 5% 1172	SF 1116 5% 1172 0.41	SF 1116 S% 1172 0.41 485.198	Mail Type Existing SF 1116 S% 1172 0.41 485.198 0.680	Specific Specific	SF 1116 5% 1172 0.41 485.198 0.680 797.222 1282.421	Mail Type Existing SF 1116 S% 1172 0.41 485.198 0.680 797.222 1282.421