0.1 Tasks

0.1.1 ROSA_tcbDelete

Prototype: unsigned int ROSA_tcbDelete(tcb *taskHandle);

Description: Removes a task from kernel

Parameters: tcb *taskHandle

- a pointer to the TCB block to be deleted

Return: unsigned int

- 1: Successful- 0: Unsuccessful

Motivation: Required by the customer

0.1.2 ROSA_tcbCreate (modified)

Prototype: unsigned int ROSA_tcbCreate(tcb *taskHandle, char *id, void *taskFunc, un-

signed int taskPrio, int *stack, int stackSize);

Description: Creates a TCB entry according to the given parameters

Parameters: tcb *taskHandle

- A pointer to the TCB block to be created

char *id

- A identification for the TCB block of length NAMESIZE (default NAMESIZE

= 4)

void *taskFunc

- A pointer to the function which are to be executed by the task

unsigned int taskPrio - The task priority

int *stack

- A pointer to the task stack area

int stackSize

- The maximum allowed stack for this task

Return: unsigned int

Successful
Unsuccessful
Out of Memory
Task Handle is busy

Motivation: Includes additional parameter Task priority