

INCIDENT REPORT - September 02, 2023

Title: Q3 pressure trip incident

Equipment Tag: C-101 (Main Air Compressor)

Reporter: Alan Walker

Severity: High

Description:

At 14:00 hours, C-101 experienced a sudden surge in discharge pressure, triggering the automated safety shutdown. The incident resulted in a 4-hour production halt.

Root Cause Analysis:

Initial findings suggest a failure in the primary pressure relief valve due to unexpected particulate buildup.

Follow-up Actions:

Immediate replacement of the relief valve and a full annual inspection of C-101 are required before restarting operations.