

## INSPECTION FINDING - September 05, 2023

Title: Post-trip internal inspection

Equipment Tag: C-101 (Main Air Compressor)

Inspector: Jane Smith

### Findings:

Following the Q3 pressure trip incident, an internal boroscope inspection was performed on the compressor.

No catastrophic damage was found to the rotor blades. However, the primary seal showed signs of thermal degradation.

### Recommendations:

Replace the primary seal during the next scheduled maintenance window.

Update the SOP to include more frequent monitoring of the intake filters.