
pickup
drop
Motor command (–)
0.0
0.2
0.4
0.6
Step statistic (–)
0.1
0.0
−0.1
0
50
100
150
200
Time since arming (s)
mean motor command
cruise-phase signal
Pelt change point
threshold detection
threshold ±0.05