

SFP MODULE DIAGNOSTIC ANALYSIS REPORT

=====

Analysis Date: 2026-09-04 04:49:16

Switches Analyzed: sw-A, sw-B

Interfaces: et-0/0/48, et-0/0/49, et-0/0/50, et-0/0/51

Total Samples: 2421


Total Issues Found: 9

CRITICAL ISSUES (9):


- sw-A et-0/0/48: FEC uncorrected errors: 552
- sw-A et-0/0/48: Link went DOWN 1 times
- sw-A et-0/0/50: FEC uncorrected errors: 75481
- sw-A et-0/0/51: RX power LOW ALARM triggered
- sw-B et-0/0/48: FEC uncorrected errors: 652781
- sw-B et-0/0/48: Link went DOWN 1 times
- sw-B et-0/0/49: FEC uncorrected errors: 1582
- sw-B et-0/0/50: FEC uncorrected errors: 1288
- sw-B et-0/0/50: RX power LOW ALARM triggered

sw-A - SFP Diagnostics


Received Optical Power




Transmitted Optical Power







Laser Bias Current



Module Temperature




sw-A - Error Metrics




sw-B - SFP Diagnostics


Received Optical Power




Transmitted Optical Power



Laser Bias Current



Module Temperature



sw-B - Error Metrics

