



Damage Assessment Report

2 damages assessed

VEHICLE

MAKE

Daihatsu

MODEL

Cuore

YEAR

2007

BODY TYPE

hatchback

TOTAL ESTIMATE

32,708 PKR

Range 15,135 – 50,281 PKR

2 estimated

DAMAGE SUMMARY

#	DAMAGE	PANEL	SEVERITY	DECISION	METHOD	COST
1	Broken Lamp	Rear Left Light	—	Replace	—	5,000–30,000 PKR
2	Scratch	Rear Bumper	Moderate	Repair	Spot Paint	15,208 PKR

DAMAGE PHOTOS



Broken Lamp

Rear Left Light

Replace

5,000–30,000 PKR



Scratch

Rear Bumper

Moderate

Repair

Spot Paint

15,208 PKR

Range 10,135 – 20,281 PKR