
Cube placement — Diffusion policy training
Training loss (per step)
Training loss (100-step moving average)
Validation loss
Diffusion loss (log scale)
$10^{0}$
$10^{-1}$
0.0671
0.0436
0
250
500
750
1000
1250
1500
1750
2000
Training step
2,000 steps · batch size 8 · 31 training / 3 validation episodes
Validation uses 64 sampled frames; loss does not measure robot success rate.