

RAGHAV ENGINEERING

ValveTrack — Job Card System

A plain-language guide to creating, processing, and closing a Job Card

This guide explains how to use the Job Card (JC) module step by step — from raising a new job to closing it after dispatch. It is written for everyone who touches a Job Card: **Admin, Operators, Engineers, QA, Accounts**, and **Management**. No technical background is needed.

What you'll find inside:

- What a Job Card is, and the journey it takes from creation to closing
- Who is allowed to do what — a role-by-role reference
- Step-by-step instructions for every section of a Job Card
- Why the system sometimes won't let you move forward ("gates") and how to clear them
- How to generate and download the Job Card PDF
- A one-page cheat sheet you can pin near your workstation

1. What is a Job Card?

A **Job Card (JC)** is the digital version of the paper traveller that used to follow a job around the shop floor. Every job — welding, machining, overlay, or cladding — gets one Job Card. It records everything about that job in one place: customer and material details, the welding parameters used, heat-treatment (PWHT) results, inspection (NDE) results, air test results, final dimensions, dispatch details, and sign-offs.

Instead of a single sheet of paper that can be lost, smudged, or filled in out of order, the Job Card is a live record that everyone — welder, QC inspector, stores, accounts — updates as the job moves through the shop. At the end, the system generates a clean, complete PDF of the whole job that looks just like the paper form your customers are used to seeing.

Each Job Card gets a unique number automatically when it is created (for example **RRE-2026-0014**) — you never need to write this by hand.

2. The Big Picture — How a Job Card Moves

A Job Card moves through a fixed sequence of **statuses**. Think of status as "which stage of the journey the job is currently at." You move a Job Card to the next status by clicking a labeled button at the top of the Job Card page — nothing advances automatically, so the status always reflects a deliberate decision by someone on the team.

#	Status name in system	What it means	Button you click
1	Created	Job Card raised with basic details	(automatic on save)
2	WPS Pending	Waiting for the welding procedure (WPS) to be requested	"Request WPS"
3	WPS Uploaded	The WPS document has been uploaded	(after upload)
4	WPS Approved	QA has approved the WPS as correct for this job	(QA approval)
5	Process Assigned	Job handed to the shop floor for work to begin	"Assign to Process"
6	In Process	Welding / machining / overlay work is underway	"Start Processing"
7	Process Complete	All shop-floor work is finished	"Mark Process Complete"
8	Reports Pending	Waiting for inspection reports (PMI / Dimension / Overlay)	"Request Reports"
9	Reports Complete	All required inspection reports are in and approved	"Mark Reports Complete"
10	Dispatch Ready	Job has passed every check and can be packed for dispatch	"Mark Dispatch Ready"
11	Dispatched	Job has physically left the factory	"Mark as Dispatched"
12	Accounts Processing	Billing / invoicing is being handled	"Send to Accounts"
13	Closed	Job is fully complete — nothing further needed	"Close Job Card"

On Hold is a special side-state. An Admin can place any Job Card on hold at any point (for example, if the customer pauses an order) and resume it later from the same stage it left off. Only Admin can place or resume a hold.

3. Who Can Do What

The system checks your role before letting you take an action — so you'll only ever see buttons for things you're allowed to do. If a button you expect is missing, it usually means someone else on the team needs to do that step, not that something is broken.

Action	Admin	Operator	Engineer	QA	Accounts	Mgmt.
Create a Job Card	Y	Y	Y	Y	Y	Y
Request / upload WPS	Y	Y	-	Y	-	-
Approve WPS	Y	-	-	Y	-	-
Assign / run process (welding, machining)	Y	-	Y	-	-	-
Enter NDE / LPT results	Y	-	-	Y	-	-
Enter Air Test results	Y	-	Y	Y	-	-
Enter PMI / Dimension / Overlay reports	Y	-	-	Y	-	-
Production sign-off	Y	-	Y	-	-	-
QC sign-off	Y	-	-	Y	-	-
Stores sign-off	Y	-	-	-	Y	-
Mark Dispatch Ready / Dispatched	Y	-	-	-	-	-
Accounts / billing / Close Job Card	Y	-	-	-	Y	-
Place / resume On Hold	Y	-	-	-	-	-

"Admin" can perform every action as a safety net (for example, to unblock a job when the usual person is unavailable). Everyone else is limited to their own area of responsibility.

There is also a **Customer** role for an external client portal — customers only ever see a read-only, simplified view and cannot edit anything.

4. Creating a New Job Card

From the Job Cards list page, click **"New Job Card"** and fill in:

- 1 **Client** — pick an existing customer, or add a new one on the spot.
- 2 **Job Details** — NBDN Number, PO Number, Description, Drawing No., Heat No., Part No., Quantity, and the date the job was received. Fields marked with an asterisk (*) are required.
- 3 **Process Types** — tick every process this job involves: Welding, Machining, Cladding, and/or Overlay. You can tick more than one.

Click **Save**. The system instantly assigns the Job Card number and status "Created" — you're ready to move to the next section.

You don't have to fill in every optional detail on day one. Basic Info can be saved with just the required fields, and the rest — like Buyer, Material Grade, Ring details — can be added later under "Advanced Details" on the Job Card page.

5. Filling In the Job Card, Section by Section

Open any Job Card to see its detail page. Scroll down and you'll find each part of the paper traveller as its own section, in this order:

#	Section	What you enter here
1	Advanced Details	Product Group, Buyer, Material Code, Valve Size/Class, Base & Overlay Material, Ring, Regularization, MPI/RT No., Punching Details, and any other free-text notes.
2	WPS	The Welding Procedure Specification this job must follow, and its approval status.
3	Process Execution	One entry per welding/machining/overlay run: welder name, weld date, consumable used (brand, AWS class, size, batch, mfg/expiry date), and the As-per-WPS vs. Actual readings (pre-heat, inter-pass, post-heat, amps, volts, travel speed, gas flow, feed rate, polarity).
4	NDE / LPT	Non-destructive examination results (e.g. liquid penetrant testing), the chemicals used (penetrant, cleaner, developer) with batch numbers and expiry dates.
5	Air Test & Inspection	Pressure test details — tester name, pressure applied, duration, pass/fail result.
6	PWHT Summary	Heat-treatment (stress-relieving) cycle: chart number, loading/soaking/unloading temperatures and times.
7	PMI Report	Positive Material Identification results, where required.
8	Dimension Report	Final measured dimensions against drawing tolerances — including the machining grid (Milling / Soft Machining / Hard Facing measurements).
9	Overlay Welding Report	Details specific to overlay/cladding jobs.
10	Customer Dossiers	Bundled document packs prepared for the customer.
11	All Documents	Every file attached to this Job Card in one place.
12	Production Sign-Off	Three separate sign-off blocks — Production, QC, and Stores — each signed by the right role.
13	Dispatch	DC Number, dispatch date, vehicle details.
14	Accounts	Billing / payment status.

You don't fill these in all at once — each role adds their part when the job reaches their stage. A welder fills in Process Execution when the job is "In Process"; QA fills in NDE and PWHT once welding is done; stores completes Dispatch once everything else is signed off.

6. Moving the Job Card to the Next Stage

At the top of every Job Card page you'll see the current status badge, how many days it has been at that stage, and one or more buttons for the next allowed action. Click the button that matches what you've just finished doing — for example, once all welding readings are entered and the job is physically done, click **"Mark Process Complete"**.

You can only click the buttons your role is allowed to use (see the role table in Section 3). If you don't see a button, the job is waiting on someone else.

7. The Gates — Why the System Sometimes Says "Not Yet"

ValveTrack won't let a Job Card skip a required check, even by accident. These checks are called **gates**. If you click a status button and it's blocked, here's what to look for:

Trying to reach...	The system first checks that...
Reports Complete / Dispatch Ready / Dispatched (welding, cladding, or overlay jobs)	At least one inspection report — PMI, Dimension, or Overlay — has been submitted or approved.
Dispatch Ready / Dispatched	The WPS for this job has been approved, and if the job requires heat treatment, the PWHT run has also been approved.
Closed	A dispatch record exists for the job, and (unless you are Admin) the payment status shows "received."

If you hit a gate, the fix is almost always to go back and finish the section it's asking about — upload/approve the missing report, get the WPS or PWHT approved, or confirm payment with Accounts. Admin can override the payment check in urgent cases, but should not skip quality gates like WPS/PWHT/inspection approval.

8. Generating the Job Card PDF

Once you're ready to produce the printable Job Card — for the customer, for your records, or for dispatch paperwork — click **"Download Job Card PDF"** at the top of the Job Card page.

- 1 The system pulls together everything entered so far — basic info, welding readings, PWHT, NDE, air test, dimensions, dispatch, and sign-offs.
- 2 It builds a clean PDF that mirrors the layout of the original paper Job Card.
- 3 The PDF opens automatically in a new browser tab, ready to view, print, or save.

You can generate the PDF at any stage — it will simply show whatever has been filled in so far, with blank sections left empty. Generating it again after adding more data always produces an up-to-date copy; older copies are kept under "All Documents" for reference.

9. One-Page Cheat Sheet

Pin this near your workstation as a quick reminder.

Status journey:

Created → WPS Pending → WPS Uploaded → WPS Approved → Process Assigned → In Process → Process Complete → Reports Pending → Reports Complete → Dispatch Ready → Dispatched → Accounts Processing → Closed

(On Hold can be entered from, and resumed to, any stage — Admin only.)

Before you click "next stage", check:

- Is every field in the current section filled in and saved?
- If moving to Reports Complete or later: is at least one inspection report (PMI / Dimension / Overlay) submitted?
- If moving to Dispatch Ready or later: is the WPS approved? Is PWHT approved (if required)?
- If closing the job: does a dispatch record exist, and has payment been confirmed?

Who to ask if you're stuck:

Problem	Talk to
WPS not yet approved	QA
Inspection report (PMI/Dimension/Overlay) missing or unapproved	QA
PWHT run missing or unapproved	Engineer / QA
Can't mark dispatched	Admin
Payment status not updated	Accounts
Wrong role / missing button	Admin