TG MEDICAL(F3), TOP QUALITY, TOP EFFICIENCY, GOOD HEALTH, SAFETY FIRST & BE HONEST






## Non Removable Dirt


Root Cause and Corrective/Preventive Actions


Presentation by Mr. Philip Thomas Factory 3


#### Statistical Data on NRD Defect


20% customer complaints received in year 2010 for TG Group come from NRD/Stain defect












# Corrective & Preventive Action

Check Dipping Tank

Dipping Tank including <u>Coagulant Tank</u>, <u>Latex</u> <u>Tank</u>, <u>Polymer Tank</u>, <u>Cornstarch Tank</u>

- 1. **Ensure No Dirt Floating** on the surface of dipping tank.
- 2. Installation of proper and sufficient filter.
- 3. Modification of dripping tray to minimize dirt.
- 4. Modification of former track to avoid dirt fall.
- 5. **Usage of stainless steel rod** to guide former in all dipping tank.



# Corrective & Preventive Action


Check Dipping Tank

Check Open Channel

Check Stripping Area

- 1. Frequent cleaning at autostripping area
- 2. Basket was placed at autostripping area.
- 3. Installation of moisture and oil separator for compressed air line.







## CONCLUSION

In order to prevent the customer's complaint on NRD, all departments had implemented the preventive actions.

## THANK YOU