TOP GLOVE SDN. BHD

WORK INSTRUCTION

Production Process Control Testing: Total Solid Content Test-Cornstarch

Purposes/Function/Objective

- To determine total solid content of cornstarch used in manufacturing process.

<u>Materials/ Chemicals/</u> <u>Tools/Equipment</u>

- 1) Analytical Balance.
- 2) Desiccators
- 3) Oven 150 °C

Specification

Calculation; % of TSC :- C - A x 100 %

В

Where is;

- A = Weight of double ring Filter paper.
- B = Weight of sample, g.
- C = Weight of dried filter paper, g.

Form/s

- LA/F05

References:

- nil





Weigh the filter paper.
(A)



Weigh 5.0 g cornstarch solution into beaker cover with filter paper. (B)



Dry the filter paper at 150°C for 45 minutes.



Cool down the filter paper in desiccator for 20 minutes.



Weigh the dried filter paper (C)

6 Calculation:

<u>C - A</u> x 100 %

Where:

A = Weight of double ring filter paper.

B = Weight of sample, g

C = Weight of dried filter paper, g.

Prepared by:	Verified by:	Approved by:
Noor Azura Binti Azman	Al-Fadilah Mohamad	Noor Akilah Saidin
QA/MQC Asst Supervisor	QA Executive II	QA Deputy General Manager

(Effective Date: 02/05/2011)