TOP GLOVE SDN. BHD

WORK INSTRUCTION

Production Process Control Testing: Total Solid Content Test - Latex

Purposes/Function/Objective

Procedures

- To determine the total solid content in latex used in manufacturing process.

Materials/ Chemicals/

Tools/Equipment

- Natural Rubber Sample
- 2. Nitrile Butadiene Rubber
- 3. Petri dish
- 4. Oven 150 °C
- 5.Cylinder
- 6.Spatula
- 7. Analytical balance
- 8 .Timer

Specification

TSC Calculation:

% of TSC = $\underline{\text{C-A X } 100\%}$

В

- A: Weight of petri dish
- **B:** Weight of latex sample,g
- C: Mass of weighing petri dish+dried sample, g

Forms:

- LA/F05

References:

- nil



Tare analytical balance



Place sample in desiccator for two minutes



Weigh aluminium foil and record as (A)



Reweigh sample and record as (C)



Weigh 0.5 g sample and record as (B)



Dry sample into oven (150°C) for 20 minutes

7

TSC Calculation:

% of TSC = $\frac{\text{C-A X } 100\%}{\text{B}}$

A: Weight of aluminium foil

B: Weight of sample

C: Weight after Drying

Record in the inspection form

Prepared by:	Verified by:	Approved by:
Noor Azura Binti Azman	Al-Fadilah Mohamad	Noor Akilah Saidin
QA/MQC Asst Supervisor	QA Executive II	QA Deputy General Manager

(Effective Date: 02/05/2011)