Release Notes for AT32F403A_407 Firmware Library Drivers

V2.0.7-2025/04/25

1. Updated RTC counter value read process.
2. Updated Flash driver and optimized process.
3. Added gpio_bits_toggle function.

V2.0.6-2024/12/13

1. Updated CAN driver.
2. Updated Flash driver.
3. Updated some notes.

V2.0.5-2024/08/08

1. Updated the “i2c_flag_clear” and “i2c_init” function.
2. Updated some notes.

V2.0.4-2024/01/05

1. Fixed the IAR7.4 compilation warning issue of some drivers.
2. Optimized EMAC PTP driver.

V2.0.3-2023/10/26

1. Added the “interrupt_flag_get” function to each of the IP sections.
2. Optimized system clock switching process.

V2.0.2-2023/08/04

1. Added CRC polynomial support.
2. Added “flash_spim_dummy_read” and “flash_spim_mass_program” functions.
3. Updated “adc_ordinary_channel_set” and “adc_preempt_channel_set” functions.
4. Updated some notes.

V2.0.1-2023/02/16

1. Updated the value of EMAC_MAX_PACKET_LENGTH to 1524.

V2.0.0-2022/11/18

1. Updated the “xmc_ext_timing_config” function.
2. Updated the default configuration of CRM_HICK48_NODIV when HICK is selected as PLL clock source.