

Noah MATLAB Example

Example Student

8 October 2026

Contents

Transient heat transfer	1
Input data	1
Command-window output	1
Symbolic result	1
Table output	1

Transient heat transfer

Input data

```
1 h = 20; % W/(m^2 K)
2 k = [0.042 0.032 0.040];
3 rho = [85 80 200]; % kg/m^3
4 Bi = h .* 0.005 ./ k;
```

Command-window output

```
Bi =
    2.3810    3.1250    2.5000
```

Symbolic result

```
tau = rho*cp*V/(h*A)
```

Table output

Material	Biot number
SAN	2.381
PET	3.125
PVC	2.500