

CENTRAL SCHOOL TRANSITION PLAN - Scenario #3			
Remain in the building and invest in repairs as needed over the next 2.5 years.			
The difficulties experienced this fall at Central School were as a result of specific incidents.			
1	Southwing roof and drain failure. The entire roof area has received a roofing cap sheet installed in asphalt with the installation of 2 new roof drains. It is highly unlikely that this roof area will leak again over the next 2.5 years.		
2	West side classroom flooding resulting from higher than normal rainfall & poor stormwater control from adjacent residential property renovation & addition. No additional flooding has occurred in this area following the storm drainage renovations performed last month and again we continue to receive higher than normal rainfall.		
3	Main hallway floor buckling and room 107 floor buckling. It remains undetermined if these items are related; however, there have been 2 independent structural engineers to investigate these incidents and state that the building appears structurally sound. An investigation of these events resulted in us finding that the hallway and cafeteria floors have buckled before years ago. You can readily see the hallway tile patch and apparently the entire cafeteria floor was replaced approximately 20 years ago.		
4	The educational and work environment of the building have been found to pose no immediate health impact to building occupants. We have communicated openly with building staff and provided the full report from the environmental engineer supporting the moisture remediation in the building. An occupational physician is currently reviewing the report and if necessary will investigate further the occupational impact, if any, of working in Central School.		
5	Current Central School PI Expenditures To Date:		
	Russell Flooring	Room 126 carpet install	\$35,050
	Paul Davis Restoration	Mold remediation cleaning	\$13,958
	Relmec	Roof drains	\$6,060
	Geotech Services, Inc.	West Exterior Drainage Repair	\$20,265
	JP Consulting	Asbestos remediation, project management	\$1,153
	Stephen J. Sebesta & Associates	Indoor Environmental Consulting Services	\$2,012
	G & T Maintenance Inc.	2500 sq ft of roofing & 2 roof drains	\$41,800
	Aramco	Dehumidifiers	\$3,145
		Total	\$120,297
6	Over the next 2.5 years the school district will continue to invest in the necessary facility repairs to keep the building operational. As is the case with all 4 of our elementary schools expenditures will be prioritized to insure the health and wellbeing of all building occupants. It is anticipated that the school district may invest approximately \$50,000 over the next 2.5 years in the areas of HVAC, sewers, roofing, masonry and other general facility repairs at Central School		