

Taylor Consulting Group, LLC
PO Box 1570
Mentor, OH 44061

Phone: 440-840-9019
Fax: 440-209-9841
Email: gtaylor@tcgroupdesign.com



February 18, 2025

Mr. Brian Koss
Facilities & Safety Coordinator
Brecksville-Broadview Heights City School District
6638 Mill Road
Brecksville, OH 44141

RE: 2025 Roof Replacement Project
Middle School (Roof Sections 20 & 27, Alternates 5 and 15)

Dear Mr. Koss:

Enclosed please find a bid evaluation report and recommendation for Brecksville-Broadview Heights City School District, Middle School Roof Replacement Project.

Should you require clarification or need additional information, please contact me at your earliest convenience.

Sincerely,

A handwritten signature in black ink, appearing to read 'Gregory R. Taylor', is written over a light gray rectangular background.

Gregory R. Taylor, RRC

GRT/ct

Enclosure

BID EVALUATION REPORT & RECOMMENDATION

PROJECT: Brecksville-Broadview Heights City School District
2025 Roof Replacement Project
Middle School (Roof Sections 20 & 27, Alternates 5 & 15)

BID OPENING: February 14, 2025, 12:00 p.m.

A total of six bids were received for the Brecksville-Broadview Heights City School District, Middle School Roof Replacement Project. The bids ranged from \$467,000.00 to \$632,101.00.

The lowest responsive bid of \$467,000.00 for Base Bid Item 1 and Alternate Bid Items 1A and 1B was submitted by Ramp Construction Company, Inc. The low bid is within the estimated project construction budget of \$514,349.00.

Matthew Maletta, Job Site Superintendent, Ramp Construction Company, Inc. was interviewed. Mr. Maletta verified he examined and carefully studied the Contract Documents and other related data identified in the Bidding Documents. Mr. Maletta confirmed he does not consider further examinations, investigations, explorations, test, studies, and data are necessary for the performance of the Work at the Contract Price, within the contract times, and in accordance with the other terms and conditions of the contract Documents. He verified there were no conflicts, errors, ambiguities, or discrepancies discovered in the Contract Documents. The Contract Documents are generally sufficient to indicate and convey understanding of all terms and conditions for performance and furnishing of the Work.

My recommendation is to award a contract to Ramp Construction Company, Inc. as follows:

Ramp Construction Company, Inc.

Bid Item 1

Middle School Roof Replacement
(Roof Sections 20 & 27)

\$427,000.00

Alternate Bid Item 1A (ADD)

Middle School Roof Replacement
(Roof Section 5)

27,000.00

Alternate Bid Item 1B (ADD)

Middle School Roof Replacement
(Roof Section 15)

13,000.00

TOTAL CONTRACT: \$467,000.00

UNIT COST ITEMS:

The add/deduct unit costs for each bid item listed below provide flexibility during the construction phase of this project, to either direct the Contractor to perform additional work items with predetermined fixed costs that are captured in the competitive environment, or to complete less work than the base bid allowances and provide a cost credit.

Base Bid Item 1: Roof Replacement – Middle School (Roof Sections 20 & 27, Alternates 5 & 15)
Division 7-Thermal & Moisture Protection
SECTION 07530-FULLY ADHERED 60 mil EPDM

Description	Estimated Quantity	Unit Price	/	Unit of Measure	Extension
Replacement of deteriorated 2" x 6" wood nailers matching the configuration of existing wood nailers.	225 LF	\$3.00	/	Lineal Foot	\$675.00
Replacement of deteriorated metal decking matching configuration of existing metal deck.	500 SF	\$20.00	/	Square Foot	\$10,000.00
Replacement of deteriorated 2" x 8" wood nailers matching the configuration of existing wood nailers.	225 LF	\$4.00	/	Lineal Foot	\$900.00
Replacement of deteriorated existing roof drains with new 4" cast roof drains including insulated leaders tied into existing leaders.	1 Each	\$1,500.00	/	3 - Total	\$4,500.00
Securement of existing loose wood nailers with mechanical fasteners (staggered 6" oc.).	600 LF	\$1.50	/	Lineal Foot	\$900.00
Installation of walkway pads	150 LF	\$20.00	/	Lineal Foot	\$3,000.00
Engineers Allowance	Lump Sum	\$3,500.00	/	Lump Sum	\$3,500.00
SUBTOTAL OF UNIT PRICE EXTENSIONS:					<u>\$23,475.00</u>

ALTERNATE BID ITEM 1A (ADD): Roof Section 5

UNIT PRICES (Include the subtotal of Unit Price extensions in the Alternate Bid 1A below. Unit prices shall be used solely for the purpose of determining the adjustment to the Contract Sum for differences between the estimated quantities on the Bid Form and the actual quantities provided. The Contractor's Fee on account of Unit Price Work is Included in the Alternate Bid1A and not in the Unit Price.)

Description	Estimated Quantity	Unit Price	/	Unit of Measure	Extension
Replacement of wet or deteriorated BUR and underlying insulation to match thickness of surrounding roof.	450 SF	\$10.00	/	Square Foot	\$4,500.00
Replacement of deteriorated 2" x 6" wood nailers matching the configuration of existing wood nailers.	100 LF	\$3.00	/	Lineal Foot	\$300.00
Replacement of deteriorated 2" x 8" wood nailers matching the configuration of existing wood nailers.	100 LF	\$4.00	/	Lineal Foot	\$400.00
Replacement of deteriorated existing roof drains with new 4" cast roof drains including insulated leaders tied into existing leaders.	1 Each	\$1,500.00	/	1 - Total	\$1,500.00
Cleaning of existing drain and leader. Removal of BUR Pitch from drain and leader.	1 Each	\$500.00	/	1 - Total	\$500.00
Installation of walkway pads.	50 LF	\$20.00	/	Lineal Foot	\$1,000.00
SUBTOTAL OF UNIT PRICE EXTENSIONS:					<u>\$8,200.00</u>

ALTERNATE BID ITEM 1B (ADD): Roof Section 15

UNIT PRICES (Include the subtotal of Unit Price extensions in the Alternate Bid 1A below. Unit prices shall be used solely for the purpose of determining the adjustment to the Contract Sum for differences between the estimated quantities on the Bid Form and the actual quantities provided. The Contractor's Fee on account of Unit Price Work is Included in the Alternate Bid1A and not in the Unit Price.)

Description	Estimated Quantity	Unit Price	/	Unit of Measure	Extension
Replacement of deteriorated 2" x 6" wood nailers matching the configuration of existing wood nailers.	40 LF	\$3.00	/	Lineal Foot	\$120.00
Replacement of deteriorated 2" x 8" wood nailers matching the configuration of existing wood nailers.	40 LF	\$4.00	/	Lineal Foot	\$160.00
Replacement of deteriorated existing roof drains with new 4" cast roof drains including insulated leaders tied into existing leaders.	1 Each	\$1,500.00	/	1 - Total	\$1,500.00
SUBTOTAL OF UNIT PRICE EXTENSIONS:					<u>\$1,780.00</u>